

Appendix I – Historical Resources Survey Report

PAGE INTENTIONALLY LEFT BLANK



MEMO

April 6, 2022

TO: Administrative File
From: Jennifer Carpenter

District: Dallas
County: Dallas, Ellis
CSJ#: 2964-10-006
Highway: SL 9, Segment A
Project Limits: US 67 to IH 34
Let Date: December 2023

SUBJECT: Internal review under the Section 106 Programmatic Agreement (Section 106 PA) among the Texas Department of Transportation, Texas State Historic Preservation Officer, Advisory Council on Historic Preservation, and Federal Highway Administration; and the Memorandum of Understanding (MOU) between the Texas Historical Commission and the Texas Department of Transportation

The environmental review, consultation, and other actions required by applicable Federal environmental laws for this project are being, or have been, carried-out by TxDOT pursuant to 23 U.S.C. 327 and a Memorandum of Understanding dated December 9, 2019, and executed by FHWA and TxDOT.

NOTE: This memo serves as a project re-coordination and updates the previous memo due to design changes. The design changes are discussed below.

Project Description

See the attachment from TxDOT's Environmental Compliance Oversight System (ECOS) that describes the project, setting, and amount of right-of-way (ROW) and easements necessary for the project. See also the updated Project Coordination Request (PCR) that describes the proposed design changes.

Previous Reviews

TxDOT conducted a reconnaissance survey of the project's area of potential effect (APE) in June 2020 to identify historic-age (1982 or older) resources. Historians found no historically significant properties (see ECOS document "Approved HIST IM CSJ 2964-10-006 Seg A 06-20.pdf" dated June 29, 2020).

Design changes in 2022 incorporated stakeholder and public feedback about the project and required TxDOT historians examine a revised project APE. Design modifications proposed for Options A, B, and C include new properties not captured by the previous survey. Design modifications proposed for Option D fall within the previously reviewed APE and require no further study. This memo addresses the findings of the revised project APE for Design Modifications A, B, and C.

Determination of Eligibility

The TxDOT Section 106 Programmatic Agreement defines the Area of Potential Effect (APE) for this project as 300' from existing and proposed ROW and easements.

TxDOT historians reviewed the National Register of Historic Places (NRHP), the list of State Antiquities Landmarks (SAL), the list of Recorded Texas Historic Landmarks (RTHL), and TxDOT files for information related to resources within the APE. There are no previously identified historic properties within the APE.

A desktop survey of the APE found the following:

Design Modification A¹

Design changes west of Hampton Road extend the APE south to include thirty-nine new properties along Stone Creek Boulevard. The properties are within a large subdivision in Ellis County. Ellis CAD and historic aerials date this section of the subdivision to c. 1995 or later; therefore, the properties are not historic-age and do not require evaluation.

Design changes east of Hampton Road extend the APE north to include ten properties along Mesa Moore Drive and Craddock Drive. The properties are part of a residential neighborhood in Dallas County. Dallas CAD and historic aerials date the properties to c. 1985 or later; therefore, they are not historic-age and do not require evaluation.

Design changes west and east of Uhl Road in Dallas County extend the APE north to include two properties containing historic-age resources:

- 2015 Uhl Road: The property contains a c. 1980 prefabricated home² with a side gable, metal roof. The roof overhang covers a front porch and a prefabricated two-car garage unit added to the front of the residence. There is a rear addition on the home's west elevation. Outbuildings on the parcel include a c. 1965 metal barn and two smaller, contemporary sheds (see *Figures 1-4*).
- 2101 S Uhl Road: The property contains a one-story frame house, constructed in 1968.³ The home is clad in brick veneer and is topped with clipped side gable roof. A small gabled front porch is supported by decorative metal posts. There is an attached garage at the north end of the house. Windows are six-over-six double hung. The property contains three c. 1980 outbuildings, one to the north of the residence and two at the rear. Outbuildings appear to be prefabricated metal units (see *Figures 5-9*).

Representative of generic mid-to-late 20th-century suburban residential growth, the properties are not associated with notable historical events or trends that would deem them eligible for listing in the NRHP under *Criterion A*, nor are they associated with persons important to local, state, or national history that would deem them eligible under *Criterion B*. The properties embody no

¹ Design Modifications Option A and B follow the same path until diverging from each other east of Archdale Lane. Therefore, some sections of the revised APE for these options are the same.

² Dallas CAD lists 1978 as the residence's construction date. The current building replaced an earlier structure. A review of historic aerials shows a residence on the parcel in 1956; it is located closer to the roadway. The current building first appears in a 1989 aerial. Dallas Central Appraisal District, <https://www.dallascad.org>; Glenn Heights, Texas. NETROnline. Nationwide Environmental Title Research, LLC (NETR). <https://www.historicaerials.com>

³ Dallas Central Appraisal District, <https://www.dallascad.org>; Glenn Heights, Texas. NETROnline. Nationwide Environmental Title Research, LLC (NETR). <https://www.historicaerials.com>

distinctive architectural characteristics of a type, period, or method of construction, are not the work of a master, and do not possess high artistic value that would deem them eligible under *Criterion C*.

Design Modification B

Design changes west of Hampton Road extend the APE south to include thirty-nine properties along Stone Creek Boulevard. The properties are within a large subdivision in Ellis County. Ellis CAD and historic aerials date this section of the subdivision to c. 1995 or later; therefore, the properties are not historic-age and do not require evaluation.

Design changes east of Hampton Road extend the APE north to include ten properties along Mesa Moore Drive and Craddock Drive. The properties are part of a residential neighborhood in Dallas County. Dallas CAD and historic aerials date the properties to c. 1985 or later; therefore, they are not historic-age and do not require evaluation.

Design Modification C

Design changes west of Westmoreland Drive in Dallas County extend the APE south to include one property along Lariat Trail and north to include three properties along Meadow Spring Drive in a residential subdivision. Dallas CAD and historic aerials date the Lariat Trail property to 1983 and the Meadow Spring Drive properties to 2006 or later. Therefore, the properties are not historic-age and do not require evaluation.

Based on the desktop survey, TxDOT historians determined that there are no historic properties within the APE.

Determination of Effects

Staff determined that the portion of the project subject to the design changes submitted after the original coordination will not affect any historic properties. Therefore, pursuant to Stipulation IX, Appendix 6 "Undertakings with the Potential to Cause Effects per 36 CFR 800.16(i)" of the Section 106 PA and the MOU, TxDOT historians determined that there are no historic properties affected by the design changes. The original finding of the overall project still stands. In compliance with the Antiquities Code of Texas and the MOU, TxDOT historians determined project activities have no potential for adverse effects. Individual project coordination with SHPO is not required.

DocuSigned by:

 Program Manager _____ for TxDOT _____ 4/7/2022
0F414A49C0E44B3...
 Rebekah Dobrasko Date



Figure 1. Overview of 2015 Uhl Road, facing northwest. Google Street View




Figure 2. View of the residence at 2015 Uhl Road, facing northwest. Dallas CAD classifies the residence as a mobile home. The two-car garage unit addition is visible through the tree branches. Outbuildings are visible to the right of the home. Google Street View



Figure 3. View of 2015 Uhl Road, facing southwest. A covered, open-air storage shed and the gable end of the barn are visible on the right. Google Street View



Figure 4. Aerial view of 2015 Uhl Drive with parcel outlines. Buildings are set back from the road. The residence is oriented north-south and has a rear addition. Outbuildings are northeast of the home. Dallas CAD



Figure 5. Overview of 2101 Uhl Road, facing southwest. Google Street View



Figure 6. View of the residence at 2101 Uhl Road, facing northwest. Google Street View



Figure 7. View of the residence at 2101 Uhl Road, facing southwest. Google Street View



Figure 8. View of 2101 Uhl Road, facing southwest, with metal outbuildings visible on the right. Google Street View



Figure 9. Aerial overview of 2101 Uhl Road with parcel outlines. Buildings are clustered in the northeast corner of the parcel. *Dallas CAD*

ECOS Project Description

[Back To List](#)

- [WPD Section I - Project Definition](#)
- [WPD Section II - Tool](#)
- [WPD Section III - Project Work Plan](#)
- [WPD Section IV - Findings](#)

[Archived WPD I](#)

Print this Page

Project Definition

 Project Name:
CSJ: - -

Anticipated Environmental Classification:

☒ Yes

Is this an FHWA project that normally requires an EIS per 23 CFR 771.115(a)?



Project Association(s)



DCIS Project Funding and Location



DCIS & P6 Letting Dates



DCIS Project Description



Jurisdiction



Environmental Clearance Project Description

Project Area

Typical Depth of Impacts: (Feet)Maximum Depth of Impacts: (Feet)New ROW Required: (Acres)New Perm. Easement Required: (Acres) New Temp. Easement Required: (Acres)

Project Description

Describe Limits of All Activities:

The proposed Loop 9, Segment A project includes the construction of a six-lane new location frontage road system between United States 67 (US 67) and Interstate Highway 35 East (IH 35E) through Dallas and Ellis counties, Texas, and is approximately 9.4 miles in length. The proposed Loop 9 roadway system would pass through the Cities of Cedar Hill, Ovilla, Glenn Heights, and Red Oak. The proposed project right-of-way (ROW) would include a median that would accommodate the future construction of an ultimate access-controlled mainlane facility. Construction of the ultimate access-controlled mainlane facility would be based on projected traffic and funding and would require additional environmental analysis prior to construction.

Describe Project Setting:

This project is located in a developing area along the Dallas-Ellis County Line. Undeveloped lands as well as residential communities comprise a majority of the immediate project vicinity. There are a few commercial properties scattered around the proposed project area.

Describe Existing Facility:

No existing facility. Project is on new location.

Describe Proposed Facility:

The new location Loop 9 frontage road system would include an eastbound and westbound frontage road facility, each consisting of three 12-foot lanes, an 8-foot inside shoulder, and an 8-foot outside shoulder for bicycle accommodations within the rural section of the proposed roadway. The proposed project ROW would include a median (358 to 512 feet wide) that would accommodate the future construction of an ultimate access-controlled mainlane facility.

The proposed project would construct intersections at eight (8) major crossroads as follows: Tar Road, future Clark Road, S. Joe Wilson Road, S. Duncanville Road, S. Cockrell Hill Road, S. Westmoreland Road, S. Hampton Road, and Uhl Road. The proposed project would also construct a grade separation at the BNSF Railroad. In addition, the western limit of the project would tie into a grade separation at US 67 which would be constructed under a separate project prior to construction of Loop 9 Segment A. The eastern limit of project would tie into a grade separation at IH 35E which would be constructed under a separate project prior to construction of Loop 9, Segment A.

The proposed Loop 9, Segment A project, from US 67 to IH 35E, would likely be constructed in three phases based on traffic needs and project funding. A logical sequence for staging the various elements for construction of the new location roadway system could be as follows:

- Phase 1 would construct a single two-lane, two-way frontage road, and would also acquire

Yes ▾

Would the project add capacity?

+

Transportation Planning

+

Environmental Clearance Information

+

Project Contacts

Last Updated By: System Admin

Last Updated Date: 03/28/2022 07:11:25

Updated PCR



Project Coordination Request for Historical Studies Project

Main CSJ: 2964-10-006

District personnel should complete this form with all appropriate documentation attached. ENV-HIST staff review is contingent on provision of an active CSJ (or equivalent if the project is not a construction project) against which environmental work can be charged. District personnel shall ensure project description information in ECOS is complete and accurate prior to submitting the PCR to ENV-HIST. District personnel shall attach ENV project description from WPD I screen to this form. District-provided responses should reflect known data about the project and identify any limitations that hindered provision of the requested information. ENV-HIST staff will review the PCR form and attached information per established Documentation Standards. This review will result in:

- ENV-HIST environmental clearance of the project; OR
- ENV-HIST identification of additional technical studies required for clearance; OR
- ENV-HIST rejection of the PCR for failure to meet specific Documentation Standards and instructions on how to address the rejection.

This form specifies minimally required information needed to properly facilitate ENV-HIST's review process. Please submit all relevant documentation with this PCR at one time.

NOTE: * If this project information changes over the course of design OR if the funding source changes, then HIST requires re-coordination.

No If FHWA funded, does the project conform to the type listed in Appendix 4 and the Historic Resources Toolkit?
OR
Does this historic coordination apply to the Antiquities Code as referenced in the Historic Resources Toolkit?

Information Required to Process Historic Resources Coordination and Consultation

1. Targeted ENV clearance date: November 1, 2023
2. *Anticipated letting date: March 2027
3. "Historic-age" date (let date minus 45 years): 1982
4. Yes *The proposed action is subject to federal permitting (i.e. Corps of Engineers, Coast Guard, IBWC, etc.).

Describe:

USACE Wetland Permit

5. Yes *The proposed action requires additional ROW (purchased or donated) or easements?

| Parcel ID | Required New ROW (acres) | Required New Easements | |
|---------------------|-----------------------------|------------------------|-----------|
| | | Temporary | Permanent |
| See Attached Tables | 616 | 0 | 0 |
| Total: | 616 | 0 | 0 |



Project Coordination Request for Historical Studies Project

6. The following maps, tables or equivalents been uploaded to ECOS?

| Yes/No/NA | Map Type | ECOS File Name: |
|------------|--|---|
| <u>Yes</u> | Existing and proposed ROW boundaries. | 296410006_Loop9SegA_Mods_PCR_032022_Attachments.PDF |
| <u>Yes</u> | Area of Potential Effects (APE) appropriate for project type. | 296410006_Loop9SegA_Mods_PCR_032022_Attachments.PDF |
| <u>Yes</u> | Parcel boundaries for properties within the APE. | 296410006_Loop9SegA_Mods_PCR_032022_Attachments.PDF |
| <u>Yes</u> | Results of the Texas Historic Sites Atlas search, identifying NHL, NRHP, SAL, and RTHL resources located within one-quarter mile of the project area listed in a table format and identified on color aerial map(s) or equivalent. | 296410006_Loop9SegA_Mods_PCR_032022_Attachments.PDF |
| | Comments: | There are no NHL, NRHP, SAL, or RTHL properties within one-quarter mile of the project area. |
| <u>Yes</u> | Results of Historic Resources Aggregator Map. | 296410006_Loop9SegA_Mods_PCR_032022_Attachments.PDF |
| | Comments: | There are no NHL, NRHP, SAL, or RTHL properties within one-quarter mile of the project area. The previous coordination for the Loop 9 project is visible on the Aggregator. |

7. Yes Representative and dated photographs of the project area are uploaded to ECOS.

Note: Photographs should include the following elements:

1. Buildings/structures in the APE and those adjacent.
2. Road Features (culverts, bridges, landscaping, etc.
3. Areas of proposed construction.

File Name in ECOS: 296410006_Loop9SegA_Mods_PCR_032022_Attachments.PDF

8. Yes Preliminary plans are uploaded to ECOS.

File Name in ECOS: 2022-02-04 Loop 9 FR-ALT 1.PDF, 2022-02-04 Loop 9 FR-ALT 2.PDF, 2022-02-04 Loop 9 FR-ALT 3.PDF, 2022-02-04 Loop 9 FR-ALT 3A.PDF, 2022-02-04 Loop 9 FR-ALT 4.PDF

9. Yes Historic-age bridges are within the project area.

| Location | NBI # | Year Built | Eligibility |
|---|-----------------|------------|--------------|
| Bear Creek Road at Little Creek | 180570S00220001 | 1963 | Not Eligible |
| Bear Creek Road at Little Creek Tributary | 180570Y00025002 | 1950/2010 | Not Eligible |



Project Coordination Request for Historical Studies Project

9.1 Yes Aerial map(s) or equivalent with bridge location(s) identified are uploaded to ECOS.

File Name in ECOS: 296410006_Loop9SegA_Mods_PCR_032022_Attachments.PDF

9.2 No CHC consultation required (contact HIST if needed).

10. No Rock masonry features (culverts, ditches, walls, etc.) are within the project area.

11. No Historic-age rest area(s) are located within the project area.

12. No The proposed action involves the relocation of historical markers.

13. No The project roadway is a known former historic highway alignment.

14. Yes Additional consulting parties (other than the THC) may be involved in this project.

| Consulting Party Name | Representing | Contact Information |
|-------------------------------------|--------------|--|
| Dallas County Historical Commission | THC | Juanita Nanez 3842 Medallion Ln Dallas, TX 75229 214-881-9304 juanitananez@yahoo.com |
| Ellis County Historical Commission | THC | David Sacha 605 Preston St Ennis, TX 75119 214-418-6510 David.Sacha@perkinswill.com |

Additional Project Comments:

This is a re-evaluation of design modifications to a previously cleared project, Loop 9 Segment A, under the same CSJ. Overall project limits have not changed. Per the previous coordination, the APE for the design modifications is recommended to be 300 ft from proposed ROW as the project exists on new location.

District Personnel Certification

Yes I reviewed all submitted documents for quality assessment and control.

Sandra Williams Digitally signed by Sandra Williams
Date: 2022.03.31 10:49:31 -05'00'

District Personnel Name

March 31, 2022

Date:

Attachments (Required for all PCRs):

Screenshot/printout of WPD I ENV Project Description text from TXECOS



Project Coordination Request for Historical Studies Project

The following table shows the revision history for this document.

| Document Number | Release Date | Document Title | Description of Action |
|-----------------|--------------|---|--|
| 421.01.PCR | July 2021 | Project Coordination Request (PCR) for Historic Studies | Version 6 The form was updated to include a printout of the WPD I screen with the project description as a required attachment. Updated required map searches. Removed drop down where filling in text is a better option. |
| 421.01.PCR | January 2021 | Project Coordination Request (PCR) for Historic Studies | Version 5. The form was updated to include a question pertaining to historic roadway alignments. The form was updated to include the ability to use a digital signature to certify the form. |
| 421.01.PCR | August 2019 | Project Coordination Request (PCR) for Historic Studies | Version 4 Revised the form to allow for Appendix 4 reviews as part of the PCR. Updated and clarified language for maps. Removed references to project description information found in ECOS. |
| 421.01.PCR | August 2015 | Project Coordination Request (PCR) for Historic Studies | Version 3 Revised the form to make it compatible with Adobe Acrobat Reader DC. No changes were made to the question sequence or form logic. |
| 421.01.PCR | June 2015 | Project Coordination Request (PCR) for Historic Studies | Version 2 The form was converted to a smart form. Form level validations were installed to ensure that all certified forms contain the minimum required information. Various questions were modified to accommodate the improved functionality of the PDF format. |
| 421.01.PCR | May 2014 | Project Coordination Request (PCR) for Historic Studies | Version 1 Used by the TxDOT districts to request assistance from the TxDOT Environmental Historical Studies Branch to determine the scope of historic resources study appropriate for a project. |



Finalized

[Back To List](#)

- [WPD Section I - Project Definition](#)
- [WPD Section II - Tool](#)
- [WPD Section III - Project Work Plan](#)
- [WPD Section IV - Findings](#)

[Archived WPD I](#) [Print this Page](#)

Project Definition

Project Name: 2964-10-006 SL 9 - Construct 0 to 2 (Ultimate 6) Ln Frt Rds

CSJ: 2964 - 10 - 006

Anticipated Environmental Classification:

EIS

Yes

Is this an FHWA project that normally requires an EIS per 23 CFR 771.115(a)?



Project Association(s)

Auto Associate CSJ from DCIS

Manually Associate CSJ:

Add

| CSJ | DCIS Funding | DCIS Number | Env Classification | DCIS Classification | Main or Associate | Doc Tracked In | Actions |
|--|--------------|-------------|--------------------|---------------------|-------------------|----------------|---------|
| There are currently no Project Associations added to this project. | | | | | | | |



DCIS Project Funding and Location

Funding

DCIS Funding Type:

☒ Federal☒ State☐ Local☐ Private

Location

DCIS Project Number: STP ()

Highway: SL 9

District: DALLAS

County: DALLAS

Project Limit -- From: US 67

Project Limit -- To: IH 35E

Begin Latitude: + .

Begin Longitude: - .

End Latitude: + .

End Longitude: - .



DCIS & P6 Letting Dates

DCIS District: 08/45

DCIS Approved:

DCIS Actual:

P6 Ready To Let:

P6 Proposed Letting:



DCIS Project Description

Type of Work: Spell

Layman's Description:

WIDEN ROAD - ADD LANES AND SHOULDERS

DCIS Project Classification: NLF - NEW LOCATION FREEWAY

Design Standard: 4R - New Location and Reconstruction

Roadway Functional Classification: 2 - Not Applicable



Jurisdiction

No

Does the project cross a state boundary, or require a new Presidential Permit or modification of an existing Presidential Permit?

Who is the lead agency responsible for the approval of the entire project?

☒ FHWA - Assigned to TxDOT ☐ TxDOT - No Federal Funding ☐ FHWA - Not Assigned to TxDOT

TxDOT ▼

Who is the project sponsor as defined by 43 TAC 2.7?

Yes ▼

Is a local government's or a private developer's own staff or consultant preparing the CE documentation, EA or EIS?

Yes ▼

Does the project require any federal permit, license, or approval?

☒ USACE ☐ IBWC ☐ USCG ☐ NPS ☐ IAJR ☐ Other

No ▼

Does the project occur, in part or in total, on federal or tribal lands?

☐ Environmental Clearance Project Description

Project Area

Typical Depth of Impacts: (Feet)

Maximum Depth of Impacts: (Feet)

New ROW Required: (Acres)

New Perm. Easement Required: (Acres) New Temp. Easement Required: (Acres)

Project Description

Describe Limits of All Activities:

The proposed Loop 9, Segment A project includes the construction of a six-lane new location frontage road system between United States 67 (US 67) and Interstate Highway 35 East (IH 35E) through Dallas and Ellis counties, Texas, and is approximately 9.4 miles in length. The proposed Loop 9 roadway system would pass through the Cities of Cedar Hill, Ovilla, Glenn Heights, and Red Oak. The proposed project right-of-way (ROW) would include a median that would accommodate the future construction of an ultimate access-controlled mainlane facility. Construction of the ultimate access-controlled mainlane facility would be based on projected traffic and funding and would require additional environmental analysis prior to construction.

Describe Project Setting:

This project is located in a developing area along the Dallas-Ellis County Line. Undeveloped lands as well as residential communities comprise a majority of the immediate project vicinity. There are a few commercial properties scattered around the proposed project area.

Describe Existing Facility:

No existing facility. Project is on new location.

Describe Proposed Facility:

The new location Loop 9 frontage road system would include an eastbound and westbound frontage road facility, each consisting of three 12-foot lanes, an 8-foot inside shoulder, and an 8-foot outside shoulder for bicycle accommodations within the rural section of the proposed roadway. The proposed project ROW would include a median (358 to 512 feet wide) that would accommodate the future construction of an ultimate access-controlled mainlane facility.

The proposed project would construct intersections at eight (8) major crossroads as follows: Tar Road, future Clark Road, S. Joe Wilson Road, S. Duncanville Road, S. Cockrell Hill Road, S. Westmoreland Road, S. Hampton Road, and Uhl Road. The proposed project would also construct a grade separation at the BNSF Railroad. In addition, the western limit of the project would tie into a grade separation at US 67 which would be constructed under a separate project prior to construction of Loop 9 Segment A. The eastern limit of project would tie into a grade separation at IH 35E which would be constructed under a separate project prior to construction of Loop 9, Segment A.

The proposed Loop 9, Segment A project, from US 67 to IH 35E, would likely be constructed in three phases based on traffic needs and project funding. A logical sequence for staging the various elements for construction of the new location roadway system could be as follows:

- Phase 1 would construct a single two-lane, two-way frontage road, and would also acquire

Would the project add capacity?

☐ Transportation Planning

Is the project within an MPO's boundaries?

Does the project meet the definition for a grouped category for planning and programming purposes?

The project is located in area.

This status applies to:

☐ CO - Carbon Monoxide

☐ O3 - Ozone

☐ NO2 - Nitrogen Dioxide

☐ PM10 - Particulate

☐ PM2.5 - Particulate

☐ Environmental Clearance Information

Environmental Clearance Date:

Environmental LOA Date:

Closed Date:

Archived Date:

Approved Environmental Classification:

☐ Project Contacts

Created By:

Date Created:

Project Sponsor: ☒ TXDOT (Or) ☐ Local Government

Sponsor Point Of Contact:

ENV Core Team Member:

District Core Team Member:

Other Point of Contact(s):

Last
Updated By: Sandra Williams

Last Updated Date: 03/28/2022 06:09:27

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas

| Table 1: Additional Proposed ROW (Mod A) | | | |
|---|---------------------------------|-------------------------------|------------------|
| Parcel ID | Required New ROW (acres) | Required New Easements | |
| | | <i>Temporary</i> | <i>Permanent</i> |
| 495 | 0.850 | 0.00 | 0.00 |
| 496 | 1.570 | 0.00 | 0.00 |
| 497 | 1.090 | 0.00 | 0.00 |
| 498 | 8.370 | 0.00 | 0.00 |
| 499 | 1.070 | 0.00 | 0.00 |
| 500 | 19.570 | 0.00 | 0.00 |
| 501 | 10.140 | 0.00 | 0.00 |
| 519 | 0.260 | 0.00 | 0.00 |
| 560 | 0.850 | 0.00 | 0.00 |
| 341E | 4.940 | 0.00 | 0.00 |
| 430E | 4.180 | 0.00 | 0.00 |
| Total: | 52.89 | 0.00 | 0.00 |

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas

| Table 2: Additional Proposed ROW (Mod B) | | | |
|--|--------------------------|------------------------|------------------|
| Parcel ID | Required New ROW (acres) | Required New Easements | |
| | | <i>Temporary</i> | <i>Permanent</i> |
| 495 | 0.070 | 0.00 | 0.00 |
| 496 | 0.560 | 0.00 | 0.00 |
| 498 | 2.870 | 0.00 | 0.00 |
| 499 | 3.880 | 0.00 | 0.00 |
| 500 | 2.160 | 0.00 | 0.00 |
| 501 | 1.120 | 0.00 | 0.00 |
| 560 | 0.180 | 0.00 | 0.00 |
| 295E | 0.000 | 0.00 | 0.00 |
| 341E | 4.340 | 0.00 | 0.00 |
| 430E | 6.250 | 0.00 | 0.00 |
| 472E | 0.080 | 0.00 | 0.00 |
| 491E | 3.390 | 0.00 | 0.00 |
| Total: | 24.90 | 0.00 | 0.00 |

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas

| Table 3: Additional Proposed ROW (Mod C) | | | |
|--|--------------------------|------------------------|------------------|
| Parcel ID | Required New ROW (acres) | Required New Easements | |
| | | <i>Temporary</i> | <i>Permanent</i> |
| 187 | 0.100 | 0.00 | 0.00 |
| 188 | 0.080 | 0.00 | 0.00 |
| 196 | 0.100 | 0.00 | 0.00 |
| 198 | 0.010 | 0.00 | 0.00 |
| 200 | 0.020 | 0.00 | 0.00 |
| 233 | 3.650 | 0.00 | 0.00 |
| 331 | 0.080 | 0.00 | 0.00 |
| 335 | 0.002 | 0.00 | 0.00 |
| 359 | 0.060 | 0.00 | 0.00 |
| 182E | 0.003 | 0.00 | 0.00 |
| 222E | 0.000 | 0.00 | 0.00 |
| 225E | 0.010 | 0.00 | 0.00 |
| 226E | 0.140 | 0.00 | 0.00 |
| 227E | 0.020 | 0.00 | 0.00 |
| 228E | 0.020 | 0.00 | 0.00 |
| 237E | 0.530 | 0.00 | 0.00 |
| 266E | 1.250 | 0.00 | 0.00 |
| Total: | 6.08 | 0.00 | 0.00 |

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas

| Table 4: Additional Proposed ROW (Mod D) | | | |
|---|---------------------------------|-------------------------------|------------------|
| Parcel ID | Required New ROW (acres) | Required New Easements | |
| | | <i>Temporary</i> | <i>Permanent</i> |
| 11 | 0.020 | 0.00 | 0.00 |
| 13 | 0.620 | 0.00 | 0.00 |
| 16 | 0.020 | 0.00 | 0.00 |
| 17 | 0.050 | 0.00 | 0.00 |
| 18 | 0.100 | 0.00 | 0.00 |
| 37 | 1.100 | 0.00 | 0.00 |
| 40 | 12.770 | 0.00 | 0.00 |
| 41 | 0.490 | 0.00 | 0.00 |
| 42 | 6.680 | 0.00 | 0.00 |
| 45 | 0.800 | 0.00 | 0.00 |
| 54 | 0.110 | 0.00 | 0.00 |
| 55 | 0.260 | 0.00 | 0.00 |
| 222E | 0.000 | 0.00 | 0.00 |
| 225E | 0.010 | 0.00 | 0.00 |
| 226E | 0.140 | 0.00 | 0.00 |
| 227E | 0.020 | 0.00 | 0.00 |
| 228E | 0.020 | 0.00 | 0.00 |
| 237E | 0.530 | 0.00 | 0.00 |
| 266E | 1.250 | 0.00 | 0.00 |
| Total: | 24.99 | 0.00 | 0.00 |

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas




Figure 1: Project Location Map (Aerial)

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas




Figure 2: Project Location Map (Topographic)

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas




Figure 3a: Study Area and APE Map

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas




Figure 3b: Study Area and APE Map

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas




Figure 3c: Study Area and APE Map

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas




Figure 3d: Study Area and APE Map

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas




Figure 3e: Study Area and APE Map

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas




Figure 3f: Study Area and APE Map

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas


| NRHP | RTHL | SAL | Historical Markers | Cemeteries |
|------|------|-----|-----------------------|------------|
| 0 | 0 | 0 | 0 | 0 |

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas



Texas Historical Commission Historic Sites Atlas, <https://atlas.thc.state.tx.us/Map> (February 25, 2022)

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas



TxDOT Historic Resources of Texas Aggregator,
<https://txdot.maps.arcgis.com/apps/webappviewer/index.html?id=e13ba0aa78bf4548a8e98758177a8dd5> (February 25, 2022)

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas



Uhl Road, facing south. (1/13/2022)



Uhl Road, facing north. (1/13/2022)

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas



Glenn Heights water tower, facing north. (11/18/2021)



Hampton Road at Stone Creek Boulevard, facing southwest. (1/13/2022)

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas



Undeveloped land on S. Westmoreland Road, facing west. (1/13/2022)



Houses along Lariat Trail, facing northwest. (1/13/2022)

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas



S. Cockrell Hill Road, facing north. (1/13/2022)



Residence at 1920 Tar Road, facing northeast. (1/13/2022)

Loop 9, Segment A
US 67 to IH 35E
CSJ: 2964-10-006
Dallas and Ellis Counties, Texas



Tar Road, facing south. (1/13/2022)

Certificate Of Completion

| | |
|---|-------------------------------|
| Envelope Id: B50B37C8957B4E628129E8368FD0CE9D | Status: Completed |
| Subject: Please DocuSign: HIST IM 2964-10-006 Seg A (04-2022).pdf | |
| Source Envelope: | |
| Document Pages: 41 | Signatures: 1 |
| Certificate Pages: 1 | Initials: 0 |
| AutoNav: Enabled | Envelope Originator: |
| Envelope Stamping: Enabled | Jennifer Carpenter |
| Time Zone: (UTC-06:00) Central Time (US & Canada) | 125 E. 11th Street |
| | Austin, TX 78701 |
| | Jennifer.Carpenter1@txdot.gov |
| | IP Address: 204.64.21.50 |

Record Tracking

| | | |
|--------------------------------------|--|--------------------|
| Status: Original | Holder: Jennifer Carpenter | Location: DocuSign |
| 4/6/2022 3:45:31 PM | Jennifer.Carpenter1@txdot.gov | |
| Security Appliance Status: Connected | Pool: StateLocal | |
| Storage Appliance Status: Connected | Pool: Texas Department of Transportation | Location: DocuSign |

Signer Events

Rebekah Dobrasko
 Rebekah.Dobrasko@txdot.gov
 Texas Department of Transportation
 Security Level: Email, Account Authentication (Optional)

Signature

DocuSigned by:

 0F414A49C0E44B3...

Signature Adoption: Pre-selected Style
 Signed by link sent to Rebekah.Dobrasko@txdot.gov
 Using IP Address: 204.64.21.251

Timestamp

Sent: 4/6/2022 4:01:14 PM
 Viewed: 4/7/2022 11:59:32 AM
 Signed: 4/7/2022 12:02:07 PM

Electronic Record and Signature Disclosure:
 Not Offered via DocuSign

In Person Signer Events**Signature****Timestamp****Editor Delivery Events****Status****Timestamp****Agent Delivery Events****Status****Timestamp****Intermediary Delivery Events****Status****Timestamp****Certified Delivery Events****Status****Timestamp****Carbon Copy Events****Status****Timestamp****Witness Events****Signature****Timestamp****Notary Events****Signature****Timestamp****Envelope Summary Events****Status****Timestamps**

| | | |
|---------------------|------------------|----------------------|
| Envelope Sent | Hashed/Encrypted | 4/6/2022 4:01:14 PM |
| Certified Delivered | Security Checked | 4/7/2022 11:59:32 AM |
| Signing Complete | Security Checked | 4/7/2022 12:02:07 PM |
| Completed | Security Checked | 4/7/2022 12:02:07 PM |

Payment Events**Status****Timestamps**



Historical Resources Survey Report

Reconnaissance Survey

Project Name: Loop 9, Segment A

Project Limits: US 67 to IH 35E

District(s): Dallas

County(s): Dallas and Ellis

CSJ Number(s): 2964-10-006

Principal Investigator: Kurt Korfmacher and Deborah Dobson-Brown

Report Completion Date: June 2020

This historical resources survey report is produced for the purposes of meeting requirements under Section 106 of the National Historic Preservation Act, the Antiquities Code of Texas, and other cultural resource legislation related to environmental clearance as applicable.

Abstract

The proposed Loop 9 project includes the construction of a six-lane new location frontage road system between Interstate Highway 35 East (IH 35E) and United States 67 (US 67) through Dallas and Ellis counties, Texas and is approximately 9.4 miles in length. The proposed Loop 9 roadway system would pass through the communities of Cedar Hill, Ovilla, Glenn Heights, and Red Oak. The proposed project right-of-way (ROW) would include a median that would accommodate the future construction of an ultimate access-controlled mainlane facility. Construction of the ultimate access-controlled mainlane facility would be based on projected traffic and funding and would require additional environmental analysis prior to construction. As the project is proposed as new location roadway and four build alternatives are under consideration, an Environmental Impact Statement (EIS) is being prepared under the National Environmental Policy Act (NEPA).

Project historians surveyed the project Area of Potential Effect (APE) in October 2019 and April 2020 and documented 84 properties with historic-age resources within the project area. None of the properties are currently listed in the National Register of Historic Places (NRHP). Following evaluation of the surveyed properties, project historians recommend that none of the properties are eligible for listing in the NRHP. Three properties are recommended for further study due to access issues and undetermined NRHP eligibility. Project historians recommend the proposed undertaking would have no effect on historic properties under Section 106, assuming further study identifies no NRHP-eligible properties. The proposed undertaking would (tentatively) not be considered a transportation use of historic properties under Section 4(f) depending on the outcome of the further studies, and no Section 4(f) analysis would be required.

Table of Contents

| | |
|--|-----|
| Abstract..... | 3 |
| Project Identification..... | 5 |
| Area of Potential Effects (APE) | 6 |
| Section 106 Consulting Parties | 6 |
| Stakeholders | 7 |
| Project Setting/Study Area | 8 |
| Survey Methods | 10 |
| Survey Results..... | 11 |
| Historical Context Statement | 12 |
| National Register Eligibility Recommendations | 16 |
| Determination of Section 106 Effects Recommendations | 28 |
| U.S. DOT Section 4(f) Applicability Statement..... | 29 |
| References Cited..... | 30 |
| Appendix A: Project Information and ROW Information | 32 |
| Appendix B: Tabular Inventory of Surveyed Properties | 39 |
| Appendix C: Survey Forms for All Surveyed Properties..... | 64 |
| Appendix D: Figures | 434 |
| Appendix E: Schematics | 455 |
| Appendix F: Project Area Photographs | 457 |
| Appendix G: Consulting Party Comments..... | 463 |

Project Identification

- Report Completion Date: 06/08/2020
- Date(s) of Fieldwork: 10/28/2019 to 10/29/2019; 4/10/2020
- Survey Type: ☐ Windshield ☒ Reconnaissance ☐ Intensive
- Report Version: ☒ Draft ☐ Final
- Regulatory Jurisdiction: ☒ Federal ☐ State
- TxDOT Contract Number: 577XXSD004
- District or Districts: Dallas
- County or Counties: Dallas and Ellis
- Highway or Facility: Loop 9, Segment A
- Project Limits:
 - From: US 67
 - To: IH 35E
- Main CSJ Number: 2964-10-006
- Report Author(s): Paige Ritter and Kurt Korfmacher, AmaTerra Environmental, Inc.
- Principal Investigator: Kurt Korfmacher and Deborah Dobson-Brown, AmaTerra Environmental, Inc.
- List of Preparers: Paige Ritter, Kurt Korfmacher, and Cherise Bell, survey; Paige Ritter and Kurt Korfmacher, authorship; Vanessa Cragle, GIS/maps

Area of Potential Effects (APE)

- ☐ Existing ROW
- ☐ 150' from Proposed ROW and Easements
- ☒ 300' from Proposed ROW and Easements
- ☐ Custom: <0'> from Proposed ROW and Easements

Custom APE not applicable.

- **Historic-Age Survey Cut-Off Date:** 1982
- **Study Area** 1300 feet from edge of the Area of Potential Effects

Section 106 Consulting Parties

- **Public Involvement Outreach Efforts:**

TxDOT held a round of identical public meetings on Alternatives 1-4 for Segment A on February 6th and 13th, 2020. The majority of comments received from attendees of both meetings were either neutral or negative in tone regarding the proposed undertaking. Two property owners (of a shared property) expressed disapproval of Alternative 4, as it would impact land that had been in the family “more than 100 years;” this property is Property No. 20. No other attendees expressed concerns about historic properties; the majority of concerns involved loss of vegetation, impacts to wildlife, loss of property value or eminent domain, increased crime, and noise pollution.

- **Identification of Section 106 Consulting Parties:**

Dallas County Historical Commission
Richard Stewart, Commission Chair
2327 Southern Oak Dr.
Irving, TX 75063
972-831-1237
rgstewartjr@sbcglobal.net

Ellis County Historical Commission
Sylvia Stanford-Smith, Commission Chair
P.O. Box 175
Waxahachie, TX 75168
214-538-9576
sylsmithro@att.net

- **Section 106 Review Efforts:**

The District has prepared formal letters to both the Dallas County Historical Commission and the Ellis County Historical Commission to be sent June 13th asking for comment within 30 days on area historic resources. Future drafts of this report will include any responses from the CHCs received by July 13th.

- **Summary of Consulting Parties Comments:**

Future revisions of this report will be updated with responses from the county historical commissions if any are forthcoming. The District may elect to handle future correspondence with consulting parties as necessary.

Stakeholders

- **Stakeholder Outreach Efforts:**

Two public meetings (noted above) and meetings between TxDOT, project engineers, and community leaders and officials have been held in recent months.

- **Identification of Stakeholder Parties:**

TxDOT initially assembled a list of over 400 potential interested parties, including over 150 representatives of government entities. Thirty-eight identified stakeholders are participating government agencies primarily associated with relevant departments or branches of federal, state, and local governments. The full list is available at the District office.

- **Summary of Stakeholder Comments:**

At a meeting with the community of Cedar Hill (meeting date unknown), mention was made of a historic building within the limits of Alternative 4 (Property No. 31). No other stakeholder concerns regarding historic properties are known.

Project Setting/Study Area

■ Study Area

The project area consists of primarily rural and suburban residential development with scattered educational, recreational, and commercial development. Agricultural properties are mostly small, active ranches with some cultivation evident. Residential properties include small farmsteads and parcels located within subdivisions.

■ Previously Evaluated Historic Resources

A review of the Texas Historical Commission's (THC) Texas Historic Sites Atlas (Atlas), the TxDOT Historic Bridge Survey database, and TxDOT Historic Districts and Properties databases resulted in the identification of no historic resources within the study area.

■ Previously Designated Historic Properties

A review of the THC Atlas and survey files, the National Park Service NRHP database, the TxDOT Historic Districts and Properties database, the list of non-archeological State Antiquities Landmarks (SAL), and the list of Recorded Texas Historic Landmarks (RTHL) resulted in the identification of no individually designated properties within the project APE.

■ Previously Designated Historic Districts

A review of the THC Atlas and survey files, the National Park Service NRHP database, the list of non-archeological SAL, and the list of RTHL resulted in the identification no NRHP-listed historic districts in the project study area.

■ Historic Land Use

Early land use was primarily agricultural, farmsteads with their associated fields and pastures dotting the landscape. Development was sparse by 1958. Few farmsteads were present in the areas directly north and south of West Bear Creek Road. Domestic work zones associated with farmsteads are scarce west of South Joe Wilson Road in 1958; however, fields and pastures were prevalent. By September of 1968, large farmsteads and their agricultural work zones and associated fields/pastures still dominated the project area with few mid-century subdivisions being developed. The town of Ovilla, first settled in 1844, was not incorporated until 1963 (Stewart, 2010), and Glenn Heights, a suburb of Dallas, was incorporated in 1969, alluding to the fact development was taking place in the rural project area, albeit gradually (Jasinski, 2010). By 1972, slightly larger

subdivisions were being constructed along US 67 and IH 35E near the towns of Glenn Heights and Red Oak. Additionally, smaller subdivisions began developing along Red Oak Creek. Agricultural fields still dominated the project area, though. Historic aerials from 1982 show little change from ten years prior, but a few larger subdivisions began to dot areas closest to Red Oak Creek. Development near the towns of Glenn Heights, Ovilla, and Red Oak expanded from their 1972 footprints.

- **Current Land Use and Environment**

Current land use is semi-rural with expanding pockets of suburban residential development. Land use is primarily agricultural, residential, and transportation related. Agricultural properties are mostly small, active farmsteads. The proposed alignment passes through the communities of Cedar Hill, Glenn Heights, Ovilla, and Red Oak.

The natural environment consists mostly of open and cultivated Blackland prairie with stands of native trees, shrubs, and grasses around rivers and streams. The project passes over Red Oak Creek near its headwaters and its tributary, Little Creek.

- **Historic Period(s) and Property Types**

Based on the resources identified in the project APE, the historic period stretches from circa 1901 to circa 1982 . Property types are rural and suburban, dominated by residential properties and supplemented by agricultural and commercial property types. Residential properties date from 1901 to 1982, most dating from the post-war era (1950-1970s). Non-domestic properties, including agricultural, commerce, and healthcare properties date from circa 1960 to circa 1980.

- **Integrity of Historic Setting**

The historic setting of the project area was primarily agricultural with small farmsteads and pockets of suburban development. The project area is mostly comprised of agricultural lands and post-war development which included the construction of residential, commercial, and industrial properties. While modern suburban development is dotted along the project corridors and more prevalent north and south of the project area, the integrity of setting for the project area has not been compromised, as it still maintains its agricultural setting and post-war, historic-age resources.

Survey Methods

▪ Methodological Description

As stipulated in the 2015 Programmatic Agreement among the Federal Highway Administration, TxDOT, the Texas State Historic Preservation Officer, and the Advisory Council on Historic Preservation Regarding the Implementation of Transportation Undertakings, project historians conducted a reconnaissance survey on the parcels within the project study area from US 67 to IH 35E.

Multiple digital photographs were taken of each accessible resource of historic age. When possible, photographs include at least two oblique view of the primary façade and at times a side or rear façade. Visible modern buildings or structures located on properties with historic-age resources were photographed to show their relationships to the historic-age resources but were not individually recorded. Each historic-age resource was given a map ID number, keyed to a resource location map, and included in a tabular inventory. The address, when available, or location information and latitude/longitude were recorded and provided in the survey report.

To determine the construction date, project historians use field assessment by a professional historian combined with historic mapping, aerial photography, and property owner information. County appraisal district records (where available) were used to assist with dating changes to the property such as additions and shed. Where appraisal district data matched what historians observed in the field, that information was used for construction date. Data collected in the field included, but was not limited to, style, construction date, and any modifications made to the property. Analysis was conducted to determine whether the property was individually eligible for listing in the NRHP or whether it contributed to the significance of a potential historic district.

Project historians visited Nicholas P. Sims Library in Waxahachie, Texas to collect information regarding Dallas County and Ellis County histories, agriculture, suburbanization, and land use.

▪ Comments on Methods

All work was conducted and supervised by individuals meeting the Secretary of Interior's Professional Qualification Standards for history and architectural history. The survey complies with ENV Standards of Submission regarding maps, tables, images, and image quality, and geographic information system files. The period for historic-age survey is 1901-1982. All alternatives of the current APE have the standard survey period up to the cut-off date of 1982. Survey maps and project schematics reflect the current proposed ROW as known to project historians at the time of report authorship.

Fieldwork was conducted from October 28, 2019 to October 29, 2019, and April 13, 2020. Weather conditions were mixed with cool to cold temperatures and intermittent rainfall in October, with mixed clouds and sun in April. Project historians were granted right-of-entry (ROE) for eleven properties. Four rights-of-entry were pursued. All remaining properties were surveyed and photographed from the public ROW. Heavy vegetation growth and/or topography obstructed views at some locations. Where necessary, project historians have supplemented survey photographs with aerial imagery.

The October 28-29, 2019 survey efforts identified a total of 68 properties in the project APE with historic-age resources, using the approved APE maps from the research design. Survey efforts which took place on April 13, 2020 identified a total of 14 properties. Most identified resources consist of domestic and agricultural properties with few commercial and industrial properties present. Per current TxDOT-ENV guidance, this report does not include any bridges or culverts from 1945 and onward previously determined not eligible for NHRP listing. The survey inventory may be found in **Appendix B**. Photo inventory pages are located in **Appendix C**. Maps showing the location of all surveyed resources may be found in **Appendix D**.

Survey Results

▪ Project Area Description

The project area consists of rural development with interspersed suburban development along the entire length of the project corridors. Small farmsteads and agricultural lands dominate the landscape along with few commercial and industrial properties. The project area is southwest of the City of Dallas and northwest of the City of Waxahachie. Little Creek travels southeast through the west portion of the project area. Red Oak Creek, south of Little Creek, follows a similar path through the project corridors.

▪ Literature Review

Project historians submitted a research design covering the project area and proposed survey methods in March 2020. The research design was approved by ENV historians in April 2020.¹ In preparation of the research design and this report, project historians reviewed general information resources in order to prepare a history of the project area. Sources included general interest websites, historic and current aerial photography, previous survey reports and property surveys, and historic and current maps. In addition, historians consulted the Texas Historic Sites Atlas, and TxDOT-provided Google Earth layer for information regarding existing historic properties located within the project study area which is shown in **Figure 3**. Online resources such as *The Handbook of Texas Online* gave

¹ An earlier research design for the project was approved in October 2019.

researchers an overview of the history of Dallas and Ellis Counties. Project historians conducted research at the Nicholas P. Sims Library in Waxahachie, Texas. Historic road and county highway maps identified highways constructed near or through the project area. S.G. Reed's *A History of the Texas Railroads* provided information about railroad construction and systems that operated near or through the project area. Additional information came from historic aerial photographs (**Appendix D**) obtained through the U.S. Geological Survey's EarthExplorer website.

Historical Context Statement

The project area has been primarily agricultural with pockets of suburban development since the mid-twentieth century as a result of post-war suburbanization from nearby Dallas and Waxahachie. Ellis County's dependency on cotton production in the late nineteenth and early twentieth centuries led to a construction boom as cotton prices and demand soared. The rural economy has preserved buildings dating to this development boom, and therefore, the period of significance is from 1901 to 1982, including the earliest extant settlement of the project area up through the end of the historic period. Agriculture and manufacturing have played significant roles in the development of Dallas and Ellis Counties, as has the creation, maintenance, and expansion of transportation corridors and systems. Therefore, important themes encountered by the survey include agriculture, transportation (both rail and highway), suburban development (both early twentieth century and post-war), and industry. Given the proposed survey period, emphasis will be placed on contexts impacting development in the early to late twentieth century.

Wheat, Cotton, and Agricultural Dominance, 1880-1950

From 1843 to 1850, development in Dallas County was progressing slowly due to a lack of transportation and nearby markets, so it remained rural until 1920 when manufacturing gradually replaced agriculture as the primary industry. From 1880 to 1920, the county population spiked from approximately 33,000 to 210,000, even as agriculture peaked in 1900. By the early twentieth century, cotton, wheat, oat, and livestock production recorded their most profitable numbers, and the number of farms in Dallas County reached a high of 5,379. By 1920, as Dallas County's economy transitioned from agricultural to industrial, the landscape transitioned from rural to suburban and urban, and the number of farms declined by 35 percent following the Great Depression. Despite rapid growth, by 1940, Dallas County's agricultural industry stabilized (Maxwell, 2019). As Dallas County's economy evolved from agricultural to industrial, it became a major agricultural-implement outlet center, providing Ellis County and other locations with cotton gin equipment. By 1920, Dallas County was manufacturing more than half of the cotton gin machinery in the world (Ellis County Museum, Inc., 2020). In addition, although

crop production had fallen, nondairy cattle production tripled from 1920 to 1950 (Maxwell, 2019).

Like Dallas County, Ellis County remained agricultural until 1930, and as the population increased, the number of farms within the county, while smaller in acreage, approximately 40 to 50 acres, nearly doubled by the turn of the century. Sudden economic prosperity was due in large part to new land management methods, which increased crop, specifically cotton, production, and improved transportation methods and routes. Beginning in the 1870s and continuing into the early twentieth century, tenant farming supported Ellis County's booming cotton economy by making up most of the county's farms. The introduction of the railway system through Ellis County further expanded its agricultural economics and is considered one of the greatest factors contributing to Ellis County's profitable cotton economy. Previously insignificant, cotton growing became the county's most profitable agricultural venture, and by the twentieth century, Ellis County was leading the country in cotton production.

Despite its agricultural success, Ellis County's agricultural prosperity was soon stunted by the Great Depression and other factors, which proved to have lasting impacts on the economy into the 1950s. Although specialists warned of the risks of monocropping, the practice of producing only one type of crop, farmers continued to only cultivate cotton on their land. When cotton prices and demand plummeted in the 1930s due to south and southwest Texas entering the cotton market, Ellis County's agricultural economy was negatively impacted. In response, the number of tenant farmers fell from 4,928 in 1930 to 1,236 by 1935. In 1930, Ellis County produced 97,192 bales of cotton, in contrast to the 67,000 bales produced in 1950. (Ellis County Museum, Inc., 2020).

Early Twentieth Century Development, Early Railroads and Highways (1910-1940)

With 295.36 miles of tracks and fourteen railroads in Dallas County by 1914, the county was well-served with railways in every direction that frequently changed names and ownership. While new communities developed and grew along routes, others, who had been bypassed, disappeared altogether.

In addition, by 1910, there were approximately 1,200 miles of public roads in Dallas County. With the introduction of the automobile, the county expanded quickly, welcoming industry in place of agriculture. Dallas County's rural and agricultural landscape gradually gave way to manufacturing, and the population began leaving rural Dallas County for manufacturing jobs in its urban pockets (Maxwell, 2019).

As did Dallas County, Ellis County industry prospered with the introduction of rail lines and roadways in the nineteenth and early twentieth centuries, aiding in the establishment of 203 industrial companies by the turn of the century. The railroads through Ellis County are considered to be one of the greatest impacts to the county's development, as communities were built and/or relocated adjacent to the tracks. Ellis County supported seven railroad companies before 1910, two of which are located in the project area. The

Missouri, Kansas, and Texas Railroad serviced the town of Red Oak by 1890, with the Gulf, Colorado, and Santa Fe servicing Midlothian (Brown, 2010).

Communities offered land and cash incentives to railroad companies as the towns nearest the railroads often became prosperous commercial hubs. Interurban lines financed by the Texas Traction Company in Dallas County were constructed across Ellis and Dallas County. The Texas Electric Railway, completed in 1913, ran parallel to the Missouri, Kansas, and Texas Railroad connecting Dallas to Waco through Red Oak and was considered the largest interurban system in the South. New and improved roads were a priority for farmers transporting their crops. State Highway 6 (US 77) was constructed under the Federal Aid Road Act of 1916 south of the project area from Waxahachie to Sterrett. It was concreted and expanded northward through Red Oak in the 1930s. Per historic aerial imagery, the construction of both roadways did not lead to areas of dense development along their corridors in the following decades. Rather, the landscape flanking US 77 remained in keeping with the surrounding area, agricultural with a few farmsteads (Ellis County Museum, Inc., 2020).

By the thirties, the Rural Electrification Administration provided power to Ellis County's farms and rural areas (Haaser, 2016). By 1938, there were 10,823 motor vehicles in Ellis County; a decade later and all major roads were paved within the county.

Post-War Development and Suburbanization, 1945-Present

From 1920 to 1950, Dallas County's population tripled to nearly 615,000. In 1950, all of Dallas County was officially classified as Dallas Metropolitan Statistical Area, and 89.8 percent of the county was urban (Maxwell, 2019). However, despite rapid urban development, the project area remained rural. Pockets of suburban development did not begin infiltrating the project area until the late sixties.

During World War II, defense factories supplied jobs to young, rural workers. Shortly following the war, Dallas County witnessed great prosperity. By the 1950s, manufacturing, retail trade, and wholesale trade dominated the economy, and employment tripled, leading to an increased demand for residential development. The decline of the agricultural industry and phasing out of tenant farming impacted Ellis County's development much as it did for Dallas County. By 1940, 48 percent of Ellis County was urban with more than 50 percent of the county population residing in urban areas. However, a lack of incoming capital by the 1950s led to slow development, and therefore, rather than being replaced by new construction, buildings dating to the early to mid-twentieth century remain in place. Within the project area specifically, development was gradual. Farmsteads dotted the project area directly north and south of West Bear Creek Road by 1958. Undeveloped land and pastures dominated the project area west of South Joe Wilson Road. By September 1968, while large farmsteads and their associated fields dominated the project area, suburban development began expanding.

The town of Ovilla, located south of the project area in Ellis County, was first settled in 1844 and not incorporated until 1963 (Stewart, 2010). Growth was stunted as railroads and major highways bypassed the settlement (Stewart, 2010). However, per aerial imagery, development rose in northeast Ovilla by the fifties. The town remained rural until the eighties with the introduction of several subdivisions north (within the project area) and east.

Glenn Heights, located in the central western half of the project area, is a suburb of Dallas incorporated in 1969 (Jasinski, 2010). Per aerial imagery, the first signs of development in Glenn Heights are apparent by the late sixties and flank South Hampton Road. Gradually, as the demand for housing rose in Dallas County, Glenn Heights expanded south of West Bear Creek Road.

Red Oak, located in Ellis County, is east of Red Oak Creek and located at the eastern end of the project area. Red Oak was settled circa the mid-nineteenth century as an agricultural community. The town was serviced by the Missouri, Kansas and Texas Railroad by 1890 (Brown, 2010). IH 35E was constructed through Red Oak in 1959. However, the early stages of suburban development are not evident until the late sixties. Sparse development is confined to directly east and west of I-35E and densifies and expands further east and west of IH 35E by the seventies.

The number of registered vehicles nearly doubled to 18,493. Development along I-35E and the growth of Waxahachie set a commercial trend in Ellis County. By 1972, slightly larger subdivisions were introduced into the rural landscape along US 67 and IH 35E near the towns of Glenn Heights and Red Oak. Additionally, smaller subdivisions began developing along Red Oak Creek. Agriculture fields still dominated the project area, though. Historic aerials from 1982 show little change from ten years prior, but a few larger subdivisions began to dot areas closest to Red Oak Creek.

Although a less significant industry by the twenty-first century, Dallas County's agriculture was led by horticultural crops, wheat, corn, and horses. While the number of farms had decreased from 3,519 in 1920 to 927 in 1987, their value spiked. By the 1980s, both manufacturing and the service industry led Dallas County's economy (Maxwell, 2019).

By 1990, Ellis County's various industries, manufacturing, agriculture, and commerce, stabilized. Most citizens of Dallas and Ellis Counties were employed in Dallas, a reminder of the economic ties between Ellis County and the Dallas-Fort Worth area. By the twenty-first century, 2,089 farms remained in the county; 59 percent purposed for crop production, including cotton, hay, wheat, sorghum, in addition to cattle, horses, turf grass, and nursery plants (Haaser, 2016). Agricultural lands still exist in the western half of the project area and scattered along Red Oak Creek, Little Creek, and between suburban developments. However, driven by economic growth in Dallas, midcentury and modern development have continued to expand in the project area, encroaching on the remaining farmsteads and pastureland.

National Register Eligibility Recommendations

- **Eligible Properties/Districts**

Survey efforts did not identify any properties recommended eligible for NRHP listing.

- **Ineligible Properties/Districts**

Domestic Properties

Domestic properties usually refer to residential properties, but also include motels, hotels, hostels, shelters, and other locations where people may sleep. Survey efforts identified 80 domestic properties in the project APE. Many of the surveyed domestic properties are small farmsteads, and therefore, consist of several outbuildings, including small sheds, garages, machine sheds, and barns. Most domestic properties contain a small shed in the backyard, so visibility is limited due to vegetation or other buildings/structures.

A domestic building can be eligible for NRHP listing under Criterion C if it was constructed in or prior to 1982 and it retains a significant amount of its architectural integrity; i.e., it should appear much as it did at the time of construction or when it was sympathetically altered in or prior to the historic survey cut-off date. Significant additions and unsympathetic alterations, such as the application of synthetic siding, replacement of wood-sash or steel casement windows with aluminum units, diminish the building's architectural integrity and make it ineligible for NRHP listing. In addition, the domestic building should be clearly associated with one of the significant historic themes listed above. Buildings eligible under Criteria A or B should have strong historical associations, but can be altered, and do not even have to be particularly noteworthy examples of an architectural style, form, or type.

Ranch Style

The Ranch style (American Ranch, Western Ranch, or California Rambler) originated in the early 1930s in California loosely following the Spanish Colonial precedents in California filtered through Craftsman and Prairie house styles that had been widely popular earlier in the twentieth century. The style remained largely confined to California until after World War II. A combination of factors created a "perfect storm" that led to the wide popularity of the Ranch style in the 1950s and 1960s: the demand for single family housing by World War II veterans starting families; the GI Bill, which provided many different types of loans for returning veterans to buy homes; an increase in automobile ownership, which freed workers from the need to live close to public transportation routes; and the strict FHA-VA guidelines under which developers operated in order to be able to market the houses to buyers using FHA and VA government-subsidized mortgages.

Because Ranch houses are very common, the bar of individual architectural significance tends to be high.

Ranch style houses have several notable character-defining features. They are usually horizontally oriented, parallel to the street with asymmetrical facades. The roof is low pitched, either gabled or hipped, with large eaves. Windows tend to be large and plentiful. Fixed picture windows and sliding glass doors are common. The overall form emphasizes the horizontal, accentuated by low walls, horizontal wood, brick, or stone siding, and a long, narrow shape with relatively simple floor plans and an attached garage (McAlester 2013: 597-612).

Ranch style houses are the dominant architectural style identified by the survey, present on 75 percent of all surveyed properties. Most are common examples of the style, exhibiting the basic characteristics, such as orientation to the street, horizontal emphasis, low pitched hipped or gabled roofs, attached garages, and prominent windows. Most Ranch style resources feature linear plans, as noticed in **Resource No. 16a** and **Resource No. 18**. Several examples have symmetrical front facades, including **Resource No. 25**, which features a recessed porch with two projecting bays flanking either side of the porch. **Resource No. 21** has a partial-width porch centered on the front façade with a side-gable roof with a lifted/tiered center extended over the porch, creating a symmetrical front façade.

A few demonstrate specific stylistic flourishes, such as “Swiss Chalet” trim and extended rooflines (see **Resource No. 82**) and “Victorian” trim (see **Resource No. 04**). While not representative of any stylistic influences, **Resource No. 21a** has exposed rafter tails under its eaves, a characteristic unique to this Ranch style house. Brick siding with stretcher bonding is very common and comes in a variety of colors, including red, cream, grey, and polychrome, as seen in **Resource No. 15a**. **Resource No. 22a** features yellow brick, whereas **Resource No. 28** is painted grey. Other common siding materials include vinyl (**Resource No. 05a**), wood (see **Resource No. 12**), cedar shake (see **Resource Nos. 7 and 46a**), and stone (see **Resource Nos. 48 and 47a**). A second material is often used on the gable ends, such as wood or vinyl siding, as noted in **Resource No. 21a**. Vinyl siding is commonly used as a replacement material, while brick siding tends to be original.

Windows are generally metal sash, often replaced with modern metal or vinyl sash windows, although original windows are not uncommon. In some cases, as seen in **Resource Nos. 02, 22a, and 56**, houses maintain their original diamond-paned windows or original casement windows (see **Resource No. 84**). Windows are often adorned with false louvered shutters, as identified in **Resource Nos. 58 and 59**. Porches are typically partial-width or small and recessed with a wide variety of support posts, including turned wood (see **Resource Nos. 04 and 11**), classical columns (see **Resource Nos. 42a and 46a**), decorative metal (see **Resource Nos. 44a and 51**), squared wood and brick columns (see **Resource Nos. 15a and 78**), and rustic wood supports (see **Resource No. 39a**).

Most houses have chimneys, and while most are located on the rear slope of the roof (see **Resource Nos. 25, 27, and 34**), **Resource No. 02** has a straddle ridge chimney, while **Resource Nos. 05a and 57** feature an exposed chimney located on the front façade. Attached garages are a frequent occurrence in the project area and are usually located on a side façade (see **Resource Nos. 30a and 35**). Most surveyed Ranch style houses are single story, but a few feature two story additions. Modern additions are a common feature among resources in the project area, as noted in **Resource No. 15a**, which has a two-story addition and **Resource No. 04**, which has a second-story addition completed with a Victorian-influence turret and trim.

The subdivision constructed directly west of South Hampton Road in Glenn Heights is comprised of Joe Top Road, Sleepy Top Road, and Tin Gee Top Drive. Formed in the mid-to-late seventies, the subdivision consists of **Resource Nos. 57 through 66**, in addition to several properties outside of the project APE. The surveyed properties are located along Pearly Top Road and Sleepy Top Road and consist of Ranch style houses circa 1973 through 1976. Parcels are of consistent size and shape (rectangular) with houses positioned at similar setbacks and oriented parallel to the road. Houses tend to be linear in plan and may feature an ell. Driveways and walkways leading to the houses' main entrances extend to the road. Attached garages are located on one of the side facades of the houses. No sidewalks are present.

Resources within the subdivision are representative of the Ranch style houses found throughout the project area. The primary siding material is brick; however, the brick veneer is seen in several shades, including red, grey, and cream. **Resource No. 62a** is unique in that it features a herringbone brick pattern, as well as half-timbering and stucco. Roof types vary and include side-gable, hipped, and clip-gable. Several houses showcase Colonial Revival influence with the use of temple-front entry porticos, false shutters, and columns (see **Resource Nos. 61 and 66**), while other houses lack additional stylistic influence. **Resource Nos. 60, 63, 65, and 66** feature rounded arches, either as window shapes, over the recessed entry, or surrounding the porch.

Properties along Pearly Top Road and Sleepy Top Road have additional resources, most commonly modern sheds. Modern features also include replacement windows and vinyl siding, affecting integrity of materials and design.

The Ranch style houses in the project APE are modest examples that individually do not convey any significance or association with important historic events, trends, persons, or architectural movements under Criteria A, B, and C. In addition, many feature replacement materials and modern additions, ultimately compromising integrity of material, design, and workmanship. Therefore, they are recommended *not eligible* for NRHP listing.

Craftsman

Craftsman style houses reached popularity from 1905 to 1930. Brother architects, Charles Sumner Greene and Mather Greene began designing Craftsman bungalows by the early twentieth century in California. Their designs quickly became the most fashionable choice for smaller American houses due in large part to pattern books and magazines. The Greene brothers were most likely inspired by the English Arts and Crafts movement and Asian wooden architecture. Craftsman style houses typically feature a low-pitched, gable roof; wide overhanging eaves; exposed rafter tails; decorative beams under gables; deep full or partial-width porches; and tapered, squared columns often over pedestals. Single-story, simpler designs are often referred to as bungalows.

Of the 84 properties surveyed, the project historians identified two properties with Craftsman-style single-family dwellings. **Resource No. 50a** is located on a small farmstead at 2011 S. Westmoreland Rd. and discussed further under Agricultural Properties, below. **Resource No. 78** features a Craftsman-style bungalow with a clip-gable roof with generous eaves and brackets, horizontal vinyl siding, a partial-width porch with a shed roof, and replacement windows. It has no known association with important historic events, trends, or persons under Criteria A and B. While the house displays Craftsman influence, it is a relatively simple interpretation of the style and suffers from numerous small changes and modifications, limiting its architectural significance under Criterion C. As such, it is recommended *not eligible* for NRHP listing.

Minimal Traditional

In the late 1930s, suburban builders introduced a new style of domestic architecture. The “Minimal Traditional” style (as named by Virginia and Lee McAlester in *A Field Guide to American Houses*) was a simplified form of the Tudor Revival and Colonial Revival styles of the 1920s and 1930s. The new, economically built dwellings had reduced ornamentation, scale, and floor space, reflecting the privations of the Great Depression and, later, material shortages during and immediately following World War II. The houses are normally less than 1,000 square feet in size and one story in height with side-gabled roofs. Other character-defining features include façade gables, a small porch at the main entrance, a detached garage, and flush eaves. Exterior wall coverings are normally weatherboard or transite siding. Windows are typically placed as single units. Early examples have double-hung wood sashes with multi-light glazing, while postwar examples have steel casement windows. Doors are typically traditional wood panel with small glass lights. Decoration is limited to exterior shutters and ornamental metal porch supports. These houses were the dominant style of suburban domestic architecture from the late 1930s until the early 1950s and are common throughout America.

Survey efforts identified one Minimal Traditional resource, **Resource No. 20a**. features a side-gable roof with exposed rafter tails and generous eaves, horizontal wood siding, a covered stoop with a flat roof and decorative iron posts, replacement windows, and a rear

addition with a side-gable roof. Additionally, the property includes a detached garage (**Resource No. 20b**), a barn (**Resource No. 20c**), and a pole barn (**Resource No. 20d**). The property does not share any known association with historically significant events, trends, or persons under Criterion A or B, and **Resource No. 20a** is a modest example of the style and features replacement materials impacting integrity. Therefore, **Property No. 20** is recommended *not eligible* for National Register listing.

Queen Anne/Folk Victorian

The Queen Anne style is one of the quintessential “Victorian” architectural styles, common throughout the country in the late decades of the nineteenth century and into the first decade of the twentieth century. Popularized by a group of nineteenth century English architects, the style’s primary defining characteristics include an irregularly shaped, steeply pitched roof with a dominant forward gable, patterned shingles, bay windows, partial to full width porch that may wrap around a corner, and fanciful detailing. Other common features include a single pointed tower to emphasize the asymmetrical façade, patterned masonry chimneys, parapets, recessed upper story porches, and finials. The general term “Folk Victorian” is often used to describe low-style houses that borrow parts of the Queen Anne style (and contemporary styles) without fully embracing them.

Survey efforts identified one Folk Victorian style resource in the project area. **Resource No. 31a** is discussed further under Agricultural Properties, below.

I-House

In its most basic form, the I-house was introduced to the American landscape by the late seventeenth century and evolved to become a prevalent architectural type by the twentieth century and became synonymous with agricultural wealth (Carney, 2020). By the mid-nineteenth century, settlers migrating to Texas constructed a brick variation of the house-type, while later versions were often of frame or log construction. By the late nineteenth century, I-houses typically featured a porch or portico, either an early two-story or later one-story example. Gabled ells were often added to a house, forming an L or T shape plan (Abernethy, 1979: 29). Other distinctive characteristics include side-gable roofs, a one room deep by a minimum of two rooms wide configuration, and two stories. Ornamentation varies from simple to ornate (Carney, 2020).

Survey efforts identified one I-house in the project area, **Resource No. 24a**. features a steep-pitch, side-gable roof, replacement horizontal wood siding, partial-width stacked porches with square columns and railings, replacement wood-sash windows, and a rear addition. The house possesses no known association with historically significant events, trends, or persons under Criterion A or B. Additionally, **Resource No. 24a** features replacement materials, negatively impacting the integrity of materials under Criterion C. Therefore, **Resource No. 24a** is recommended *not eligible* for the National Register.

No Discernible Style

Some residential properties identified by survey efforts do not fall into any particular stylistic classification. This may be due to use of generic building patterns or floor plans, remodeling and additions, or a desire to place function over form. While some of these houses may have influences from a particular style, they generally do not display sufficient character-defining features to be included within that style description. Nonetheless, such buildings may still be eligible under Criterion C depending on materials, features, and other distinctive characteristics that evoke a particular time period.

Resource No. 71 is a small, single-family dwelling with a side-gable roof, horizontal vinyl siding, a partial-width porch with a metal shed roof and wood supports, and replacement windows. The property has no known association with important historic events, trends, or persons under Criteria A or B. In addition, the house possesses no discernible style and has undergone several modern alterations, including replacement vinyl siding, a porch, and sash windows, limiting its architectural significance under Criterion C. Therefore, **Resource No. 71** is recommended *not eligible* for NRHP listing.

Agricultural Properties

Agricultural resources include a variety of buildings, objects, and structures with varying roles in the production of crops and livestock. The form of individual elements, as well as their arrangement of the buildings, fields, fence lines, and vehicular access, often reflects the type of farming or ranching originally practiced. Postwar ranches saw a shift to premanufactured metal buildings and silos and an increase in recreational ranches where owners leased their land to active ranches. At some point, landowners separated the homesite plot on one acre or so from the entire acreage to address property taxes and agricultural exemptions. This pattern is not visible from the streetscape but is noticeable when reviewing aerial maps and reviewing county records superimposed over aerial maps.

Agricultural resources may be eligible under Criterion A if they have known associations with a historic event, trend, or ethnic group, or under B for association with a significant person or group of persons. To be considered eligible in the area of Agriculture, they must show a clear association with historic agricultural methods and retain integrity to convey how such methods were used. Agricultural resources are usually evaluated under Criterion C for the architecture of the primary residence or building.

Agricultural properties, farms and ranches, are best understood when separated into functions: Domestic work zone, Agricultural work zone, and fields/pastures. The residential portion of an agricultural property includes a domestic work zone. "Common types of resources found within the domestic work zone are: main house, privy, garage or carport, domestic shed, cistern, well, windmill, well house and pump house, worker housing, chicken coop, storm shelter, smokehouse, [and] landscaping features (including vegetation, fences, gates, paths, driveways)" (TxDOT 2013 p.5-2). Several properties in

the project APE had several agricultural outbuildings of some type (mostly small sheds or barns), but several appear to no longer be used for agricultural purposes.

The agricultural work zone includes structures which support the daily management and operation of the property. Common resources in this area include barn, work shed, silo, corrals, pens, stock tank, grain storage and self-feeders (TxDOT 2013 p.5-34). “The agricultural zone is usually located close to the domestic work zone, mainly to allow workers easy access to both areas. This zone is also located adjacent to the fields and pastures so equipment and/or feed can be moved directly into the fields and pasture zone” (TxDOT 2013 p.5-34). To access the agricultural zone there is often a driveway direct from the main road separate from the driveway to the main house. The agricultural work zone is often not enclosed by fencing.

Fields and pastures are the third zone for an agricultural property. Common resources found in this zone include drainage ditch, self-feeder, stock tank, corrals, fences, cattle guard, and contouring or terracing for soil conservation.

Agricultural Complexes

Agricultural complexes are ranches and farmsteads with a historic-age domestic work zone, agricultural work zone, and associated fields or pasture (actively cultivated/grazed or fallow). They vary greatly in size and complexity, ranging from simple compounds with a house and a handful of outbuildings to large organized properties with multiple groupings of outbuildings of differing functions. Many of the agricultural properties identified by the survey did not appear to be used for active agricultural practices, but others did have observable activities occurring at the time of survey.

Property No. 8 is a large ranch consisting of a recently historic (circa 1985) Ranch style house (**Resource No. 08a**) and several older barns and shed (**Resource Nos. 08b-08g**). The property is not accessible from public ROW, with the driveway blocked by an elaborate modern gate. An examination of historic aerials shows that the barns and shed pre-date the house, with the outbuildings varying in age from circa 1965 (**Resource Nos. 08b, 08c, 08f, and 08g**) and circa 1975 (**Resource Nos. 08d and 08e**). The barns are arranged in one agricultural work zone, while the two sheds are in a second agricultural work zone. The fields/pastures are located to the north and west of the domestic and agricultural work zones. A stock tank is located adjacent to the house/domestic work zone. Although project historians did not have access to the property, based on the age of the buildings and an examination of historic aerials, the potential for significance under Criteria A and/or C is minimal (**Figures 5 and 6**). The property has no known association with important historic persons under Criterion B. As such, it is recommended *not eligible* for NRHP listing.

Several agricultural buildings and structures associated with **Property No. 10** are located within the domestic and agricultural work zones of the farmstead. **Resource No. 10a** is the circa 1962 Ranch style house located within the domestic work zone of the property.

The house features multiple shallow-pitched, side-gable roofs, cream brick siding, and replacement sliding windows. Within the domestic work zone, **Resource No. 10c** is a possible shed. Viewing was limited due to vegetation. Per aerial imagery, the building features a rectangular footprint and a hip roof. Several modern buildings are located within the agricultural work zone and associated fields and pastures, including a large horse stable and attached barn, horse exercise corrals and covered pens, and two machine sheds. **Resource No. 10b**, a barn, is the only historic-age resource within the agricultural work zone. Viewing is limited due to vegetation and topography, so historians relied on aerial imagery. The barn appears to have a square footprint and a metal, gable roof.

The property has no known association with important historic events, trends or persons under Criteria A and B. The horse stable and barn are modern additions to the property. **Resource No. 10a** has been altered by way of replacement windows and is a modest example of Ranch style architecture, and therefore recommended *not eligible* for NRHP listing under Criterion C.

Resource No. 14 is a vacant residence that appears to have once been part of a farm or ranch. Although project historians did have ROE to the parcel, extensive growth of poison ivy across the old access drive prevented further egress or observation of the house. Based on a comparison of historic and more recent aerials (**Figures 7 and 8**), the house appears to have been vacant for the past twenty years. The remains of fencing are visible due east of the house, and one additional outbuilding may be located due west. The 1970 aerial does not show any other buildings on the property. Although project historians were unable to directly observe the property, it is unlikely it retains sufficient integrity to convey any significance it may possess under Criteria A, B, or C, and is tentatively recommended *not eligible* for NRHP listing.²

Property No. 17 is a small ranch consisting of a mid-1970s Ranch style house (**Resource No. 17a**), several circa 1980 barns (**Resource Nos. 17b, 17c, 17d, and 17g**), and two older, circa 1970 sheds or barns (**Resource Nos. 17e and 17f**). Several of the buildings had limited visibility due to vegetation, topography, and distance. The house is the lone building in the domestic work zone; the barns are located in a separate agricultural work zone adjacent to the fields. A comparison of modern aerial photos with historic aerial imagery suggests the property may once have been a horse or cattle ranch with a show ring, but little remains of that today. No animal husbandry was observed during field survey, and aerials suggest no animal husbandry has occurred since 2012 (**Figures 9 and 10**). The house itself is a standard Ranch style home with a side-gable roof, brick siding, partial-width porch, replacement windows and panel and louvered shutters.

² See further note under **Recommendations for Further Study**, below.

The property has no known association with important historic events, trends, or persons under Criteria A and B. The main house has been altered with replacement windows and is a modest example of the style; it does not rise to level of significance required under Criterion C. As such, the property is recommended *not eligible* for NRHP listing.

Property No. 20 is a small cattle ranch consisting of a circa 1945 house (**Resource No. 20a**), a circa 1950 garage (**20b**), a circa 1950 barn (**20c**), and a circa 1950 pole barn (**20d**). The house is of the Minimal Traditional style with some Craftsman influences and features a side-gable roof with exposed rafter tails and generous eaves, horizontal wood siding, a covered stoop with a flat roof and decorative iron posts, replacement windows, and a rear addition with a side-gable roof. The garage has asbestos shingle siding, original windows, two replacement garage doors, and a rear addition. The barn and shed both feature metal siding. The house and garage are within the domestic work zone, with the barn in an agricultural work zone and the shed in a small field/pasture. A larger field and pasture are located west of the domestic work zone, beyond a stand of trees. A stock tank north of the barn is intermittently dry.

This property was reported to be owned by the same family for over 100 years at a public meeting for the project. However, all of the existing buildings on the property date to the mid-twentieth century at the earliest. Although no animals were observed during field survey, aerial images do show a small herd of cattle on the property. Historic aerials support the property's agricultural use during the historic period.

Although the property does appear to host a small number of cattle, historically farming was more important to the Dallas County agricultural economy under Criterion A. The owners, the Chauvin family, do not seem to have any local significance (someone sharing the name with the current owner, Judge M. Chauvin, passed in 1940 and is buried in a cemetery off IH 20 to the north). The house itself is modest, with replacement windows and a rear addition, and does not rise to a level of significance required under Criterion C. As such, the property is recommended *not eligible* for NRHP listing.

Resource No. 26 is an isolated front-gabled metal barn with no other buildings on the parcel. It does not appear to be associated with any historic-age residence or other outbuildings. The barn is not visible from public-right-of-way, and historians had no right-of-entry. The property has no known association with historically significant trends, events, or persons under Criterion A or B, and per aerial imagery, the barn is not an exemplary example of architecture under Criterion C. Therefore, **Resource No. 26** is recommended *not eligible* for listing.

Property No. 31 is a large farm consisting of a circa 1905 folk Victorian home (**Resource No. 31a**), a circa 1930 wood garage (**31b**), a circa 1940 metal pole barn (**31c**), two circa 1940 metal loafing sheds (**31d and 31e**), a circa 1950 metal pole barn (**31f**), and a vacant circa 1930 wood barn (**31g**) buried in trees. The house is a mixed Folk Victorian house featuring a cross-gable roof, original horizontal wood siding, a covered verandah

with a shallow-pitch, hipped roof square columns, replacement windows, a large addition which includes an attached garage, and a front slope, stone chimney. The wood-frame garage features two open bays, a front-gable metal roof and a shallow-pitch, metal shed roof, and vertical and wood siding. These two buildings form the basis of the domestic work zone, although this zone blends in with the agricultural work zone due to proximity and lack of defined boundaries or fencing. The two nearby barns feature metal siding and roofing. To the north, the second loafing shed and barn comprise an agricultural work zone. Buried in a clump of trees near **31c** is a large vacant wood barn (**31g**) with vertical board siding, missing barn door, and gabled roof with metal roofing. The barn is hidden from view except during winter months and was not observable at the time of survey; it was identified later with the help of historic aerials and observed using back-dated Google Streetview imagery (**Figure 11**). The agricultural buildings comprise the agricultural work zone. The cultivated fields are divided into two sections. Immediately adjacent to the work zones are three small cultivated fields to the west (surrounding the hidden barn) and northwest. The primary fields are to the east and north of the farmstead core. All fields appear cultivated and in some degree of use.

The farmstead is significant as a surviving example of an early twentieth century farm in south Dallas County under Criterion A at the local level, in the area of Agriculture. Its period of significance is 1905-1940, covering the pre-World War II agricultural focus of the county. However, the farmstead lacks sufficient integrity to convey this significance. The farmhouse has undergone significant alterations with a large incompatible addition composed of a new garage with living space. This addition greatly impacts integrity of design, materials, workmanship, and feeling. The original garage has an historic-age addition and appears to be used solely for storage. The metal barns appear to be in use for storing equipment. The large wood barn is no longer in use, in poor condition, and generally inaccessible, impacting integrity of materials, workmanship, feeling, and association. While the working barns do house some farm equipment, they are of a size incapable of working the large primary fields; this equipment is likely kept off-site and may not be operated by the property owners.

These changes compromise the domestic work zone to a significant degree, and the farmstead lacks sufficient integrity of design, materials, workmanship, and feeling to convey its significance under Criterion A. It has no known association with persons of historic importance under Criterion B. The farmhouse lacks sufficient architectural integrity for consideration under Criterion C, as noted above. It is thus recommended *not eligible* for NRHP listing.

Property No. 50 is a small horse ranch consisting of a circa 1920 Craftsman influenced bungalow (**Resource No. 50a**), a contemporary wood barn (**50b**), a circa 1950 shed (**50c**), and a circa 1950 stable (**50d**). The house has a metal hip roof, exposed rafter tails, replacement siding, a full-width porch with rustic wood supports, and replacement windows. The barn features a metal front-gable roof and a metal shed roof, vertical wood

siding, and a hay loft. The shed and stable both feature wood siding and metal roofing. Also on the property are several modern loafing sheds and barns, along with horse training facilities; these amenities all date to within the past twenty years. Overall, the property has no known association with important historic events, trends, or persons under Criteria A and B. The main house has undergone alterations and is not a good example of the Craftsman style under Criterion C. As such, it is recommended *not eligible* for NRHP listing.

Commercial Properties

Generally, a commercial building is any resource originally built for commercial purposes. The oldest examples and densest concentrations are found in urban settings, typically in central locations, such as downtowns where they form one and two-part commercial blocks. However, other examples of this property type are also found in suburban settings, along principle roadways, at major street/road intersections, or at other hubs of activity. They may be single buildings housing one or two business, or large structures supporting dozens of separate commercial enterprises. Later examples often include ample off-street parking in front of or even surrounding the building(s); by the mid-century, parking lots became a primary feature of strip malls, shopping malls, and freestanding commercial buildings.

A commercial building can be eligible for NRHP listing under Criterion C if it was constructed in or prior to 1982 and it retains a significant amount of its architectural integrity; i.e., it should appear much as it did at the time of construction or when it was sympathetically altered in or prior to the historic survey cut-off date. Significant additions and unsympathetic alterations, such as the application of synthetic siding, replacement of original windows, added awnings, and altered facades, diminish the building's architectural integrity and make it ineligible for NRHP listing. In addition, a commercial building should be clearly associated with one of the significant historic themes listed above. Buildings eligible under Criteria A or B should have strong historical associations, but can be altered, and do not even have to be particularly noteworthy examples of an architectural style, form, or type.

The survey identified one historic-age commercial resource in the APE. **Resource No. 40** is a former ranch style house, now restaurant, with a complex roof system consisting of steep side-gable roofs, two metal shed roofs, and a shallow-pitch, side-gable roof. The building features wood panel siding, an open porch with a metal, shed roof, and replacement windows. The property is currently occupied by Juicy Bones Restaurant at BoxCar. The property has no known association with important historic events, trends or persons under Criteria A and B. **Resource No. 40** is an altered and modest example of Ranch style architecture. The building has been altered to accommodate a restaurant by way of additions, replacement siding, replacement windows, and a modern porch with ramp. Therefore, **Resource No. 40** is recommended *not eligible* for NRHP listing under Criterion C.

Healthcare Properties

Per the National Park Service National Register Bulletin: How to Complete the National Register Registration Form, healthcare properties are properties which contribute to “the care of the sick, disable, and handicapped; [and] the promotion of health and hygiene” (41).

The survey identified one historic-age healthcare property in the APE. Resource No. 83 is occupied by Country Veterinary Clinic which consists of an office building (**Resource No. 83a**), a barn (**Resource No. 83b**), and an RV shed (**Resource No. 83c**). **Resource No. 83a** features an office building with a shallow-pitch, metal gable roof, metal siding, a vestibule, and replacement windows. A large addition spans from the north façade. The addition, circa 1981, features a shallow-pitch, metal, gable roof, metal siding, a sliding bay door, and a metal cantilevered structure across the north façade. **Resource No. 83b** is a barn with a shallow-pitch, metal gable roof and metal siding. **Resource No. 83c** is a large RV shed with a metal shed roof and steel supports. The property has no known association with important historic events, trends or persons under Criteria A and B. In addition, the resources do not possess distinctive characteristics of an architectural style, nor do they possess great artistic value or the work of a master under Criteria C. Therefore, the property is recommended *not eligible* for NRHP listing.

▪ Recommendations for Further Study

Several properties have limited or no visibility from public ROW and lacked ROE. Most of these properties are mid-1970s complexes with a main house and outbuildings and exhibited limited evidence of ranching or agricultural pursuits. Based on historic aerials, their potential for significance due to their age (and the difficulty of evaluating properties barely 40 years old due to the extended letting date) is limited, and they are not recommended for further study (e.g., **Property No. 08**)

One property, **Resource No. 14**, had ROE, but extensive growth of poison ivy and other vegetation prevented access to the property as detailed above. Based on its vacant status, project historians do not feel it is likely to be eligible as noted above. However, it is within the footprint of Alternative 1 and would be directly impacted by construction. Further study may be warranted should additional information from consulting parties suggest it has potential significance.

Two other properties had no ROE and no visibility from public ROW. **Resource No. 19a** is a 1970s house with a Ranch style footprint per historic aerials. Dallas CAD data lists brick siding and a gabled roof. The house has a small shed (19b) as well. It is completely obscured from public ROW by multiple layers of thick vegetation and would be taken by Alternative 4 (**Figure 10**). **Resource 33** is a house of unknown style with a complex roofline per historic aerials (**Figure 12**). According to Dallas CAD, the house was constructed in 1978 and is one-and-a-half stories with brick siding, a gable roof, and an attached garage and carport. Other unusual buildings including a large round dome constructed in 2005,

and several round outbuildings are visible on aerials. The house would not be directly impacted by the proposed project, but the corner of the parcel would be clipped (possibly resulting in the loss of some outbuildings). Both properties are candidates for further study due to their unknown architectural style and potential for adverse effect.

A fourth property is almost entirely unknown. **Resource No. 09** is a likely mid-1970s house (CAD date 1976) completely hidden from view, both from the ground and in aerials. The parcel has no ROE. It is within the project footprint of Alternative 1, and thus would be directly impacted by this alternative. It is recommended for further study based on its unknown architectural potential.

Determination of Section 106 Effects Recommendations

▪ Direct Effects

As none of the surveyed resources in the project APE are listed in or recommended eligible for listing in the NRHP, the proposed undertaking would have no direct effect on historic properties. Assuming none of the properties recommended for further study are determined eligible, the proposed undertaking would have no effect on historic properties.

▪ Indirect, Cumulative or Reasonable Foreseeable Effects

With no NRHP-listed or eligible properties located within the project study area, the proposed undertaking would have no indirect effect on historic properties. Due to the new location nature of the project, however, it may have a cumulative impact on the overall health of the project area.

Determining cumulative impacts on historic properties relies on identifying general patterns of change in the human environment relevant to historic properties and evaluating whether or not a project under study follows these patterns (King, 2006). The project area has been subjected to continuous development since the historic period, particularly suburban neighborhood growth. This pattern has increased in the current century, with multiple new neighborhoods constructed or currently under construction in the past ten years. It is unlikely the construction of Loop 9 would substantially alter this existing pattern of development beyond a possible acceleration. Construction would likely continue without the presence of the new roadway, a pattern common throughout Dallas County as the population increases. As the existing patterns of change appear to be independent of the roadway's construction, the proposed undertaking is not anticipated to have a cumulative effect for the reasonably foreseeable future.

U.S. DOT Section 4(f) Applicability Statement

As the project has no identified listed or eligible NRHP properties and would not constitute a transportation use of a historic property, no Section 4(f) analysis would be required at this time. Should further study identify an eligible historic property, additional analysis may be required to see whether or not Section 4(f) would apply to the eligible property.

References Cited

Abernethy, Francis Edward

- 1979 "Built in Texas, Issue 42." University of North Texas Press, Denton: 1979.
(Accessed May 14, 2020)

Brown, Scott

- 2010 Handbook of Texas Online, s.v. "Red Oak, Texas."
<https://tshaonline.org/handbook/online/articles/hjr05> (accessed August 15, 2019)

Carney, George O.

- 2020 "I-House," The Encyclopedia of Oklahoma History and Culture, Oklahoma Historical Society.
<https://www.okhistory.org/publications/enc/entry.php?entry=IH001>.
(accessed May 14, 2020)

EarthExplorer

- 2020 EarthExplorer website (<https://earthexplorer.usgs.gov/>), accessed May 6, 2020.

Ellis County Museum, Inc.

- 2020 "Ellis County History." Ellis County Museum, Inc.
<http://sites.rootsweb.com/~txecm/index.htm> (accessed May 4, 2020)

Haaser, Robert

- 2016 Handbook of Texas Online, s.v. "Ellis County."
<https://tshaonline.org/handbook/online/articles/eqc05> (accessed August 14, 2019)

Jasinski, Laurie E.

- 2010 Handbook of Texas Online, s.v. "Glenn Heights, Texas."
<https://tshaonline.org/handbook/online/articles/hfg09> (accessed August 15, 2019)

King, Thomas F.

- 2006 "The Cumulative Impacts of Transportation Projects on Cultural Resources: What Are They and How Can We Assess Them?" Paper presented at the Summer 2006 meeting of the Archeological and Historic Preservation in Transportation (ADC50) Committee, Williamsburg, Virginia.

<http://crmplus.blogspot.com/2007/12/cumulative-effects.html> (accessed March 2, 2020)

Maxwell, Lisa C.

- 2019 Handbook of Texas Online, s.v. "Dallas County."
<https://tshaonline.org/handbook/online/articles/hcd02> (accessed August 15, 2019)

Moore, David W. Jr., M. Freemond, and M. Russo

- 2013 Agricultural Theme Study for Central Texas. Historical Studies Report No. 2013-01. Texas Department of Transportation, Austin.

McAlester, Virginia

- 2013 *A Field Guide to American Houses*. Alfred A. Knopf: New York, 2013.

McClellan, Lisa

- 1997 How to Complete the National Register Registration Form. National Register Bulletin No. 16A, Guidelines for Completing National Register of Historic Places Forms. National Park Service, U.S. Department of the Interior, Washington, D.C.

Reed, S. G.

- 1941 *A History of the Texas Railroads*. St. Clair Publishing Company, Houston. Reprinted by Arno Press, New York, 1981.

Stewart, Paula

- 2010 Handbook of Texas Online, s.v. "Ovilla, TX."
<https://tshaonline.org/handbook/online/articles/hdd01> (accessed September 20, 2019)

Werner, George C.

- 2010 Handbook of Texas Online, s.v. "Houston and Texas Central Railway."
<https://tshaonline.org/handbook/online/articles/eqc05> (accessed August 14, 2019)

Appendix A: Project Information and ROW Information

[Back To List](#)

- [WPD Section I - Project Definition](#)
- [WPD Section II - Tool](#)
- [WPD Section III - Project Work Plan](#)
- [WPD Section IV - Findings](#)

[+ -](#) [Archived WPD I](#) [Print this Page](#)

Project Definition

Project Name:

CSJ: - -

Anticipated Environmental Classification:

☒ Is this an FHWA project that normally requires an EIS per 23 CFR 771.115(a)?

☐ Project Association(s)

Manually Associate CSJ:

| CSJ | DCIS Funding | DCIS Number | Env Classification | DCIS Classification | Main or Associate | Doc Tracked In | Actions |
|--|--------------|-------------|--------------------|---------------------|-------------------|----------------|---------|
| There are currently no Project Associations added to this project. | | | | | | | |

☐ DCIS Project Funding and Location

Funding

DCIS Funding Type:

☒ Federal ☒ State ☐ Local ☐ Private

Location

DCIS Project Number: Highway:

District: County:

Project Limit -- From:

Project Limit -- To:

Begin Latitude: + . Begin Longitude: - .

End Latitude: + . End Longitude: - .

☐ DCIS & P6 Letting Dates

DCIS District: DCIS Approved: DCIS Actual:

P6 Ready To Let: P6 Proposed Letting:

☐ DCIS Project Description

Type of Work:

Layman's Description:

DCIS Project Classification:

Design Standard:

Roadway Functional Classification:

☐ Jurisdiction

Does the project cross a state boundary, or require a new Presidential Permit or modification of an existing Presidential Permit?

Who is the lead agency responsible for the approval of the entire project?

☒ FHWA - Assigned to TxDOT ☐ TxDOT - No Federal Funding ☐ FHWA - Not Assigned to TxDOT

TxDOT

Who is the project sponsor as defined by 43 TAC 2.7?

Yes

Is a local government's or a private developer's own staff or consultant preparing the CE documentation, EA or EIS?

Yes

Does the project require any federal permit, license, or approval?

☒ USACE ☐ IBWC ☐ USCG ☐ NPS ☐ IAJR ☐ Other

No

Does the project occur, in part or in total, on federal or tribal lands?

☐ Environmental Clearance Project Description

Project Area

Typical Depth of Impacts: 6 (Feet)

Maximum Depth of Impacts: 55 (Feet)

New ROW Required: 616 (Acres)

New Perm. Easement Required: 0 (Acres) New Temp. Easement Required: 0 (Acres)

Project Description

Describe Limits of All Activities: Spell

The proposed Loop 9, Segment A project includes the construction of a six-lane new location frontage road system between United States 67 (US 67) and Interstate Highway 35 East (IH 35E) through Dallas and Ellis counties, Texas, and is approximately 9.4 miles in length. The proposed Loop 9 roadway system would pass through the Cities of Cedar Hill, Ovilla, Glenn Heights, and Red Oak. The proposed project right-of-way (ROW) would include a median that would accommodate the future construction of an ultimate access-controlled mainline facility. Construction of the ultimate access-controlled mainline facility would be based on projected traffic and funding and would require additional environmental analysis prior to construction.

Describe Project Setting: Spell

This project is located in a developing area along the Dallas-Ellis County Line. Undeveloped lands as well as residential communities comprise a majority of the immediate project vicinity. There are a few commercial properties scattered around the proposed project area.

Describe Existing Facility:

No existing facility. Project is on new location.

Describe Proposed Facility:

The new location Loop 9 frontage road system would include an eastbound and westbound frontage road facility, each consisting of three 12-foot lanes, an 8-foot inside shoulder, and an 8-foot outside shoulder for bicycle accommodations within the rural section of the proposed roadway. The proposed project ROW would include a median (358 to 512 feet wide) that would accommodate the future construction of an ultimate access-controlled mainline facility.

The proposed project would construct intersections at eight (8) major cross roads as follows: Tur Road, future Clark Road, S. Joe Wilson Road, S. Duncanville Road, S. Cockrell Hill Road, S. Westmoreland Road, S. Hampton Road, and Uhl Road. The proposed project would also construct a grade separation at the BNSF Railroad. In addition, the western limit of the project would tie into a grade separation at US 67 which would be constructed under a separate project prior to construction of Loop 9 Segment A. The eastern limit of project would tie into a grade separation at IH 35E which would be constructed under a separate project prior to construction of Loop 9, Segment A.

The proposed Loop 9 project, from US 67 to IH 35E, would likely be constructed in two phases based on traffic needs and project funding. A logical sequence for staging the various elements for construction of the new location frontage road system could be as follows:

- Phase 1 would construct a single two-lane, two-way frontage road, and would also acquire

Would the project add capacity?

☐ Transportation Planning

Is the project within an MPO's boundaries?

Does the project meet the definition for a grouped category for planning and programming purposes?

The project is located in area.

This status applies to:

☐ CO - Carbon Monoxide ☐ O3 - Ozone ☐ NO2 - Nitrogen Dioxide

☐ PM10 - Particulate ☐ PM2.5 - Particulate

☐ Environmental Clearance Information

Environmental Clearance Date: Environmental LOA Date:

Closed Date: Archived Date:

Approved Environmental Classification:

☐ Project Contacts

Created By: Date Created:

Project Sponsor: ☒ TXDOT (Or) ☐ Local Government

Sponsor Point Of Contact:

ENV Core Team Member:

District Core Team Member:

Other Point of Contact(s):

Last Updated System Admin By: Last Updated Date: 01/10/2020 07:12:02

Loop 9, Segment A – PROJECT DESCRIPTION
US 67 to IH 35E
Dallas and Ellis Counties, Texas
CSJ: 2964-10-006

The proposed Loop 9, Segment A project includes the construction of a six-lane new location frontage road system between United States 67 (US 67) and Interstate Highway 35 East (IH 35E) through Dallas and Ellis counties, Texas, and is approximately 9.4 miles in length. The proposed Loop 9 roadway system would pass through the Cities of Cedar Hill, Ovilla, Glenn Heights, and Red Oak. The proposed project right-of-way (ROW) would include a median that would accommodate the future construction of an ultimate access-controlled mainlane facility. Construction of the ultimate access-controlled mainlane facility would be based on projected traffic and funding and would require additional environmental analysis prior to construction.

The new location Loop 9 frontage road system would include an eastbound and westbound frontage road facility, each consisting of three 12-foot lanes, an 8-foot inside shoulder, and an 8-foot, outside shoulder for bicycle accommodations within the rural section of the proposed roadway. The proposed project ROW would include a median (358 to 512 feet wide) that would accommodate the future construction of an ultimate access-controlled mainlane facility.

The proposed project would construct intersections at eight (8) major cross roads as follows: Tar Road, future Clark Road, S. Joe Wilson Road, S. Duncanville Road, S. Cockrell Hill Road, S. Westmoreland Road, S. Hampton Road, and Uhl Road. The proposed project would also construct a grade separation at the BNSF Railroad. In addition, the western limit of the project would tie into a grade separation at US 67 which would be constructed under a separate project prior to construction of Loop 9 Segment A. The eastern limit of project would tie into a grade separation at IH 35E which would be constructed under a separate project prior to construction of Loop 9, Segment A.

The proposed Loop 9 project, from US 67 to IH 35E, would likely be constructed in two phases based on traffic needs and project funding. A logical sequence for staging the various elements for construction of the new location frontage road system could be as follows:

- Phase 1 would construct a single two-lane, two-way frontage road, and would also acquire the proposed ROW to accommodate all six-lane frontage road system and the future ultimate access-controlled mainlane facility.
- As traffic warrants and funding becomes available, Phase 2 would involve the construction of the three-lane frontage road in each direction, which would include the conversion of the two-way frontage road built in Phase 1 to a one-way operation, and the construction of grade separations at specific high-volume intersections.

- Phase 3 would involve the construction of the ultimate access-controlled mainline facility in both directions. Construction of the ultimate access-controlled mainline facility would be based on projected traffic and funding and would require additional environmental analysis prior to construction.

Appendix B: Tabular Inventory of Surveyed Properties

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|--|----------------------------------|--------------------------------|---------|--|------------------|
| 01 | 1937 Tar Rd. 32.549482, -96.956574 | DOMESTIC/ Single family dwelling | Ranch | 1978 | Ranch style house with multiple hip roofs, brick siding, a recessed entry, a bay window, and replacement arched windows. Two brick half walls extend from the northeast and southeast corners of the house. | Not Eligible |
| 02a | 1948 Tar Rd. 32.549107, -96.955512 | DOMESTIC/ Single family dwelling | Ranch | 1978 | Ranch style house with cross-gable roof, generous eaves, horizontal wood siding on gable ends, brick siding, and replacement windows. A modern addition of a garage extends from the rear (southwest) corner of the house. | Not Eligible |
| 02b | 1948 Tar Rd. 32.549072, -96.955150 | DOMESTIC/ Shed | No Style | 1979 | Resource 02b is a shed with a gambrel roof, horizontal vinyl siding, and replacement windows. | Not Eligible |
| 03a | 485 Tar Rd. 32.546774, -96.956353 | DOMESTIC/ Single family dwelling | Ranch | 1966 | Ranch style house with shallow-pitch, replacement metal hip roof, polychrome brick siding, a partial-width porch, original diamond plated windows, replacement sash windows, and a straddle ridge chimney. A carport extends from the rear (west) façade. | Not Eligible |
| 03b | 485 Tar Rd. 32.546830, -96.956999 | DOMESTIC/ Barn | No Style | 1979 | Resource 03b is a barn featuring three bays, a front-gable roof, and vertical wood siding. | Not Eligible |
| 04 | 585 Tar Rd. 32.546193, -96.955863 | DOMESTIC/ Single family dwelling | Ranch with Victorian influence | 1964 | Ranch style house with Victorian-style second-story addition. The house features multiple side-gable roofs, generous eaves on the ground floor, a turret, vinyl and polychrome brick siding. The ground floor has an encircling verandah, while the upper story features a partial-width deck. Both feature spindle-like ornamentation. In addition, the house features replacement windows. | Not Eligible |
| 05a | 482 Tar Rd. 32.547213, -96.954627 | DOMESTIC/ Single family dwelling | Ranch | 1968 | Ranch style house with cross-gable roof, horizontal vinyl siding, a stoop, replacement windows, and an exterior chimney. | Not Eligible |
| 05b | 482 Tar Rd. 32.547227, -96.954816 | DOMESTIC/ Garage | No Style | 1968 | Resource 05b is a garage with a front-gable roof, horizontal vinyl siding, and replacement sliding bay doors. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|---|----------------------------------|---------------------|----------|---|------------------|
| 05c | 482 Tar Rd. 32.547389, -96.954843 | DOMESTIC/ Shed | No Style | 1968 | Resource 05c is a shed with a side-gable roof, exposed rafter tails, and horizontal wood siding. | Not Eligible |
| 05d | 482 Tar Rd. 32.547412, -96.954749 | DOMESTIC/ Shed | No Style | 1979 | Resource 05d is a shed with a gambrel roof, vertical wood siding. The shed sits on a system of wood and concrete piers. | Not Eligible |
| 06a | 551 Knight St. 32.547562, -96.951886 | DOMESTIC/ Single family dwelling | Ranch | 1955 | Ranch style house with irregular footprint, cross-gable and hip roofs, dormers, brick and horizontal vinyl siding, a partial-width porch, and replacement windows with louvered shutters, a partial-width porch, and a breezeway. | Not Eligible |
| 06b | 551 Knight St. 32.547873, -96.952364 | DOMESTIC/ Barn | No Style | 1982 | Resource 06b is a metal barn with a shallow-pitch, side-gable, metal roof and metal siding. | Not Eligible |
| 07 | 501 Knight St. 32.547681, -96.948996 | DOMESTIC/ Single family dwelling | Ranch | 1965 | Ranch style house with tiered side-gable roof and a front-gable roof over the carport. The house features horizontal vinyl siding, a partial-width porch, replacement windows, and a front slope chimney. | Not Eligible |
| 08a | 491 Hidden Valley Rd. 32.547946, -96.942182 | DOMESTIC/ Single family dwelling | Ranch | Ca. 1985 | Ranch style house with cross-gable hipped roof. No rights-of-entry, not visible from public ROW. Per historic aerials, the other buildings on property appear to be older barns and sheds that pre-date the house. | Not Eligible |
| 08b | 491 Hidden Valley Rd. 32.548355, -96.942357 | DOMESTIC/ Barn | No Style | Ca. 1965 | Resource 08b is one of two adjacent front-gabled barns. No rights-of-entry, not visible from public ROW. | Not Eligible |
| 08c | 491 Hidden Valley Rd. 32.548432, -96.942338 | DOMESTIC/ Barn | No Style | Ca. 1965 | Resource 08c is one of two adjacent front-gabled barns. No rights-of-entry, not visible from public ROW. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|--|-------------------------------------|---------------------|----------|--|------------------|
| 08d | 491 Hidden Valley Rd. 32.548691, -96.941633 | DOMESTIC/ Barn | No Style | Ca. 1975 | Resource 08d is a large metal roofed gabled barn. No rights-of-entry, not visible from public ROW. | Not Eligible |
| 08e | 491 Hidden Valley Rd. 32.548504, -96.941701 | DOMESTIC/ Barn | No Style | Ca. 1975 | Resource 08e is a mid-sized metal roofed gabled barn. No rights-of-entry, not visible from public ROW. | Not Eligible |
| 08f | 491 Hidden Valley Rd. 32.547897, -96.940981 | DOMESTIC/ Shed | No Style | Ca. 1965 | Resource 08f is a small metal loafing shed. No rights-of-entry, not visible from public ROW. | Not Eligible |
| 08g | 491 Hidden Valley Rd. 32.547883, -96.940810 | DOMESTIC/ Barn | No Style | Ca. 1965 | Resource 08g is a small barn. No rights-of-entry, not visible from public ROW. | Not Eligible |
| 09 | 476 Hidden Valley Rd. 32.546245, -96.939552 | DOMESTIC/ Single family dwelling | Unknown | Ca. 1976 | Unknown residence with solar panels visible on the roof. No rights-of-entry, not visible from public ROW. Date from CAD data. | Undetermined |
| 10a | 1601 S. Joe Wilson Rd. 32.552060, -96.927237 | AGRICULTURE/ Single family dwelling | Ranch | Ca. 1960 | Ranch style house with multiple tiered, shallow-pitch, side-gable roofs, brick siding, and replacement sliding windows. The property also contains an enormous modern horse barn and associated support structures that do not appear on 1982 aerials. | Not Eligible |
| 10b | 1601 S. Joe Wilson Rd. 32.551687, -96.927916 | AGRICULTURE/ Barn | No Style | Ca. 1970 | Resource 10b is a barn. Due to vegetation, project historians were unable to view the barn from the public ROW. Per aerial imagery, the barn appears to have a square footprint and metal, gable roof. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|---|----------------------------------|---------------------|----------|---|------------------|
| 10c | 1601 S. Joe Wilson Rd. 32.552047, -96.927453 | AGRICULTURE/ Shed | No Style | Ca. 1970 | Resource 10c is possibly a shed. Due to an obstructed view, project historians were unable to view Resource 10c. Per aerial imagery, the structure appears to have a rectangular footprint and hip roof. | Not Eligible |
| 11 | 1707 S. Joe Wilson Rd. 32.550446, -96.924758 | DOMESTIC/ Single family dwelling | Ranch | 1968 | Ranch style house with shallow-pitch, cross-gable roof, polychrome brick siding, vinyl siding on gable ends and along the recessed porch. The house features both original and replacement windows. An attached carport extends from the south façade of the house. | Not Eligible |
| 12 | 1730 S. Joe Wilson Rd. 32.551195, -96.924327 | DOMESTIC/ Single family dwelling | Ranch | 1973 | Ranch style house with a gable roof, vertical wood siding, and replacement windows. An open porch extends from the south façade of the house. | Not Eligible |
| 13a | 1702 S. Joe Wilson Rd. 32.552352, -96.923857 | DOMESTIC/ Single family dwelling | Ranch | 1978 | A ranch style house featuring a rectangular plan and a hip roof. Project historians were unable to view Resource 13a from public ROW due to vegetation. | Not Eligible |
| 13b | 1702 S. Joe Wilson Rd. 32.551974, -96.924800 | DOMESTIC/ Barn | No Style | 1978 | A barn with metal flat and shed roofs and metal siding. Project historians were limited due to vegetation and views from ROW, but per aerial imagery, several additional structures are located within the parcel. | Not Eligible |
| 14 | 1621 S. Joe Wilson Rd. 32.554078, -96.921265 | DOMESTIC/ Vacant | Unknown | Ca. 1940 | Abandoned house hidden deep within vegetation. Although historians had right-of-entry to the property, thick vegetation and heavy poison ivy growth prevented access to the house. | Not Eligible |
| 15a | 1511 S. Joe Wilson Rd. 32.556862, -96.925949 | DOMESTIC/ Single family dwelling | Ranch | 1979 | Ranch style house with two-story addition at rear (west) façade of house. The house features hip and side-gable roofs, polychrome brick and horizontal vinyl siding, a partial-width porch, and replacement windows. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|--|----------------------------------|---------------------|---------|---|------------------|
| 15b | 1511 S. Joe Wilson Rd. 32.556684, -96.926108 | DOMESTIC/ Barn | No Style | 1979 | Resource 15b is a metal barn with a shallow-pitch, metal side-gable roof and metal siding. It features large sliding bay doors. | Not Eligible |
| 16a | 1424 Joe Wilson Rd. 32.333137°, -96.553007° | DOMESTIC/ Single family dwelling | Ranch | 1970 | Ranch style house featuring a linear plan, a side-gable roof with a raised center extending over the porch, painted brick siding with horizontal vinyl siding on the gable ends, a partial-width porch accentuated by Doric columns, and replacement wood-sash windows. | Not Eligible |
| 16b | 1424 Joe Wilson Rd. 32.333200°, -96.552893° | DOMESTIC/ Carport | No Style | 1975 | Metal carport featuring a metal roof and metal supports. | Not Eligible |
| 16c | 1424 Joe Wilson Rd. 32.333199°, -96.552858° | DOMESTIC/ Garage | No Style | 1975 | Garage featuring a cross-gambrel roof, horizontal vinyl siding, and the original garage door. | Not Eligible |
| 17a | 1415 S. Joe Wilson Rd. 32.559512, -96.925935 | DOMESTIC/ Single family dwelling | Ranch | 1973 | Ranch style house with side-gable roof, brick siding, partial-width porch, replacement windows and panel and louvered shutters. | Not Eligible |
| 17b | 1415 S. Joe Wilson Rd. 32.556860, -96.928104 | DOMESTIC/ Barn | No Style | 1980 | Resource 17b is a barn with a shallow-pitch, metal gable roof with cantilevered overhangs and metal siding. | Not Eligible |
| 17c | 1415 S. Joe Wilson Rd. 32.557127, -96.928423 | DOMESTIC/ Barn | No Style | 1980 | Resource 17c is a barn with a shallow-pitch, metal gable roof and metal siding. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|--|----------------------------------|---------------------|----------|---|------------------|
| 17d | 1415 S. Joe Wilson Rd. 32.557853, -96.927795 | DOMESTIC/ Barn | No Style | 1980 | Resource 17d is a barn with a shallow-pitch, metal gable roof and metal siding. | Not Eligible |
| 17e | 1415 S. Joe Wilson Rd. 32.557033, -96.929226 | DOMESTIC/ Barn | No Style | Ca. 1970 | Resource 17e is a barn. Due to vegetation, project historians were unable to view the barn from the public ROW. Per aerial imagery, the barn features a square footprint and metal, gable roof. This resource appears on a 1970 aerial. | Not Eligible |
| 17f | 1415 S. Joe Wilson Rd. 32.556697, -96.928284 | DOMESTIC/ Barn | No Style | Ca. 1970 | Resource 17f is possibly a barn. Project historians were unable to view Resource 17f from public ROW due to vegetation. Resource 17f features a square footprint and a metal roof. This resource appears on a 1970 aerial. | Not Eligible |
| 17g | 1415 S. Joe Wilson Rd. 32.558041, -96.928376 | DOMESTIC/ Shed | No Style | 1980 | Resource 17g is a small metal shed with a shallow pitch, metal gable roof and metal siding. | Not Eligible |
| 18 | 1410 S. Joe Wilson Rd. 32.559757, -96.924989 | DOMESTIC/ Single family dwelling | Ranch | Ca. 1970 | Ranch style house featuring a linear plan with a hipped roof extending over the porch, painted brick siding, an attached garage on the west façade, a partial-width porch accentuated by two wood columns, and replacement sash and picture windows with louvered shutters. | Not Eligible |
| 19a | 1401 S. Joe Wilson Rd. 32.560082, -96.927298 | DOMESTIC/ Single family dwelling | Unknown (Ranch) | Ca. 1970 | Possible Ranch style house. According to Dallas CAD data, the house features a gable roof and brick siding. | Undetermined |
| 19b | 1401 S. Joe Wilson Rd. 32.559920, -96.927970 | DOMESTIC/ Shed | No Style | Ca. 1970 | Per aerial imagery, Resource No. 19b appears to be a shed with a metal roof. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|--|----------------------------------|--|----------|---|------------------|
| 20a | 1321 S. Joe Wilson Rd. 32.562511, -96.925722 | DOMESTIC/ Single family dwelling | Minimal Traditional with Craftsman influence | Ca. 1945 | Minimal Traditional style house with Craftsman influences features a side-gable roof with exposed rafter tails and generous eaves, horizontal wood siding, a covered stoop with a flat roof and decorative iron posts, replacement windows, and a rear addition with a side-gable roof. | Not Eligible |
| 20b | 1321 S. Joe Wilson Rd. 32.562434, -96.925918 | DOMESTIC/ Garage | No Style | Ca. 1950 | Garage featuring a front-gable roof with exposed rafter tails, asbestos shingle siding, original windows, two replacement garage doors, and a rear, wood-frame addition with a shed roof and metal siding. | Not Eligible |
| 20c | 1321 S. Joe Wilson Rd. 32.562916, -96.926164 | DOMESTIC/ Barn | No Style | Ca. 1950 | Barn featuring a rectangular plan, a front-gable roof, a hay loft, metal siding, and an open, central bay. | Not Eligible |
| 20d | 1321 S. Joe Wilson Rd. 32.562300, -96.926054 | DOMESTIC/ Pole barn | No Style | Ca. 1950 | Small pole barn featuring a saltbox roof, metal siding, and open bays on the south façade. | Not Eligible |
| 21a | 1329 S. Joe Wilson Rd. 32.561446, -96.925996 | DOMESTIC/ Single family dwelling | Ranch | Ca. 1975 | Ranch style house featuring a linear plan, a tiered side-gable roof with exposed rafter tails, brick siding with vertical wood siding on the gable ends, a partial-width porch with wood columns, original windows with louvered shutters, and a rear addition. | Not Eligible |
| 21b | 1329 S. Joe Wilson Rd. 32.561628, -96.926154 | DOMESTIC/ Well house | No Style | Ca. 1975 | Well house of brick construction featuring a gable roof with exposed rafter tails and generous eaves. | Not Eligible |
| 21c | 1329 S. Joe Wilson Rd. 32.561622, -96.925517 | DOMESTIC/ Gate | No Style | Ca. 1975 | Two brick piers flanking the driveway. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|--|----------------------------------|---------------------|----------|---|------------------|
| 22a | 1135 Bear Creek Rd. 32.561186, -96.924438 | DOMESTIC/ Single family dwelling | Ranch | Ca. 1970 | Ranch style house featuring a linear plan, hipped roof, painted brick siding, a partial-width porch, original diamond-paned windows with louvered shutters, an attached garage on the east façade, and a brick chimney located on the rear slope of the roof. | Not Eligible |
| 22b | 1135 Bear Creek Rd. 32.561186, -96.924438 | DOMESTIC/ Garage | No Style | Ca. 1970 | Metal garage featuring a metal gambrel roof and metal siding. | Not Eligible |
| 23 | 1136 Bear Creek Rd. 32.560458, -96.924252 | DOMESTIC/ Single family dwelling | Ranch | Ca. 1960 | Ranch style house with an irregular plan, a hipped roof, brick siding, original metal sash windows, and a recessed stoop. | Not Eligible |
| 24a | 1155 Bear Creek Rd. 32.561424, -96.923935 | DOMESTIC/ Single family dwelling | I-house | Ca. 1901 | I-house featuring a steep-pitch, side-gable roof, replacement horizontal wood siding, partial-width stacked porches with square columns and railings, replacement wood-sash windows, and a rear addition. | Not Eligible |
| 24b | 1155 Bear Creek Rd. 32.561432, -96.923727 | DOMESTIC/ Garage | No Style | Ca. 1960 | Pole barn featuring a shallow-pitch, side-gable, metal roof, metal siding, original metal frame windows, and two open bays serving as garage space. | Not Eligible |
| 25 | 1159 Bear Creek Rd. 32.561288, -96.921681 | DOMESTIC/ Single family dwelling | Ranch | Ca, 1970 | Ranch style house featuring an L-shape plan, a symmetrical façade with a recessed porch and two protruding bays, a shallow-pitch, hipped roof, brick siding, original windows, and a rear slope, brick chimney. | Not Eligible |
| 26 | 1123 S. Joe Wilson Rd. 32.562344, -96.921125 | AGRICULTURE/ Barn | No Style | Ca. 1960 | Isolated front-gabled metal barn with no other buildings on the parcel. Does not appear to be associated with any historic-age residence or other outbuildings. Not visible from public-right-of-way, and historians had no right-of-entry. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|---|----------------------------------|---------------------|----------|---|------------------|
| 27 | 1223 Bear Creek Rd. 32.561280, -96.920842 | DOMESTIC/ Single family dwelling | Ranch | Ca. 1965 | Ranch style house with shallow-pitch, side-gable roof, painted brick siding, a small portico accentuated by a decorative iron post, original sash windows, an attached garage on the south façade, and a rear slope chimney. | Not Eligible |
| 28 | 1326 Bear Creek Rd. 32.560317, -96.920762 | DOMESTIC/ Single family dwelling | Ranch | 1965 | Ranch style house with shallow-pitch, cross-hip roof, brick siding, a front stoop, both original and replacement windows, louvered shutters, an exterior chimney, and an attached garage to the west with a replacement garage door. | Not Eligible |
| 29 | 1327 Bear Creek Rd. 32.560317, -96.920762 | DOMESTIC/ Single family dwelling | Ranch | 1965 | Ranch style house with an L-shaped plan featuring a shallow-pitch, side-gable roof, brick siding, a recessed, partial-width porch, and replacement windows with louvered shutters. | Not Eligible |
| 30a | 1328 Bear Creek Rd. 32.560296, -96.919078 | DOMESTIC/ Single family dwelling | Ranch | 1978 | Ranch style house with shallow-pitch, hip roof, brick siding, and replacement windows. Rounded arches mark the main entry point. An attached garage is located to the west. | Not Eligible |
| 30b | 1328 Bear Creek Rd. 32.559752, -96.918857 | DOMESTIC/ Shed | No Style | 1981 | Resource 30b is a shed with a front-gable roof and vertical wood siding. | Not Eligible |
| 31a | 1349 Bear Creek Rd. 32.561251, -96.918263 | DOMESTIC/ Single family dwelling | Folk Victorian | 1905 | Folk Victorian style house featuring a cross-gable roof, original horizontal wood siding, a covered verandah with a shallow-pitch, hipped roof square columns, replacement windows, and a rear addition, which includes an attached garage, and a front slope, stone chimney. | Not Eligible |
| 31b | 1349 Bear Creek Rd. 32.561399, -96.918422 | DOMESTIC/ Garage | No Style | 1930 | Wood-frame garage featuring two open bays, a front-gable metal roof and a shallow-pitch, metal shed roof, and vertical and wood siding. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|--|------------------------------------|---------------------|----------|---|------------------|
| 31c | 1349 Bear Creek Rd. 32.561257, -96.918546 | AGRICULTURE/ Pole barn | No Style | 1940 | Metal pole barn featuring a rectangular plan, a shallow-pitch, side-gable metal roof with wide overhanging eaves, and metal siding. | Not Eligible |
| 31d | 1349 Bear Creek Rd. 32.561481, -96.918236 | AGRICULTURE / Loafing shed | No Style | 1940 | Loafing shed featuring a metal, saltbox roof and metal siding. | Not Eligible |
| 31e | 1349 Bear Creek Rd. 32.561819, -96.918646 | AGRICULTURE / Loafing shed | No Style | 1940 | Wood-frame loafing shed featuring a large open bay, a side-gable, metal roof, and metal siding. | Not Eligible |
| 31f | 1349 Bear Creek Rd. 32.562039, -96.918709 | AGRICULTURE / Pole barn | No Style | 1950 | Wood-frame pole barn featuring a shallow-pitch, front-gable, metal roof, metal siding, and three large bays. | Not Eligible |
| 31g | 1349 Bear Creek Rd. 32.561254, -96.918883 | AGRICULTURE/ Barn | No Style | Ca. 1930 | Large vacant wood barn with vertical board siding, open/missing door, and front-gabled roof with metal roofing. Barn is completely obscured due to vegetation except during winter months; identified post-survey via historic aerials. | Not Eligible |
| 32a | 1360 Bear Creek Rd. 32.560298, -96.917705 | DOMESTIC/ Single family welling | Ranch | 1978 | Ranch style house with side-gable roof, brick siding, vinyl siding on gable ends, replacement windows accentuated by paneled shutters, and a partial-width porch. | Not Eligible |
| 32b | 1360 Bear Creek Rd. 32.559833 °, -96. 917797 ° | DOMESTIC/ Barn | No Style | 1978 | Resource 32b is possibly a barn. Project historians were unable to view Resource 32b due to vegetation and structures obstructing the view from public ROW. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|--|----------------------------------|---------------------|---------|---|------------------|
| 33 | 1470 Bear Creek Rd. 32.560222°, -96.914243° | DOMESTIC/ Single family dwelling | Unknown | 1978 | Project historians were unable to photograph resources from the public ROW due to vegetation. According to Dallas CAD, the property includes a one-and-a-half story wood-frame house with brick siding, a gable roof, and an attached garage and carport. A storage building and outbuilding may also be present on the parcel according to CAD data. | Undetermined |
| 34 | 1474 Bear Creek Rd. 32.560427, -96.912539 | DOMESTIC/ Single family dwelling | Ranch | 1982 | Ranch style house with hip roof, polychrome brick siding, a recessed porch, replacement windows, a rear slope chimney, and two decorative brick half-walls extending from the northwest and northeast corners of the house. | Not Eligible |
| 35 | 1576 Bear Creek Rd. 32.560471, -96.911466 | DOMESTIC/ Single family dwelling | Ranch | 1982 | Ranch style house with hip roof, polychrome brick siding, a recessed entry, original windows with panel shutters, and replacement garage doors. | Not Eligible |
| 36a | 1902 Bear Creek Rd. 32.560195, -96.896535 | DOMESTIC/ Single family dwelling | Ranch | 1972 | Ranch style house with hip roof, brick siding, front stoop, and replacement windows. | Not Eligible |
| 36b | 1902 Bear Creek Rd. 32.559871, -96.896324 | DOMESTIC/ Barn | No Style | 1972 | Resource 36b is a metal barn with a metal, front-gable roof and metal siding. | Not Eligible |
| 36c | 1902 Bear Creek Rd. 32.560001, -96.896321 | DOMESTIC/ Tank | No Style | 1972 | Resource 36c is a possible a water tank, however, due to views from the public ROW and vegetation, it is difficult to confirm the purpose of the structure. It is a barreled structure with metal siding. | Not Eligible |
| 36d | 1902 Bear Creek Rd. 32.560008, -96.896368 | DOMESTIC/ Shed | No Style | 1972 | Resource 36d is a shed with a wood-shingle gable roof, exposed rafter tails, horizontal wood siding, and replacement windows. The roof appears to be in poor condition. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|---|----------------------------------|---------------------|---------|--|------------------|
| 36e | 1902 Bear Creek Rd. 32.560689, -96.896368 | DOMESTIC/ Shed | No Style | 1979 | Resource 36e is a shed with a side-gable, metal roof and horizontal wood siding. Original windows have been boarded up. | Not Eligible |
| 37 | 1914 Bear Creek Rd. 32.560606, -96.895594 | DOMESTIC/ Single family dwelling | Ranch | 1950 | A highly renovated Ranch style house with a hip roof, horizontal vinyl siding, a partial-width porch with decorative railings, and replacement sash and picture windows. | Not Eligible |
| 38a | 2002 Bear Creek Rd. 32.560583, -96.895312 | DOMESTIC/ Single family dwelling | Ranch | 1972 | A highly renovated Ranch style house with a shallow-pitch, hip roof with generous eaves, removed siding, a partial-width porch, replacement windows, and an exterior chimney. | Not Eligible |
| 38b | 2002 Bear Creek Rd. 32.559996, -96.895464 | DOMESTIC/ Shed | No Style | 1968 | Resource 38b is a shed with a front-gable roof, horizontal wood siding on the gable front, brick siding, and original windows. | Not Eligible |
| 39a | 2102 Bear Creek Rd. 32.560530, -96.893816 | DOMESTIC/ Single family dwelling | Ranch | 1970 | A highly renovated Ranch style house (subtype: courtyard) with shallow-pitch, cross-gable roofs, brick and stone siding, replacement windows, a decorative brick half wall extending from the northeast corner of the house, and an exterior chimney. An addition of an integrated garage extends from the west façade of the original footprint of the house. | Not Eligible |
| 39b | 2102 Bear Creek Rd. 32.560401, -96.894093 | DOMESTIC/ Secondary housing | No Style | 1979 | Resource 39b is a highly renovated guesthouse with a hip roof, replacement vinyl siding, and replacement windows. A deck extends from the rear (southwest) corner of the guesthouse. | Not Eligible |
| 39c | 2102 Bear Creek Rd. 32.560118, -96.893774 | DOMESTIC/ Shed | No Style | 1979 | Resource 39c is possibly a shed with a rectangular footprint and gable roof. Modern additions extend from the east and south facades of the structure. Project historians were unable to view Resource 39c from public ROW due to vegetation. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|--|----------------------------------|---------------------|---------|---|------------------|
| 40 | 2222 Bear Creek Rd. 32.560504, -96.891805 | COMMERCE/ Restaurant | Ranch | 1976 | A former Ranch style house with a complex roof system consisting of steep side-gable roofs, two metal shed roofs, and a shallow-pitch, side-gable roof. The building features wood panel siding, an open porch with a metal shed roof, and replacement windows. Currently occupied by Juicy Bones Restaurant at BoxCar. | Not Eligible |
| 41a | 1435 Cockrell Hill Rd. 32.559767, -96.891641 | DOMESTIC/ Single family dwelling | Ranch | 1975 | Ranch style house with mansard roof, stucco siding, replacement windows, and an arched projection emphasizing the recessed main entry. | Not Eligible |
| 41b | 1435 Cockrell Hill Rd. 32.559753, -96.891998 | DOMESTIC/ Secondary housing | Ranch | 1979 | Resource 41b is a Ranch style guesthouse with a mansard roof, stucco siding, and original windows. A modern roofed structure extends from the guesthouse's south façade. | Not Eligible |
| 42a | 923 Cockrell Hill Rd. 32.558887, -96.891631 | DOMESTIC/ Single family dwelling | Ranch | 1979 | Ranch style house with shallow-pitch, hip roof, brick siding, original sash windows and decorative panel shutters, a partial-width porch emphasized with classical columns, and a straddle ridge chimney. | Not Eligible |
| 42b | 923 Cockrell Hill Rd. 32.558655, -96.891614 | DOMESTIC/ Shed | No Style | 1979 | Resource 42b is a metal shed with a metal shed roof and metal siding over a wood frame. | Not Eligible |
| 43a | 916 Cockrell Hill Rd. 32.558497, -96.890580 | DOMESTIC/ Single family dwelling | Contemporary Ranch | 1953 | Contemporary Ranch style house with metal shed roof, hip roof, stucco siding, replacement fixed windows, and an exterior brick chimney. | Not Eligible |
| 43b | 916 Cockrell Hill Rd. 32.558292, -96.890612 | DOMESTIC/ Secondary housing | No Style | 1953 | Resource 43b is a former carport renovated into a guesthouse with a flat roof, wood panel siding, and square brick columns. The west-most portion of the guesthouse remains open. A metal addition (an attached garage) with a shed roof extends from the rear (east) façade of the guesthouse. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|--|----------------------------------|---------------------|---------|--|------------------|
| 43c | 916 Cockrell Hill Rd. 32.558280, -96.890252 | DOMESTIC/ Shed | No Style | 1970 | Resource 43c is a shed with a shed roof and vertical wood siding. | Not Eligible |
| 43d | 916 Cockrell Hill Rd. 32.558302, -96.890445 | DOMESTIC/ Shed | No Style | 1970 | Resource 43d is a shed with an irregular footprint topped by a metal front-gable roof and a metal shed roof, and metal siding. | Not Eligible |
| 44a | 912 Cockrell Hill Rd. 32.557840, -96.890289 | DOMESTIC/ Single family dwelling | Ranch | 1972 | Ranch style house with hip roof, polychrome brick siding, replacement sash windows, panel shutters, a partial-width porch with decorative wrought iron supports, and a rear slope chimney. | Not Eligible |
| 44b | 912 Cockrell Hill Rd. 32.558063, -96.890029 | DOMESTIC/ Shed | No Style | 1972 | Resource 44b is a metal shed with a metal gable roof and metal siding. | Not Eligible |
| 44c | 912 Cockrell Hill Rd. 32.558060°, -96.889828° | DOMESTIC/ Shed | No Style | 1972 | Resource 44c is a metal shed with a metal gable roof and metal siding. | Not Eligible |
| 45a | 1230 W. Bear Creek Rd. 32.560546, -96.886844 | AGRICULTURE/ Barn | No Style | 1967 | Resource 45a is a metal barn with a shallow-pitch, metal gable roof and metal siding. | Not Eligible |
| 45b | 1230 W. Bear Creek Rd. 32.560505, -96.886673 | AGRICULTURE/ Shed | No Style | 1967 | Resource 45b is a wood-frame shed with a metal gable roof. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|--|----------------------------------|---------------------|---------|---|------------------|
| 45c | 1230 W. Bear Creek Rd. 32.559426, -96.885458 | AGRICULTURE/ Barn | No Style | 1979 | Resource 45c is a wood-frame barn with a shallow-pitch, metal front-gable roof, metal siding, and large sliding metal doors. | Not Eligible |
| 45d | 1230 W. Bear Creek Rd. 32.559319, -96.885273 | AGRICULTURE/ Grain bin | No Style | 1979 | Resource 45d is a grain bin with a conical metal roof and metal panel siding. | Not Eligible |
| 46a | 1230 W. Bear Creek Rd. 32.560309, -96.885832 | DOMESTIC/ Single family dwelling | Ranch | 1967 | Ranch style house with shallow-pitch, side-gable roofs with generous eaves, polychrome brick siding, cedar shake siding on gable ends, replacement windows, a partial-width porch supported by classical columns, and a rear slope chimney. An enclosed, integrated garage is located on the east façade. | Not Eligible |
| 46b | 1230 W. Bear Creek Rd. 32.560318, -96.885483 | DOMESTIC/ Shed | No Style | 1967 | Resource 46b is a shed with a front-gable roof, exposed rafter tails, generous eaves, brackets, and vertical wood panel siding. | Not Eligible |
| 47a | 1002 W. Bear Creek Rd. 32.556377, -96.881444 | DOMESTIC/ Single family dwelling | Ranch | 1977 | Ranch style house with a shallow-pitch, cross-gable metal roof, rusticated stone and vertical wood siding, a recessed entry, and an exterior stone chimney. An integrated carport extends from the west façade of the house. The carport features a shallow-pitch, side gable roof, and vertical wood siding. | Not Eligible |
| 47b | 1002 W. Bear Creek Rd. 32.555779, -96.882432 | DOMESTIC/ Barn | No Style | 1977 | Resource 47b is possibly a barn. Project historians were unable to view Resource 47b from public ROW due to vegetation. Per aerial imagery, Resource 47b features a rectangular footprint and a metal, gable roof. | Not Eligible |
| 47c | 1002 W. Bear Creek Rd. 32.556127, -96.882465 | DOMESTIC/ Barn | No Style | 1977 | Resource 47c is possibly a barn. Project historians were unable to view Resource 47c from public ROW due to vegetation. Per aerial imagery, Resource 47c features a rectangular footprint and a metal, gable roof. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|--|----------------------------------|--------------------------|----------|--|------------------|
| 47d | 1002 W. Bear Creek Rd. 32.556602, -96.882356 | DOMESTIC/ Barn | No Style | 1977 | Resource 47d is a possibly a barn. Project historians were unable to view Resource 47d from public ROW due to vegetation. Per aerial imagery, the structure features a rectangular footprint and a metal roof. | Not Eligible |
| 47e | 1002 W. Bear Creek Rd. 32.556625, -96.882143 | DOMESTIC/ Shed | No Style | 1977 | Resource 47e is possibly a shed. Project historians were unable to view Resource 47e from public ROW. Per aerial imagery, the shed appears to have a metal, gable roof. | Not Eligible |
| 48 | 838 Cockrell Hill Rd. 32.553202, -96.889864 | DOMESTIC/ Single family dwelling | Ranch | 1942 | Ranch style house with cross-gable roof, stone façade, and replacement windows. There appear to be decorative brick or stone quoins at the corners of the house. | Not Eligible |
| 49a | 2100 S. Westmoreland Rd. 32.552293, -96.874392 | DOMESTIC/ Single family dwelling | Unknown (Ranch) | Ca. 1960 | Ranch style house with vinyl or hardplank siding, replacement vinyl windows, and two small inset porches (one with a single wood support) under a cross-gabled roof with modest eaves and low pitch. The seemingly detached garage with modern carport has been attached to the house via a rear porch addition. | Not Eligible |
| 49b | 2100 S. Westmoreland Rd. 32.552616, -96.874639 | DOMESTIC/ Barn | No Style | Ca. 1960 | Metal side-gabled barn with corrugated metal siding and roofing, roll metal door, and metal-covered windows. | Not Eligible |
| 50a | 2011 S. Westmoreland Rd. 32.551517, -96.874644 | DOMESTIC/ Single family dwelling | Craftsman style bungalow | Ca. 1920 | Craftsman style bungalow with a metal hip roof, exposed rafter tails, replacement siding, a full-width porch featuring rustic wood supports, and replacement windows. | Not Eligible |
| 50b | 2011 S. Westmoreland Rd. 32.550857, -96.875232 | DOMESTIC/ Barn | No Style | Ca. 1920 | Resource 50b is a barn with a metal front-gable roof and a metal shed roof, vertical wood siding, and a hay loft. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|--|----------------------------------|---------------------|---------|--|------------------|
| 50c | 2011 S. Westmoreland Rd. 32.551131, -96.875166 | DOMESTIC/ Shed | No Style | 1950 | Resource 50c is a shed with a metal front-gable roof, wood siding on the gable ends, and metal siding. | Not Eligible |
| 50d | 2011 S. Westmoreland Rd. 32.551790, -96.874651 | DOMESTIC/ Stable | No Style | 1950 | Resource 50d is a stable with a shallow-pitch, front-gable metal roof, exposed rafter tails, and vertical wood siding. | Not Eligible |
| 51 | 2020 Westmoreland Rd. 32.549761, -96.873675 | DOMESTIC/ Vacant | Ranch | 1955 | A vacant Ranch style house with a shallow-pitch, hip roof with generous eaves, brick siding, a variety of original windows, a covered front porch featuring decorative wrought iron supports, and an integrated, enclosed garage extending from the north façade of the house. | Not Eligible |
| 52 | 807 Westmoreland Rd. 32.548842, -96.874409 | DOMESTIC/ Single family dwelling | Ranch | 1974 | Ranch style house with a cross gable roof and a shallow-pitch hip roof, brick siding with decorative brick projections bordering windows, a low, brick screen wall along the front (east) façade, a recessed entry with stoop, replacement windows, and a rear slope, brick chimney. | Not Eligible |
| 53a | 108 Lariat Tr. 32.547700, -96.876467 | DOMESTIC/ Single family dwelling | Ranch | 1972 | Ranch style house with a shallow-pitch, gable-hip roof, brick siding, replacement windows, a covered stoop, and an exterior brick chimney. An enclosed, integrated garage extends from the west façade of the house. | Not Eligible |
| 53b | 108 Lariat Tr. 32.548000, -96.876649 | DOMESTIC/ Barn | No Style | 1972 | Metal barn with a shallow gabled roof and sliding metal doors. Viewing angles limited due to location. | Not Eligible |
| 53c | 108 Lariat Tr. 32.548122, -96.876451 | DOMESTIC/ Shed | No Style | 1985 | Metal side-gabled shed with a shallow roof pitch behind the main house. Visibility limited due to fencing and vegetation. | Not Eligible |
| 54 | 106 Lariat Tr. 32.547695, -96.875975 | DOMESTIC/ Single family dwelling | Ranch | 1972 | Ranch style house with shallow-pitch, hip roof, brick siding, a partial-width porch accentuated with classical columns, a recessed entry, replacement windows, a rear slope brick chimney, and an enclosed, integrated garage extending from the east façade of the house. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|--|----------------------------------|---------------------|----------|---|------------------|
| 55a | 104 Lariat Tr. 32.547706, -96.875455 | DOMESTIC/ Single family dwelling | Ranch | 1972 | Ranch style house (subtype: linear with clusters) with a shallow-pitch, side-gable roof, brick siding, a recessed entry, a front slope brick chimney, and replacement windows. An enclosed integrated garage extends from the west façade of the house. | Not Eligible |
| 55b | 104 Lariat Tr. 32.547796, -96.875616 | DOMESTIC/ Garage | No Style | Ca. 1980 | Resource 55b is a detached garage post-dating the main house. The building has a hipped roof and single garage door. | Not Eligible |
| 55c | 104 Lariat Tr. 32.548009, -96.875473 | DOMESTIC/ Barn | No Style | 1972 | Resource 55c is a barn. Project historians were unable to view the barn from public ROW due to vegetation and structures obstructing views. Per aerial imagery, the barn appears to have a rectangular footprint, a side-gable, metal roof, and an addition with a metal roof extending from the east façade. | Not Eligible |
| 55d | 104 Lariat Tr. 32.548098, -96.875707 | DOMESTIC/ Pole barn | No Style | Ca. 1985 | Resource 55d is a recent gambrel roof barn or shed with vinyl sash windows. Visibility was limited due to vegetation, fencing, and other buildings. | Not Eligible |
| 56 | 803 Westmoreland Rd. 32.547842, -96.874606 | DOMESTIC/ Single family dwelling | Ranch | 1972 | A 1.5-story Ranch style house with a steep-pitch clipped cross-gable roof, a dormer with a shed roof and horizontal vinyl siding polychrome brick siding and horizontal vinyl siding on gable ends, original metal-frame sash windows and diamond-plated casement windows. An integrated, enclosed garage extends from the south façade of the house. The garage features a replacement door. | Not Eligible |
| 57 | 443 Sleepy Top Rd. 32.548926, -96.865141 | DOMESTIC/ Single family dwelling | Ranch | 1973 | Ranch style house with shallow-pitch hip roof, brick siding, a variety of original windows, a partial-width front porch, a recessed entry, an exterior brick chimney, and an integrated, enclosed garage at the south end of the house. | Not Eligible |
| 58 | 432 Pearly Top Dr. 32.548476, -96.865221 | DOMESTIC/ Single family dwelling | Ranch | 1976 | Ranch style house with shallow-pitch, side-gable roof with generous eaves, brick siding, horizontal vinyl siding on gable ends, a partial-width porch with a recessed entry, replacement windows, louvered shutters, and an integrated, enclosed garage on the east end of the house. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|--|----------------------------------|---------------------|---------|---|------------------|
| 59 | 426 Pearly Top Dr. 32.548481, -96.864749 | DOMESTIC/ Single family dwelling | Ranch | 1976 | Ranch style house with steep-pitch, side-gable roof, brick siding, partial-width porch, horizontal wood siding on gable ends, and replacement windows with louvered shutters. | Not Eligible |
| 60 | 419 Pearly Top Dr. 32.548921, -96.864558 | DOMESTIC/ Single family dwelling | Ranch | 1973 | Ranch style house with shallow-pitch, hip roof, brick siding, a series of rounded arches mimicking an arcade along the partial-width porch, replacement rounded arch windows, replacement shutters, and a front slope brick chimney. An integrated, enclosed garage is located at the west end of the house. | Not Eligible |
| 61 | 420 Pearly Top Dr. 32.548485, -96.864384 | DOMESTIC/ Single family dwelling | Ranch | 1974 | Ranch style house with shallow-pitch, cross-gable and hip roof, brick siding, horizontal wood siding on the gable end over the partial-width porch, replacement windows with panel shutters, and an integrated, enclosed garage on the west end of the house. | Not Eligible |
| 62a | 414 Pearly Top Dr. 32.548492, -96.863956 | DOMESTIC/ Single family dwelling | Ranch | 1974 | Ranch style house with cross-clip gable roof, brick siding with decorative herringbone pattern and decorative half-timbering with stucco siding. In addition, the house features original double hung windows, a straddle ridge chimney, and a brick half wall extending from the northwest corner of the house. An integrated, enclosed garage is located at the west end of the house. | Not Eligible |
| 62b | 414 Pearly Top Dr. 32.548211, -96.864158 | DOMESTIC/ Shed | No Style | 1980 | Resource 62b is a shed with a gambrel roof and wood panel siding. | Not Eligible |
| 63 | 408 Pearly Top Dr. 32.548475, -96.863542 | DOMESTIC/ Single family dwelling | Ranch | 1974 | Ranch style house with shallow-pitch, cross-gable roof, brick siding, horizontal vinyl siding on gable ends, a series of rounded arches along the partial-width porch, replacement rounded arch windows, a front slope chimney, and brick half-walls extending from the northwest and northeast corners of the house. An integrated, enclosed garage with a replacement door is located at the west end of the house. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|---|----------------------------------|---------------------|---------|--|------------------|
| 64 | 402 Pearly Top Dr. 32.548460, -96.863172 | DOMESTIC/ Single family dwelling | Ranch | 1973 | Ranch style house with shallow-pitch, hip roof, brick siding, a partial-width porch, a variety of replacement windows, including bay windows, brick half-walls extending from the northwest and northeast corners of the house. An integrated, enclosed garage is located at the rear (south) of the house. | Not Eligible |
| 65 | 320 Pearly Top Dr. 32.548483, -96.862751 | DOMESTIC/ Single family dwelling | Ranch | 1973 | Ranch style house with shallow-pitch, hip roof with generous eaves, brick and horizontal vinyl siding, a covered front stoop with decorative wrought-iron supports, original rounded arch windows, and brick half-walls extending from the west and east corners of the house. | Not Eligible |
| 66 | 314 Pearly Top Dr. 32.548476, -96.862311 | DOMESTIC/ Single family dwelling | Ranch | 1974 | Ranch style house with shallow-pitch, hip roof, brick siding, a recessed entry, replacement windows, a rear slope chimney, and brick half-walls extending from the northwest and northeast corners of the house. An integrated, enclosed garage with a replacement door is located on the west end of the house. | Not Eligible |
| 67a | 2123 S. Hampton Rd. 32.547222, -96.857089 | DOMESTIC/ Single family dwelling | Ranch | 1967 | Ranch style house with shallow-pitch, hip roof, brick and horizontal vinyl siding, a partial-width porch with a flat roof and decorative, wrought iron supports, original and replacement windows, and an integrated, enclosed garage located on the north end of the house. | Not Eligible |
| 67b | 2123 S. Hampton Rd. 32.547381, -96.858016 | DOMESTIC/ Barn | No Style | 1967 | Resource 67b is a metal barn with a shallow-pitch, side-gable roof, metal siding, and three open bays. | Not Eligible |
| 67c | 2123 S. Hampton Rd. 32.547319, -96.858211 | DOMESTIC/ Loafing shed | No Style | 1967 | Resource 67c is a wood-frame barn with a shed roof and an additional cantilevered metal shed roof extending from the front (south) façade, metal siding, and three open bays. | Not Eligible |
| 67d | 2123 S. Hampton Rd. 32.547192, -96.858272 | DOMESTIC/ Shed | No Style | 1967 | Resource 67d is a wood-frame shed with a metal shed roof, metal siding, and two open bays. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|---|----------------------------------|----------------------|---------|--|------------------|
| 68a | 2127 S. Hampton Rd. 32.546404, -96.857195 | DOMESTIC/ Single family dwelling | Ranch | 1971 | Ranch style house with shallow-pitch, cross-gable and hip metal roof with generous eaves, brick siding, a variety of replacement windows, a rear slope brick chimney, and brick half-walls extending from the southeast and northeast corners of the house. | Not Eligible |
| 68b | 2127 S. Hampton Rd. 32.546412, -96.857897 | DOMESTIC/ Barn | No Style | 1950 | Resource 68b is barn with a shallow-pitch, metal monitor roof, metal siding, and three open bays. | Not Eligible |
| 69 | 2307 S. Hampton Rd. 32.542903, -96.857221 | DOMESTIC/ Single family dwelling | Ranch | 1982 | Ranch style house with shallow-pitch, cross-gable roof, brick siding, stucco and vertical vinyl siding on gable ends, a covered front stoop with a shed roof, replacement windows, and an attached wood-frame carport extending from the rear (west) façade. | Not Eligible |
| 70a | 500 W. Overhill Dr. 32.544444, -96.849491 | DOMESTIC/ Unknown | No Style | 1970 | Resource 70a is a metal building with a shallow-pitch, side-gable metal roof, metal siding, and replacement windows. | Not Eligible |
| 70b | 500 W. Overhill Dr. 32.544421, -96.849402 | DOMESTIC/ Shed | No Style | 1970 | Resource 70b is a metal shed with an irregular footprint. It includes both a gable and shed roof and metal siding. | Not Eligible |
| 71 | 308 Watercrest Ln. 32.544533, -96.846960 | DOMESTIC/ Single family dwelling | No discernible style | 1978 | Resource 71 is a single-family dwelling with no discernible style. It features a side-gable roof, horizontal vinyl siding, a partial-width porch with a metal shed roof and wood supports, and replacement windows. | Not Eligible |
| 72 | 402 Watercrest Ln. 32.544948, -96.846789 | DOMESTIC/ Vacant | Ranch | 1952 | Vacant Ranch style house with shallow-pitch hip roof, horizontal vinyl siding, a recessed porch, and replacement double-hung windows. The south end of the house is in ruin. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|---|----------------------------------|---------------------|---------|--|------------------|
| 73a | 307 Lake Shore Ln. 32.544420, -96.846280 | DOMESTIC/ Single family dwelling | Ranch | 1970 | Ranch style house with shallow-pitch, cross-gable roof, vertical and horizontal vinyl siding, a recessed porch, and replacement double-hung windows. | Not Eligible |
| 73b | 307 Lake Shore Ln. 32.544242, -96.846355 | DOMESTIC/ Barn | No Style | 1982 | Resource 73b is a wood-frame barn with a shallow-pitch, side-gable metal roof, metal and vertical vinyl siding. | Not Eligible |
| 73c | 307 Lake Shore Ln. 32.544333, -96.846508 | DOMESTIC/ Shed | No Style | 1982 | Resource 73c is a wood-frame shed with a front-gable roof and vertical vinyl siding. | Not Eligible |
| 74 | 309 Lake Shore Ln. 32.544684, -96.846186 | DOMESTIC/ Single family dwelling | Ranch | 1976 | Ranch style house with shallow-pitch, side-gable roof, horizontal vinyl siding, a partial width porch with a flat roof, and replacement windows. | Not Eligible |
| 75 | 320 Lake Shore Ln. 32.544386, -96.845687 | DOMESTIC/ Single family dwelling | Mixed | 1950 | Mixed style house with steep-pitch, side-gable roof over second story addition and shallow-pitch side-gable roof over original footprint, horizontal vinyl siding, a portico, and replacement windows. | Not Eligible |
| 76 | 603 E. Southbrook Dr. 32.544109, -96.845138 | DOMESTIC/ Single family dwelling | Ranch | 1982 | Ranch style house with shallow-pitch, cross-gable roof, horizontal vinyl and composite siding, a partial-width porch with a shed roof and picket-fence style railing, replacement windows, and a carport extending from the east façade of the house. An addition is located along the rear (north) façade of the house. | Not Eligible |
| 77 | 609 E. Southbrook Dr. 32.544233, -96.844651 | DOMESTIC/ Garage | No Style | 1982 | Resource 77 is a garage with a cross-gable roof, horizontal wood and vinyl siding, and sliding doors along the south façade. | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|---|----------------------------------|---------------------|---------|---|------------------|
| 78 | 611 E. Overhill Dr. 32.545065, -96.843843 | DOMESTIC/ Single family dwelling | Craftsman | 1940 | Craftsman style bungalow with clip-gable roof with generous eaves and brackets, horizontal vinyl siding, a partial-width porch with a shed roof, and replacement windows. | Not Eligible |
| 79a | 619 E. Overhill Dr. 32.545046, -96.842911 | DOMESTIC/ Single family dwelling | Ranch | 1981 | Ranch style house with shallow-pitch, side-gable roof, exposed rafter tails vertical vinyl siding, covered front stoop, and original double-hung windows. | Not Eligible |
| 79b | 619 E. Overhill Dr. 32.545156, -96.843035 | DOMESTIC/ Shed | No Style | 1982 | Resource 79b is a shed with a metal shed roof, metal siding, and an open bay on the front (south) façade. | Not Eligible |
| 80 | 2121 Uhl Rd. 32.546609, -96.842587 | DOMESTIC/ Unknown | No Style | 1980 | Resource 80 is a composite building featuring a variety of roof types, including gable, hip, and shed, as well as a variety of materials, including horizontal vinyl siding, wood siding, and metal siding. | Not Eligible |
| 81a | 2115 S. Uhl Rd. 32.547617, -96.842632 | DOMESTIC/ Single family dwelling | Ranch | 1982 | Ranch style house with shallow-pitch, cross-gable roof with generous eaves, brick and stone siding, vertical vinyl siding on gable ends, a recessed porch with decorative wrought iron supports and a brick half-wall, an exterior brick chimney, and a variety of replacement windows. A metal carport extends from the rear (west) façade of the house. | Not Eligible |
| 81b | 2115 S. Uhl Rd. 32.547780, -96.842957 | DOMESTIC/ Garage | No Style | 1982 | Resource 81b is a garage with a shallow-pitch, front-gable metal roof, metal siding, original windows, and a rolling garage door and panel door. | Not Eligible |
| 81c | 2115 S. Uhl Rd. 32.547740, -96.843701 | DOMESTIC/ Pole barn | No Style | 1979 | Resource 81c is a wood-frame pole barn with a shallow-pitch, metal shed roof, metal siding and three open bays. | Not Eligible |
| 81d | 2115 S. Uhl Rd. 32.547657, -96.843703 | DOMESTIC/ Shed | No Style | 1979 | Resource 81d is a shed with a metal gambrel shed, metal siding, wood panel doors, and an original window | Not Eligible |

| Resource No. | Address/ Location | Function/ Sub-function | Architectural Style | Date(s) | Integrity/Comments | NRHP Eligibility |
|--------------|--|--------------------------------------|-----------------------------|----------|---|------------------|
| 82 | 2155 S. I-35 32.549433, -96.823457 | DOMESTIC/ Single family dwelling | Ranch with chalet influence | Ca. 1965 | Ranch style house with chalet influence featuring vertical vinyl and rusticated stone siding, replacement windows, and a shallow-pitch, cross-gable roof with generous eaves. A modern shed and storage container are located nearby. The house appears to serve as the office or primary residence for an RV park located immediately to the south. A tall wood fence with brick posts and entry separates the house and RV park from the interstate frontage road. | Not Eligible |
| 83a | 901 N. I-35 32.546948, -96.823828 | HEALTHCARE/ Medical business/office | No Style | Ca. 1970 | Office building with a shallow-pitch, metal gable roof, metal siding, a vestibule, and replacement windows. A large addition spans from the north façade. The addition features a shallow-pitch, metal, gable roof, metal siding, a sliding bay door, and a metal cantilevered structure across the north façade. Currently occupied by Country Veterinary Clinic. | Not Eligible |
| 83b | 901 N. I-35 32.546918, -96.824690 | HEALTHCARE/ Medical business/Barn | No Style | Ca. 1980 | Metal barn with a shallow-pitch, metal gable-front roof and metal siding. Currently occupied by Country Veterinary Clinic. | Not Eligible |
| 83c | 901 N. I-35 32.547044, -96.825112 | HEALTHCARE/Medical business/ RV shed | No Style | Ca. 1980 | Large RV shed with a metal shed roof and steel supports. Currently occupied by Country Veterinary Clinic. | Not Eligible |
| 84 | 897 N. I-35 32.545574, -96.822963 | DOMESTIC/ Vacant | Ranch | Ca. 1955 | Ranch style house with brick siding, a partial width porch with simple wood posts, replacement sliding windows, and original casement windows. The house has a shallow pitch, gable-on-hip roof with modest eaves. Aerial photos show a covered back porch adjacent to the attached garage. Visibility of the house was somewhat limited due to heavy vegetation growth. The house is surrounded by a dilapidated chain link fence. The house appears to serve as the office or primary residence for the Village Square Mobile Home and RV Park, although it appears to be vacant. | Not Eligible |

Appendix C: Survey Forms for All Surveyed Properties

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 01 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1937 Tar Rd. 32.549482°, -96.956574° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1978 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with multiple hip roofs, brick siding, a recessed entry, a bay window, and replacement arched windows. Two brick half walls extend from the northeast and southeast corners of the house. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 01 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1937 Tar Rd. 32.549482°, -96.956574° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1978 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with multiple hip roofs, brick siding, a recessed entry, a bay window, and replacement arched windows. Two brick half walls extend from the northeast and southeast corners of the house. |



Camera facing west.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 02a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1948 Tar Rd. 32.549107°, -96.955512° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1978 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with cross-gable roof, generous eaves, horizontal wood siding on gable ends, brick siding, and replacement windows. A modern addition of a garage extends from the rear (southwest) corner of the house. |



Camera facing southeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 02a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1948 Tar Rd. 32.549107°, -96.955512° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1978 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with cross-gable roof, generous eaves, horizontal wood siding on gable ends, brick siding, and replacement windows. A modern addition of a garage extends from the rear (southwest) corner of the house. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 02b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1948 Tar Rd. 32.549072°, -96.955150° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 02b is a shed with a gambrel roof, horizontal vinyl siding, and replacement windows. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 02b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1948 Tar Rd. 32.549072°, -96.955150° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 02b is a shed with a gambrel roof, horizontal vinyl siding, and replacement windows. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 03a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 485 Tar Rd. 32.546774°, -96.956353° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1966 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, replacement metal hip roof, polychrome brick siding, a partial-width porch, original diamond plated windows, replacement sash windows, and a straddle ridge chimney. A carport extends from the rear (west) façade. |



Camera facing southwest

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 03a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 485 Tar Rd. 32.546774°, -96.956353° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1966 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, replacement metal hip roof, polychrome brick siding, a partial-width porch, original diamond plated windows, replacement sash windows, and a straddle ridge chimney. A carport extends from the rear (west) façade. |



Camera facing west.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 03b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 485 Tar Rd. 32.546830°, -96.956999° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 03b is a barn featuring three bays, a front-gable roof, and vertical wood siding. |



Camera facing west.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 03b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 485 Tar Rd. 32.546830°, -96.956999° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 03b is a barn featuring three bays, a front-gable roof, and vertical wood siding. |



Camera facing west.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 04 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 585 Tar Rd. 32.546193°, -96.955863° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1964 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with Victorian-style second-story addition. The house features multiple side-gable roofs, generous eaves on the ground floor, a turret, vinyl and polychrome brick siding. The ground floor has an encircling verandah, while the upper story features a partial-width deck. Both feature spindle-like ornamentation. In addition, the house features replacement windows. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 04 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 585 Tar Rd. 32.546193°, -96.955863° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1964 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with Victorian-style second-story addition. The house features multiple side-gable roofs, generous eaves on the ground floor, a turret, vinyl and polychrome brick siding. The ground floor has an encircling verandah, while the upper story features a partial-width deck. Both feature spindle-like ornamentation. In addition, the house features replacement windows. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 04 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 585 Tar Rd. 32.546050°, -96.956008° |
| Function/Sub-function: | DOMESTIC/ Carport |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern carport. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 05a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 482 Tar Rd. 32.547213°, -96.954627° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1968 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with cross-gable roof, horizontal vinyl siding, a stoop, replacement windows, and an exterior chimney. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 05a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 482 Tar Rd. 32.547213°, -96.954627° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1968 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with cross-gable roof, horizontal vinyl siding, a stoop, replacement windows, and an exterior chimney. |



Camera facing

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 05b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 482 Tar Rd. 32.547227°, -96.954816° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 1968 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 05b is a garage with a front-gable roof, horizontal vinyl siding, and replacement sliding bay doors. |



Camera facing north.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 05b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 482 Tar Rd. 32.547227°, -96.954816° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 1968 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 05b is a garage with a front-gable roof, horizontal vinyl siding, and replacement sliding bay doors. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 05c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 482 Tar Rd. 32.547389°, -96.954843° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1968 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 05c is a shed with a side-gable roof, exposed rafter tails, and horizontal wood siding. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 05c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 482 Tar Rd. 32.547389°, -96.954843° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1968 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 05c is a shed with a side-gable roof, exposed rafter tails, and horizontal wood siding. |



Camera facing north.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 05d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 482 Tar Rd. 32.547412°, -96.954749° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 05d is a shed with a gambrel roof, vertical wood siding. The shed sits on a system of wood and concrete piers. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 05d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 482 Tar Rd. 32.547412°, -96.954749° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 05d is a shed with a gambrel roof, vertical wood siding. The shed sits on a system of wood and concrete piers. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 05 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 482 Tar Rd. 32.547404°, -96.954960° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1989 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 06a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 551 Knight St. 32.547562°, -96.951886° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1955 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with irregular footprint, cross-gable and hip roofs, dormers, brick and horizontal vinyl siding, a partial-width porch, and replacement windows with louvered shutters, a partial-width porch, and a breezeway. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 06a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 551 Knight St. 32.547562°, -96.951886° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1955 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with irregular footprint, cross-gable and hip roofs, dormers, brick and horizontal vinyl siding, a partial-width porch, and replacement windows with louvered shutters, a partial-width porch, and a breezeway. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 06b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 551 Knight St. 32.547873°, -96.952364° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 06b is a metal barn with a shallow-pitch, side-gable, metal roof and metal siding. |



Camera facing north.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 06b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 551 Knight St. 32.547873°, -96.952364° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 06b is a metal barn with a shallow-pitch, side-gable, metal roof and metal siding. |



Camera facing north.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 06 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 551 Knight St. 32.547967°, -96.952192° |
| Function/Sub-function: | DOMESTIC/ Machine shed |
| Construction Date: | Ca. 1995 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern machine shed. |



Camera facing north.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 06 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 551 Knight St. 32.547967°, -96.952192° |
| Function/Sub-function: | DOMESTIC/ Machine shed |
| Construction Date: | Ca. 1995 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern machine shed. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 07 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 501 Knight St. 32.547681°, -96.948996° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1965 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with tiered side-gable roof and a front-gable roof over the carport. The house features horizontal vinyl siding, a partial-width porch, replacement windows, and a front slope chimney. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 07 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 501 Knight St. 32.547681°, -96.948996° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1965 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with tiered side-gable roof and a front-gable roof over the carport. The house features horizontal vinyl siding, a partial-width porch, replacement windows, and a front slope chimney. |



Camera facing north.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 08 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 491 Hidden Valley Rd. 32.547946, -96.942182 |
| Function/Sub-function: | DOMESTIC/ Single-family dwelling |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with cross-gable hipped roof. No rights-of-entry, not visible from public ROW. Per historic aerials, the other buildings on property appear to be older barns and sheds that pre-date the house. |



Aerial view of resources on Property 08, facing north. Google Earth.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 08 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 491 Hidden Valley Rd. 32.547946, -96.942182 |
| Function/Sub-function: | DOMESTIC/ Single-family dwelling |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with cross-gable hipped roof. No rights-of-entry, not visible from public ROW. Per historic aerials, the other buildings on property appear to be older barns and sheds that pre-date the house. |



Aerial view of resources on Property 08, facing north. Google Earth.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 08 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 491 Hidden Valley Rd. 32.547946, -96.942182 |
| Function/Sub-function: | DOMESTIC/ Single-family dwelling |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern gate. View of parcel from ROW. Historians were not able to view resources within the parcel due to their proximity to the ROW and vegetation. |




Camera facing east.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 08 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 491 Hidden Valley Rd. 32.547946, -96.942182 |
| Function/Sub-function: | DOMESTIC/ Single-family dwelling |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | View of parcel from ROW. Historians were not able to view resources within the parcel due to their proximity to the ROW and vegetation. |




Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 09 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 476 Hidden Valley Rd. 32.546245, -96.939552 |
| Function/Sub-function: | DOMESTIC/ Single-family dwelling |
| Construction Date: | Ca. 1975 |
| NRHP Eligibility: | Unknown |
| Integrity/Comments: | Unknown residence with solar panels visible on the roof. No rights-of-entry, not visible from public ROW. Date from CAD data. |



Aerial view of resources on Property 09, facing north. Google Earth.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 09 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 476 Hidden Valley Rd. 32.546245, -96.939552 |
| Function/Sub-function: | DOMESTIC/ Single-family dwelling |
| Construction Date: | Ca. 1975 |
| NRHP Eligibility: | Unknown |
| Integrity/Comments: | Unknown residence with solar panels visible on the roof. No rights-of-entry, not visible from public ROW. Date from CAD data. |



Aerial view of resources on Property 09, facing north. Google Earth.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 10a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1601 S. Joe Wilson Rd. 32.552060°, -96.927237° |
| Function/Sub-function: | AGRICULTURE/ Single family dwelling |
| Construction Date: | 1962 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with multiple tiered, shallow-pitch, side-gable roofs, brick siding, and replacement sliding windows. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 10a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1601 S. Joe Wilson Rd. 32.552060°, -96.927237° |
| Function/Sub-function: | AGRICULTURE/ Single family dwelling |
| Construction Date: | 1962 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with multiple tiered, shallow-pitch, side-gable roofs, brick siding, and replacement sliding windows. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 10b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1601 S. Joe Wilson Rd. 32.551687°, -96.927916° |
| Function/Sub-function: | AGRICULTURE/ Barn |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 10b is a barn. Due to vegetation, project historians were unable to view the barn from the public ROW. Per aerial imagery, the barn appears to have a square footprint and metal, gable roof. |



Aerial view, facing north (GoogleEarth, 2020).

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 10c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1601 S. Joe Wilson Rd. 32.552047°, -96.927453° |
| Function/Sub-function: | AGRICULTURE/ Shed |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 10c is possibly a shed. Due to an obstructed view, project historians were unable to view Resource 10c. Per aerial imagery, the structure appears to have a rectangular footprint and hip roof. |



Aerial view, facing north (GoogleEarth, 2020).

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 10 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1601 S. Joe Wilson Rd. 32.554257°, -96.928726° |
| Function/Sub-function: | AGRICULTURE/ Stable |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern stable. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 11 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1707 S. Joe Wilson Rd. 32.550446°, -96.924758° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1968 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-gable roof, polychrome brick siding, vinyl siding on gable ends and along the recessed porch. The house features both original and replacement windows. An attached carport extends from the south façade of the house. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 11 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1707 S. Joe Wilson Rd. 32.550446°, -96.924758° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1968 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-gable roof, polychrome brick siding, vinyl siding on gable ends and along the recessed porch. The house features both original and replacement windows. An attached carport extends from the south façade of the house. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 11 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1707 S. Joe Wilson Rd. 32.550446°, -96.924758° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1995 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed. |



Camera facing east.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 12 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1730 S. Joe Wilson Rd. 32.551195°, -96.924327° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1973 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with a gable roof, vertical wood siding, and replacement windows. An open porch extends from the south façade of the house. |




Camera facing east.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 12 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1730 S. Joe Wilson Rd. 32.551195°, -96.924327° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1973 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with a gable roof, vertical wood siding, and replacement windows. An open porch extends from the south façade of the house. |



Camera facing east.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 13a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1702 S. Joe Wilson Rd. 32.552352°, -96.923857° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1978 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | A Ranch style house featuring a rectangular plan and a hip roof. Project historians were unable to view Resource 13a from public ROW due to vegetation. |



Aerial view, facing north (GoogleEarth, 2020).

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 13b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1702 S. Joe Wilson Rd. 32.551974°, -96.924800° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | 1978 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | A barn with metal flat and shed roofs and metal siding. Project historians were limited due to vegetation and views from ROW, but per aerial imagery, several additional structures are located within the parcel. |



Camera facing east.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 13b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1702 S. Joe Wilson Rd. 32.551974°, -96.924800° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | 1978 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | A barn with metal flat and shed roofs and metal siding. Project historians were limited due to vegetation and views from ROW, but per aerial imagery, several additional structures are located within the parcel. |




Camera facing east.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 14 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1621 S. Joe Wilson Rd. 32.554078°, -96.921265° |
| Function/Sub-function: | DOMESTIC/ Vacant |
| Construction Date: | Ca. 1940 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Abandoned house hidden deep within vegetation. Although historians had right-of-entry to the property, thick vegetation and heavy poison ivy growth prevented access to the house. |



Heavy vegetation and poison ivy growth blocking access to the resource, facing east.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 14 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1621 S. Joe Wilson Rd. 32.554078°, -96.921265° |
| Function/Sub-function: | DOMESTIC/ Vacant |
| Construction Date: | Ca. 1940 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Abandoned house hidden deep within vegetation. Although historians had right-of-entry to the property, thick vegetation and heavy poison ivy growth prevented access to the house. |



Aerial view, facing north (Google Earth 2020).

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 14 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1621 S. Joe Wilson Rd. 32.554078°, -96.921265° |
| Function/Sub-function: | DOMESTIC/ Vacant |
| Construction Date: | Ca. 1940 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Abandoned house hidden deep within vegetation. Although historians had right-of-entry to the property, thick vegetation and heavy poison ivy growth prevented access to the house. |



Aerial view of parcel showing location of the vacant resource, facing north (Google Earth 2020).

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 15a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1511 S. Joe Wilson Rd. 32.556862°, -96.925949° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with two-story addition at rear (west) façade of house. The house features hip and side-gable roofs, polychrome brick and horizontal vinyl siding, a partial-width porch, and replacement windows. |



Camera facing west.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 15a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1511 S. Joe Wilson Rd. 32.556862°, -96.925949° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with two-story addition at rear (west) façade of house. The house features hip and side-gable roofs, polychrome brick and horizontal vinyl siding, a partial-width porch, and replacement windows. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 15b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1511 S. Joe Wilson Rd. 32.556684°, -96.926108° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 15b is a metal barn with a shallow-pitch, metal side-gable roof and metal siding. It features large sliding bay doors. |



Camera facing west.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 15b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1511 S. Joe Wilson Rd. 32.556684°, -96.926108° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 15b is a metal barn with a shallow-pitch, metal side-gable roof and metal siding. It features large sliding bay doors. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 016a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1424 Joe Wilson Rd. 32,333137°, -96.553007° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house featuring a linear plan, a side-gable roof with a raised center extending over the porch, painted brick siding with horizontal vinyl siding on the gable ends, a partial-width porch accentuated by Doric columns, and replacement wood-sash windows. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 016a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1424 Joe Wilson Rd. 32,333137°, -96.553007° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house featuring a linear plan, a side-gable roof with a raised center extending over the porch, painted brick siding with horizontal vinyl siding on the gable ends, a partial-width porch accentuated by Doric columns, and replacement wood-sash windows. |



Camera facing east.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 016b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1424 Joe Wilson Rd. 32.333200°, -96.552893° |
| Function/Sub-function: | DOMESTIC/ Carport |
| Construction Date: | Ca. 1975 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Metal carport featuring a metal roof and metal supports. |



Camera facing east.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 016b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1424 Joe Wilson Rd. 32.333200°, -96.552893° |
| Function/Sub-function: | DOMESTIC/ Carport |
| Construction Date: | Ca. 1975 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Metal carport featuring a metal roof and metal supports. |



Camera facing east.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 016c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1424 Joe Wilson Rd. 32.333199°, -96552858° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 1975 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Garage featuring a cross-gambrel roof, horizontal vinyl siding, and the original garage door. |



Camera facing east.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 016c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1424 Joe Wilson Rd. 32.333199°, -96552858° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 1975 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Garage featuring a cross-gambrel roof, horizontal vinyl siding, and the original garage door. |



Camera facing east.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 17a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1415 S. Joe Wilson Rd. 32.559512°, -96.925935° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1973 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with side-gable roof, brick siding, partial-width porch, replacement windows and panel and louvered shutters. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 17a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1415 S. Joe Wilson Rd. 32.559512°, -96.925935° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1973 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with side-gable roof, brick siding, partial-width porch, replacement windows and panel and louvered shutters. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 17b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1415 S. Joe Wilson Rd. 32.556860°, -96.928104° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 17b is a barn with a shallow-pitch, metal gable roof with cantilevered overhangs and metal siding. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 17b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1415 S. Joe Wilson Rd. 32.556860°, -96.928104° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 17b is a barn with a shallow-pitch, metal gable roof with cantilevered overhangs and metal siding. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 17c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1415 S. Joe Wilson Rd. 32.557127°, -96.928423° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 17c is a barn with a shallow-pitch, metal gable roof and metal siding. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 17c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1415 S. Joe Wilson Rd. 32.557127°, -96.928423° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 17c is a barn with a shallow-pitch, metal gable roof and metal siding. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 17d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1415 S. Joe Wilson Rd. 32.557853°, -96.927795° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 17d is a barn with a shallow-pitch, metal gable roof and metal siding. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 17d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1415 S. Joe Wilson Rd. 32.557853°, -96.927795° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 17d is a barn with a shallow-pitch, metal gable roof and metal siding. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 17e |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1415 S. Joe Wilson Rd. 32.557033°, -96.929226° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 17e is a barn. Due to vegetation, project historians were unable to view the barn from the public ROW. Per aerial imagery, the barn features a square footprint and metal, gable roof. This resource appears on a 1970 aerial. |



Aerial view facing north (Google Earth 2020).

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 17f |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1415 S. Joe Wilson Rd. 32.556697°, -96.928284° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 17f is possibly a barn. Project historians were unable to view Resource 17f from public ROW due to vegetation. Resource 17f features a square footprint and a metal roof. This resource appears on a 1970 aerial. |



Aerial view facing north (Google Earth 2020).

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 17g |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1415 S. Joe Wilson Rd. 32.558041°, -96.928376° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 17g is a small metal shed with a shallow pitch metal gable roof and metal siding.. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 17g |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1415 S. Joe Wilson Rd. 32.558041°, -96.928376° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 17g is a small metal shed with a shallow pitch metal gable roof and metal siding.. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 18 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1410 Joe Wilson Road 32.559757°, -96.924989° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house featuring a linear plan with a hipped roof extending over the porch, painted brick siding, an attached garage on the west façade, a partial-width porch accentuated by two wood columns, and replacement sash and picture window with louvered shutters. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 18 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1410 Joe Wilson Road 32.559757°, -96.924989° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house featuring a linear plan with a hipped roof extending over the porch, painted brick siding, an attached garage on the west façade, a partial-width porch accentuated by two wood columns, and replacement sash and picture window with louvered shutters. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 18 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1410 Joe Wilson Road 32.559757°, -96.924989° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 18 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1410 Joe Wilson Road 32.559757°, -96.924989° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern machine shed |



Camera facing east.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 19 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1401 Joe Wilson Road 32.560082°, -96.927298° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | N/A |
| NRHP Eligibility: | Undetermined |
| Integrity/Comments: | Entryway with closed gate. Project historians were unable to photograph resources from the public ROW due to vegetation. |



Camera facing west.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 19 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1401 Joe Wilson Road 32.560082°, -96.927298° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | N/A |
| NRHP Eligibility: | Undetermined |
| Integrity/Comments: | Project historians were unable to photograph resources from the public ROW due to vegetation. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 19a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1401 Joe Wilson Road 32.560082°, -96.927298° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Undetermined |
| Integrity/Comments: | Possible Ranch style house. According to Dallas CAD data, the house features a gable roof and brick siding. |



Aerial view facing north (Google Earth 2020)

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 19b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1401 Joe Wilson Road 32.559920°, -96.927970° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Per aerial imagery, Resource No. 19b appears to be a shed with a metal roof. |



Aerial view facing north (Google Earth 2020)

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 20a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1321 Joe Wilson Rd. 32.562511°, -96.925722° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1945 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Minimal Traditional style house with Craftsman influences features a side-gable roof with exposed rafter tails and generous eaves, horizontal wood siding, a covered stoop with a flat roof and decorative iron posts, replacement windows, and a rear addition with a side-gable roof. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 20a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1321 Joe Wilson Rd. 32.562511°, -96.925722° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1945 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Minimal Traditional style house with Craftsman influences features a side-gable roof with exposed rafter tails and generous eaves, horizontal wood siding, a covered stoop with a flat roof and decorative iron posts, replacement windows, and a rear addition with a side-gable roof. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 20b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1321 Joe Wilson Rd. 32.562434°, -96.925918° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Garage featuring a front-gable roof with exposed rafter tails, asbestos shingle siding, original windows, two replacement garage doors, and a rear, wood-frame addition with a shed roof and metal siding. |



Camera facing west.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 20b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1321 Joe Wilson Rd. 32.562434°, -96.925918° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Garage featuring a front-gable roof with exposed rafter tails, asbestos shingle siding, original windows, two replacement garage doors, and a rear, wood-frame addition with a shed roof and metal siding. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 20c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1321 Joe Wilson Rd. 32.562916°, -96.926164° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Barn featuring a rectangular plan, a front-gable roof, a hay loft, metal siding, and an open, central bay. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 20c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1321 Joe Wilson Rd. 32.562916°, -96.926164° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Barn featuring a rectangular plan, a front-gable roof, a hay loft, metal siding, and an open, central bay. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 20d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1321 Joe Wilson Rd. 32.562300°, -96.926054° |
| Function/Sub-function: | DOMESTIC/ Pole barn |
| Construction Date: | Ca. 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Small pole barn featuring a saltbox roof, metal siding, and open bays on the south façade. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 20d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1321 Joe Wilson Rd. 32.562300°, -96.926054° |
| Function/Sub-function: | DOMESTIC/ Pole barn |
| Construction Date: | Ca. 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Small pole barn featuring a saltbox roof, metal siding, and open bays on the south façade. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 21a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1329 Joe Wilson Rd. 32.561446°, -96.925996° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1975 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house featuring a linear plan, a tiered side-gable roof with exposed rafter tails, brick siding with vertical wood siding on the gable ends, a partial-width porch with wood columns, original windows with louvered shutters, and a rear addition. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 21a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1329 Joe Wilson Rd. 32.561446°, -96.925996° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1975 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house featuring a linear plan, a tiered side-gable roof with exposed rafter tails, brick siding with vertical wood siding on the gable ends, a partial-width porch with wood columns, original windows with louvered shutters, and a rear addition. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 21b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1329 Joe Wilson Rd. 32.561628°, -96.926154° |
| Function/Sub-function: | DOMESTIC/ Well house |
| Construction Date: | Ca. 1975 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Well house of brick construction featuring a gable roof with exposed rafter tails and generous eaves. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 21b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1329 Joe Wilson Rd. 32.561628°, -96.926154° |
| Function/Sub-function: | DOMESTIC/ Well house |
| Construction Date: | Ca. 1975 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Well house of brick construction featuring a gable roof with exposed rafter tails and generous eaves. |



Camera facing west.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 21c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1329 Joe Wilson Rd. 32.561622°, -96.925517° |
| Function/Sub-function: | DOMESTIC/ Gate |
| Construction Date: | Ca. 1975 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Two brick piers flanking the driveway. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 21c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1329 Joe Wilson Rd. 32.561622°, -96.925517° |
| Function/Sub-function: | DOMESTIC/ Gate |
| Construction Date: | Ca. 1975 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Two brick piers flanking the driveway. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 22a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1135 Bear Creek Rd. 32.561186°, -96.924438° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house featuring a linear plan, hipped roof, painted brick siding, a partial-width porch, original diamond-paned windows with louvered shutters, an attached garage on the east façade, and a brick chimney located on the rear slope of the roof. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 22a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1135 Bear Creek Rd. 32.561186°, -96.924438° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house featuring a linear plan, hipped roof, painted brick siding, a partial-width porch, original diamond-paned windows with louvered shutters, an attached garage on the east façade, and a brick chimney located on the rear slope of the roof. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 22b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1135 Bear Creek Rd. 32.561513°, -96.924219° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Metal garage featuring a metal gambrel roof and metal siding. |



Camera facing north.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 22b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1135 Bear Creek Rd. 32.561513°, -96.924219° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Metal garage featuring a metal gambrel roof and metal siding. |



Camera facing northeast

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 23 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1136 Bear Creek Rd. 32.560458°, -96.924252° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1960 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with an irregular plan, a hipped roof, brick siding, original metal sash windows, and a recessed stoop. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 23 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1136 Bear Creek Rd. 32.560458°, -96.924252° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca.1960 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with an irregular plan, a hipped roof, brick siding, original metal sash windows, and a recessed stoop. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 23 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1136 Bear Creek Rd. 32.560458°, -96.924252° |
| Function/Sub-function: | DOMESTIC/ Mobile home |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern mobile home. |



Camera facing south.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 24a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1155 Bear Creek Rd. 32.561424°, -96.923935° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1901 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | I-house featuring a steep-pitch, side-gable roof, replacement horizontal wood siding, partial-width stacked porches with square columns and railings, replacement wood-sash windows, and a rear addition. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 24a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1155 Bear Creek Rd. 32.561424°, -96.923935° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1901 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | I-house featuring a steep-pitch, side-gable roof, replacement horizontal wood siding, partial-width stacked porches with square columns and railings, replacement wood-sash windows, and a rear addition. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 24b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1155 Bear Creek Rd. 32.561432°, -96.923727° |
| Function/Sub-function: | DOMESTIC/ Pole barn |
| Construction Date: | Ca. 1960 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Pole barn featuring a shallow-pitch, side-gable, metal roof, metal siding, original metal frame windows, and two open bays serving as garage space. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 24b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1155 Bear Creek Rd. 32.561432°, -96.923727° |
| Function/Sub-function: | DOMESTIC/ Pole barn |
| Construction Date: | Ca. 1960 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Pole barn featuring a shallow-pitch, side-gable, metal roof, metal siding, original metal frame windows, and two open bays serving as garage space. |



Camera facing north.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 25 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1159 Bear Creek Rd. 32.561288°, -96.921681° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house featuring an L-shape plan, a symmetrical façade with a recessed porch and two protruding bays, a shallow-pitch, hipped roof, brick siding, original windows, and a rear slope, brick chimney. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 25 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1159 Bear Creek Rd. 32.561288°, -96.921681° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house featuring an L-shape plan, a symmetrical façade with a recessed porch and two protruding bays, a shallow-pitch, hipped roof, brick siding, original windows, and a rear slope, brick chimney. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 25 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1159 Bear Creek Rd. 32.561288°, -96.921681° |
| Function/Sub-function: | DOMESTIC/ Playground |
| Construction Date: | Ca. 2015 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern playground and playhouse. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 25 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1159 Bear Creek Rd. 32.561288°, -96.921681° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 2000 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern secondary housing. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 25 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1159 Bear Creek Rd. 32.561288°, -96.921681° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1995 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern sheds (2). |



Camera facing north.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 25 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1159 Bear Creek Rd. 32.561288°, -96.921681° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1995 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern sheds (2) |




Camera facing north.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 25 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1159 Bear Creek Rd. 32.561288°, -96.921681° |
| Function/Sub-function: | DOMESTIC/ Machine shed |
| Construction Date: | Ca. 2015 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern machine shed |



Camera facing north.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 26 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1123 Joe Wilson Rd. 32.562344, -96.921125 |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1960 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Isolated front-gabled metal barn with no other buildings on the parcel. Does not appear to be associated with any historic-age residence or other outbuildings. Not visible from public-right-of-way, and historians had no right-of-entry. |



Aerial view of barn at Property No. 26, facing north (Google Earth 2020).

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 26 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1123 Joe Wilson Rd. 32.562344, -96.921125 |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | N/A |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | New construction inhibiting view of resources. |



Camera facing east.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 26 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1123 Joe Wilson Rd. 32.562344, -96.921125 |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | N/A |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | New construction and vegetation inhibiting views of resources. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 27 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1223 Bear Creek Rd. Rd. 32.561280°, -96.920842° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1965 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, side-gable roof, painted brick siding, a small portico accentuated by a decorative iron post, original sash windows, an attached garage on the south façade, and a rear slope chimney. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 27 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1223 Bear Creek Rd. Rd. 32.561280°, -96.920842° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1965 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, side-gable roof, painted brick siding, a small portico accentuated by a decorative iron post, original sash windows, an attached garage on the south façade, and a rear slope chimney. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 27 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1223 Bear Creek Rd. Rd. 32.561280°, -96.920842° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 2008 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern garage. |



Camera facing north.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 27 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1223 Bear Creek Rd. Rd. 32.561280°, -96.920842° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 2015 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed. |



Camera facing north.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 28 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1326 Bear Creek Rd. 32.560317°, -96.920762° |
| Function/Sub-function: | DOMESTIC/Single family dwelling |
| Construction Date: | 1965 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-hip roof, brick siding, a front stoop, both original and replacement windows, louvered shutters, an exterior chimney, and an attached garage to the west with a replacement garage door. |



Camera facing southeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 28 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1326 Bear Creek Rd. 32.560317°, -96.920762° |
| Function/Sub-function: | DOMESTIC/Single family dwelling |
| Construction Date: | Ca. 1965 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-hip roof, brick siding, a front stoop, both original and replacement windows, louvered shutters, an exterior chimney, and an attached garage to the west with a replacement garage door. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 28 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1326 Bear Creek Rd. 32.559846°, -96.921245° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 2019 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 28 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1326 Bear Creek Rd. 32.559892°, -96.921033° |
| Function/Sub-function: | DOMESTIC/ Machine shed |
| Construction Date: | Ca. 2019 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern machine shed. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 28 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1326 Bear Creek Rd. 32.560128°, -96.920904° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 2016 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern garage. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 29 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1327 Bear Creek Rd. 32.561664°, -96.919866° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1965 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with an L-shaped plan featuring a shallow-pitch, side-gable roof, brick siding, a recessed, partial-width porch, and replacement windows with louvered shutters. |



Camera facing north.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 29 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1327 Bear Creek Rd. 32.561664°, -96.919866° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1965 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with an L-shaped plan featuring a shallow-pitch, side-gable roof, brick siding, a recessed, partial-width porch, and replacement windows with louvered shutters. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 30a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1328 Bear Creek Rd. 32.560296°, -96.919078° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1978 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, hip roof, brick siding, and replacement windows. Rounded arches mark the main entry point. An attached garage is located to the west. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 30a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1328 Bear Creek Rd. 32.560296°, -96.919078° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1978 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, hip roof, brick siding, and replacement windows. Rounded arches mark the main entry point. An attached garage is located to the west. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 30b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1328 Bear Creek Rd. 32.559752° , -96.918857° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1981 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 30b is a shed with a front-gable roof and vertical wood siding. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 30b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1328 Bear Creek Rd. 32.559752°, -96.918857° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1981 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 30b is a shed with a front-gable roof and vertical wood siding. |



Camera facing south.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 31a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1349 Bear Creek Rd. 32.561251°, -96.918263° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1905 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Folk Victorian style house featuring a cross-gable roof, original horizontal wood siding, a covered verandah with a shallow-pitch, hipped roof square columns, replacement windows, and a rear addition, which includes an attached garage, and a front slope, stone chimney. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 31a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1349 Bear Creek Rd. 32.561251°, -96.918263° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1905 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Folk Victorian style house featuring a cross-gable roof, original horizontal wood siding, a covered verandah with a shallow-pitch, hipped roof square columns, replacement windows, and a rear addition, which includes an attached garage and a front slope, stone chimney. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 31b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1349 Bear Creek Rd. 32.561399°, -96.918422° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 1930 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Wood-frame garage featuring two open bays, a front-gable metal roof and a shallow-pitch, metal shed roof, and vertical and wood siding. |



Camera facing north.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 31b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1349 Bear Creek Rd. 32.561399°, -96.918422° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 1930 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Wood-frame garage featuring two open bays, a front-gable metal roof and a shallow-pitch, metal shed roof, and vertical and wood siding. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 31c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1349 Bear Creek Rd. 32.561257°, -96.918546° |
| Function/Sub-function: | AGRICULTURE / Pole barn |
| Construction Date: | Ca. 1940 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Metal pole barn featuring a rectangular plan, a shallow-pitch, side-gable metal roof with wide overhanging eaves, and metal siding. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 31c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1349 Bear Creek Rd. 32.561257°, -96.918546° |
| Function/Sub-function: | AGRICULTURE / Pole barn |
| Construction Date: | Ca. 1940 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Metal pole barn featuring a rectangular plan, a shallow-pitch, side-gable metal roof with wide overhanging eaves, and metal siding. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 31d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1349 Bear Creek Rd. 32.561481°, -96.918236° |
| Function/Sub-function: | AGRICULTURE / Loafing shed |
| Construction Date: | Ca. 1940 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Loafing shed featuring a metal, saltbox roof and metal siding. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 31d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1349 Bear Creek Rd. 32.561481°, -96.918236° |
| Function/Sub-function: | AGRICULTURE / Loafing shed |
| Construction Date: | Ca. 1940 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Loafing shed featuring a metal, saltbox roof and metal siding. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 31e |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1349 Bear Creek Rd. 32.561819°, -96.918646° |
| Function/Sub-function: | AGRICULTURE / Loafing shed |
| Construction Date: | Ca. 1940 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Wood-frame loafing shed featuring a large open bay, a side-gable, metal roof, and metal siding. |



Camera facing north.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 31e |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1349 Bear Creek Rd. 32.561819°, -96.918646° |
| Function/Sub-function: | AGRICULTURE / Loafing shed |
| Construction Date: | Ca. 1940 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Wood-frame loafing shed featuring a large open bay, a side-gable, metal roof, and metal siding. |



Camera facing north.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 31f |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1349 Bear Creek Rd. 32.562039°, -96.918709° |
| Function/Sub-function: | AGRICULTURE / Pole barn |
| Construction Date: | Ca. 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Wood-frame pole barn featuring a shallow-pitch, front-gable, metal roof, metal siding, and three large bays. |



Camera facing north.

| | |
|------------------------|--|
| Survey Date: | April 10, 2020 |
| Resource No: | 31f |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1349 Bear Creek Rd. 32.562039°, -96.918709° |
| Function/Sub-function: | AGRICULTURE / Pole barn |
| Construction Date: | Ca. 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Wood-frame pole barn featuring a shallow-pitch, front-gable, metal roof, metal siding, and three large bays. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 31g |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1349 Bear Creek Rd. 32.561254°, -96.918883° |
| Function/Sub-function: | AGRICULTURE/ Barn |
| Construction Date: | Ca. 1930 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Large vacant wood barn with vertical board siding, open/missing door, and front-gabled roof with metal roofing. Barn is completely obscured due to vegetation except during winter months; identified post-survey via historic aerials. |



Aerial view, facing north (Google Earth 2020).

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 31g |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1349 Bear Creek Rd. 32.561254°, -96.918883° |
| Function/Sub-function: | AGRICULTURE/ Barn |
| Construction Date: | Ca. 1930 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Large vacant wood barn with vertical board siding, open/missing door, and front-gabled roof with metal roofing. Barn is completely obscured due to vegetation except during winter months; identified post-survey via historic aerials. |



Camera facing northeast (Google Streetview revealing hidden barn, November 2018).

| | |
|------------------------|---|
| Survey Date: | April 10, 2020 |
| Resource No: | 31g |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1349 Bear Creek Rd. 32.561254°, -96.918883° |
| Function/Sub-function: | AGRICULTURE/ Barn |
| Construction Date: | Ca. 1930 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Large vacant wood barn with vertical board siding, open/missing door, and front-gabled roof with metal roofing. Barn is completely obscured due to vegetation except during winter months; identified post-survey via historic aerials. |



Camera facing northeast (Google Streetview showing vegetative view, July 2018).

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 32a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1360 Bear Creek Rd. 32.560298°, -96.917705° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1978 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with side-gable roof, brick siding, vinyl siding on gable ends, replacement windows accentuated by paneled shutters, and a partial-width porch. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 32a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1360 Bear Creek Rd. 32.560298°, -96.917705° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1978 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with side-gable roof, brick siding, vinyl siding on gable ends, replacement windows accentuated by paneled shutters, and a partial-width porch. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 32b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1360 Bear Creek Rd. 32.559833°, -96.917797° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1978 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 32b is possibly a barn. Project historians were unable to view Resource 32b due to vegetation and structures obstructing the view from public ROW. |



Aerial view of resources, facing north (Google Earth 2020).

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 33 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1470 Bear Creek Rd. 32.560222°, -96.914243° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1978 |
| NRHP Eligibility: | Undetermined |
| Integrity/Comments: | Project historians were unable to photograph resources from the public ROW due to vegetation. According to Dallas CAD, the property includes a one-and-a-half story wood-frame house with brick siding, a gable roof, and an attached garage and carport. A storage building and outbuilding may also be present on the parcel according to CAD data. |



Camera facing south.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 33 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1470 Bear Creek Rd. 32.560222°, -96.914243° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1978 |
| NRHP Eligibility: | Undetermined |
| Integrity/Comments: | Project historians were unable to photograph resources from the public ROW due to vegetation. According to Dallas CAD, the property includes a one-and-a-half story wood-frame house with brick siding, a gable roof, and an attached garage and carport. A storage building and outbuilding may also be present on the parcel according to CAD data. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 34 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1474 Bear Creek Rd. 32.560427°, -96.912539° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with hip roof, polychrome brick siding, a recessed porch, replacement windows, a rear slope chimney, and two decorative brick half-walls extending from the northwest and northeast corners of the house. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 34 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1474 Bear Creek Rd. 32.560427°, -96.912539° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with hip roof, polychrome brick siding, a recessed porch, replacement windows, a rear slope chimney, and two decorative brick half-walls extending from the northwest and northeast corners of the house. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 35 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1576 Bear Creek Rd. 32.560471°, -96.911466° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with hip roof, polychrome brick siding, a recessed entry, original windows with panel shutters, and replacement garage doors. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 35 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1576 Bear Creek Rd. 32.560471°, -96.911466° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with hip roof, polychrome brick siding, a recessed entry, original windows with panel shutters, and replacement garage doors. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 35 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1576 Bear Creek Rd. 32.560383°, -96.911294° |
| Function/Sub-function: | DOMESTIC/ Carport |
| Construction Date: | Ca. 2010 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern carport. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 35 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1576 Bear Creek Rd. 32.560298°, -96.911343° |
| Function/Sub-function: | DOMESTIC/ Unknown |
| Construction Date: | Ca. 2010 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern roofline |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 35 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1576 Bear Creek Rd. 32.560419°, -96.911616° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 2010 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 36a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1902 Bear Creek Rd. 32.560195°, -96.896535° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with hip roof, brick siding, front stoop, and replacement windows. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 36a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1902 Bear Creek Rd. 32.560195°, -96.896535° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with hip roof, brick siding, front stoop, and replacement windows. |



Camera facing south.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 36b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1902 Bear Creek Rd. 32.559871°, -96.896324° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 36b is a metal barn with a metal, front-gable roof and metal siding. |



Camera facing south.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 36b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1902 Bear Creek Rd. 32.559871°, -96.896324° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 36b is a metal barn with a metal, front-gable roof and metal siding. |



Camera facing south.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 36c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1902 Bear Creek Rd. 32.560001°, -96.896321° |
| Function/Sub-function: | DOMESTIC/ Tank |
| Construction Date: | Ca. 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 36c is a possible a water tank, however, due to views from the public ROW and vegetation, it is difficult to confirm the purpose of the structure. It is a barreled structure with metal siding. |



Camera facing south.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 36c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1902 Bear Creek Rd. 32.560001°, -96.896321° |
| Function/Sub-function: | DOMESTIC/ Tank |
| Construction Date: | Ca. 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 36c is a possible a water tank, however, due to views from the public ROW and vegetation, it is difficult to confirm the purpose of the structure. It is a barreled structure with metal siding. |



Camera facing south.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 36d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1902 Bear Creek Rd. 32.560008°, -96.896368° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 36d is a shed with a wood-shingle gable roof, exposed rafter tails, horizontal wood siding, and replacement windows. The roof appears to be in poor condition. |



Camera facing south.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 36d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1902 Bear Creek Rd. 32.560008°, -96.896368° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 36d is a shed with a wood-shingle gable roof, exposed rafter tails, horizontal wood siding, and replacement windows. The roof appears to be in poor condition. |



Camera facing south.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 36e |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1902 Bear Creek Rd. 32.560689°, -96.896368° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 36e is a shed with a side-gable, metal roof and horizontal wood siding. Original windows have been boarded up. |



Camera facing east.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 36e |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1902 Bear Creek Rd. 32.560689°, -96.896368° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 36e is a shed with a side-gable, metal roof and horizontal wood siding. Original windows have been boarded up. |



Camera facing southeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 37 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1914 Bear Creek Rd. 32.560606°, -96.895594° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | A highly renovated Ranch style house with a hip roof, horizontal vinyl siding, a partial-width porch with decorative railings, and replacement sash and picture windows. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 37 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1914 Bear Creek Rd. 32.560606°, -96.895594° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | A highly renovated Ranch style house with a hip roof, horizontal vinyl siding, a partial-width porch with decorative railings, and replacement sash and picture windows. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 38a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2002 Bear Creek Rd. 32.560583°, -96.895312° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | A highly renovated Ranch style house with a shallow-pitch, hip roof with generous eaves, removed siding, a partial-width porch, replacement windows, and an exterior chimney. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 38a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2002 Bear Creek Rd. 32.560583°, -96.895312° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | A highly renovated Ranch style house with a shallow-pitch, hip roof with generous eaves, removed siding, a partial-width porch, replacement windows, and an exterior chimney. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 38b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2002 Bear Creek Rd. 32.559996°, -96.895464° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1968 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 38b is a shed with a front-gable roof, horizontal wood siding on the gable front, brick siding, and original windows. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 38b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2002 Bear Creek Rd. 32.559996°, -96.895464° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1968 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 38b is a shed with a front-gable roof, horizontal wood siding on the gable front, brick siding, and original windows. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 39a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2102 Bear Creek Rd. 32.560530°, -96.893816° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | A highly renovated Ranch style house (subtype: courtyard) with shallow-pitch, cross-gable roofs, brick and stone siding, replacement windows, a decorative brick half wall extending from the northeast corner of the house, and an exterior chimney. An addition of an integrated garage extends from the west façade of the original footprint of the house. |



Camera facing southeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 39a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2102 Bear Creek Rd. 32.560530°, -96.893816° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | A highly renovated Ranch style house (subtype: courtyard) with shallow-pitch, cross-gable roofs, brick and stone siding, replacement windows, a decorative brick half wall extending from the northeast corner of the house, and an exterior chimney. An addition of an integrated garage extends from the west façade of the original footprint of the house. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 39b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2102 Bear Creek Rd. 32.560401°, -96.894093° |
| Function/Sub-function: | DOMESTIC/ Secondary housing |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 39b is a highly renovated guesthouse with a hip roof, replacement vinyl siding, and replacement windows. A deck extends from the rear (southwest) corner of the guesthouse. |



Camera facing southeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 39b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2102 Bear Creek Rd. 32.560401°, -96.894093° |
| Function/Sub-function: | DOMESTIC/ Secondary housing |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 39b is a highly renovated guesthouse with a hip roof, replacement vinyl siding, and replacement windows. A deck extends from the rear (southwest) corner of the guesthouse. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 39c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2102 Bear Creek Rd. 32.560118°, -96.893774° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 39c is possibly a shed with a rectangular footprint and gable roof. Modern additions extend from the east and south facades of the structure. Project historians were unable to view Resource 39c from public ROW due to vegetation. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 39c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2102 Bear Creek Rd. 32.560118°, -96.893774° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 39c is possibly a shed with a rectangular footprint and gable roof. Modern additions extend from the east and south facades of the structure. Project historians were unable to view Resource 39c from public ROW due to vegetation. |



Aerial view showing building relationships, facing north (GoogleEarth, 2020).

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 40 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2222 Bear Creek Rd. 32.560504, -96.891805 |
| Function/Sub-function: | COMMERCE/ Restaurant |
| Construction Date: | Ca. 1976 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | A former ranch style house with a complex roof system consisting of steep side-gable roofs, two metal shed roofs, and a shallow-pitch, side-gable roof. The building features wood panel siding, an open porch with a metal shed roof, and replacement windows. Currently occupied by Juicy Bones Restaurant at BoxCar. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 40 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2222 Bear Creek Rd. 32.560504, -96.891805 |
| Function/Sub-function: | COMMERCE/ Restaurant |
| Construction Date: | Ca. 1976 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | A former ranch style house with a complex roof system consisting of steep side-gable roofs, two metal shed roofs, and a shallow-pitch, side-gable roof. The building features wood panel siding, an open porch with a metal shed roof, and replacement windows. Currently occupied by Juicy Bones Restaurant at BoxCar. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 41a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1435 Cockrell Hill Rd. 32.559767°, -96.891641° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1975 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with mansard roof, stucco siding, replacement windows, and an arched projection emphasizing the recessed main entry. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 41a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1435 Cockrell Hill Rd. 32.559767°, -96.891641° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with mansard roof, stucco siding, replacement windows, and an arched projection emphasizing the recessed main entry. |




Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 41b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1435 Cockrell Hill Rd. 32.559753°, -96.891998° |
| Function/Sub-function: | DOMESTIC/ Secondary housing |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 41b is a Ranch style guesthouse with a mansard roof, stucco siding, and original windows. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 41b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1435 Cockrell Rd. 32.559753°, -96.891998° |
| Function/Sub-function: | DOMESTIC/ Secondary housing |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 41b is a Ranch style guesthouse with a mansard roof, stucco siding, and original windows. A modern roofed structure extends from the guesthouse's south façade. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 42a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 923 Cockrell Hill Rd. 32.558887, -96.891631 |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, hip roof, brick siding, original sash windows and decorative panel shutters, a partial-width porch emphasized with classical columns, and a straddle ridge chimney. |



Camera facing west.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 42a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 923 Cockrell Hill Rd. 32.558887, -96.891631 |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, hip roof, brick siding, original sash windows and decorative panel shutters, a partial-width porch emphasized with classical columns, and a straddle ridge chimney. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 42b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 923 Cockrell Hill Rd. 32.558655, -96.891614 |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 42b is a metal shed with a metal shed roof and metal siding over a wood frame. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 42b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 923 Cockrell Hill Rd. 32.558655, -96.891614 |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 42b is a metal shed with a metal shed roof and metal siding over a wood frame. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 42 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 923 Cockrell Hill Rd. 32.333136°, -96.533070° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 2007 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed with attached carport |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 42 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 923 Cockrell Hill Rd. 32.3330.73°, -96.53316° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 2015 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed. |



Camera facing west.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 43a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 916 Cockrell Hill Rd. 32.558497°, -96.890580° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1953 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Contemporary Ranch style house with metal shed roof, hip roof, stucco siding, replacement fixed windows, and an exterior brick chimney. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 43a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 916 Cockrell Hill Rd. 32.558497°, -96.890580° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1953 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Contemporary Ranch style house with metal shed roof, hip roof, stucco siding, replacement fixed windows, and an exterior brick chimney. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 43b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 916 Cockrell Hill Rd. 32.558292°, -96.890612° |
| Function/Sub-function: | DOMESTIC/ Secondary housing |
| Construction Date: | Ca. 1953 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 43b is a former carport renovated into a guesthouse with a flat roof, wood panel siding, and square brick columns. The west-most portion of the guesthouse remains open. A metal addition (an attached garage) with a shed roof extends from the rear (east) façade of the guesthouse. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 43b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 916 Cockrell Rd. 32.558292°, -96.890612° |
| Function/Sub-function: | DOMESTIC/ Secondary housing |
| Construction Date: | Ca. 1953 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 43b is a former carport renovated into a guesthouse with a flat roof, wood panel siding, and square brick columns. The west-most portion of the guesthouse remains open. A metal addition (an attached garage) with a shed roof extends from the rear (east) façade of the guesthouse. |



Camera facing east.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 43c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 916 Cockrell Hill Rd. 32.558280°, -96.890252° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 43c is a shed with a shed roof and vertical wood siding. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 43c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 916 Cockrell Hill Rd. 32.558280°, -96.890252° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 43c is a shed with a shed roof and vertical wood siding. |



Camera facing east.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 43d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 916 Cockrell Hill Rd. 32.558302°, -96.890445° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 43d is a shed with an irregular footprint topped by a metal front-gable roof and a metal shed roof, and metal siding. |



Camera facing east.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 43d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 916 Cockrell Hill Rd. 32.558302°, -96.890445° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 43d is a shed with an irregular footprint topped by a metal front-gable roof and a metal shed roof, and metal siding. |



Camera facing east.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 43 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 916 Cockrell Hill Rd. 32.558650°, -96.890558° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 2000 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed. |



Camera facing east.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 43 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 916 Cockrell Hill Rd. 32.558649°, -96.890583° |
| Function/Sub-function: | DOMESTIC/ Aviary |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern aviary. |



Camera facing east.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 44a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 912 Cockrell Hill Rd. 32.557840°, -96.890289° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with hip roof, polychrome brick siding, replacement sash windows, panel shutters, a partial-width porch with decorative wrought iron supports, and a rear slope chimney. |



Camera facing southeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 44a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 912 Cockrell Hill Rd. 32.557840°, -96.890289° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with hip roof, polychrome brick siding, replacement sash windows, panel shutters, a partial-width porch with decorative wrought iron supports, and a rear slope chimney. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 44b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 912 Cockrell Hill Rd. 32.558063°, -96.890029° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 44b is a metal shed with a metal gable roof and metal siding. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 44b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 912 Cockrell Rd. 32.558063°, -96.890029° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 44b is a metal shed with a metal gable roof and metal siding. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 44c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 912 Cockrell Hill Rd. 32.558060°, -96.889828° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 44c is an open, metal shed with a metal roof. Observations were limited due to vegetation obstructing views from public ROW. Per aerial imagery, this may not have existed prior to 2002. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 44c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 912 Cockrell Hill Rd. 32.558060°, -96.889828° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 44c is a metal shed with a metal gable roof and metal siding. |



Aerial view of resources, facing north (Google Earth 2020).

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 44 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 912 Cockrell Rd. 32.557796°, -96.890913° |
| Function/Sub-function: | DOMESTIC/ Cistern |
| Construction Date: | Ca. 2000 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern cistern. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 45a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1230 W. Bear Creek Rd. 32.560546°, -96.886844° |
| Function/Sub-function: | AGRICULTURE/ Barn |
| Construction Date: | Ca. 1967 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 45a is a metal barn with a shallow-pitch, metal gable roof and metal siding. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 45a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1230 W. Bear Creek Rd. 32.560546°, -96.886844° |
| Function/Sub-function: | AGRICULTURE/ Barn |
| Construction Date: | Ca. 1967 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 45a is a metal barn with a shallow-pitch, metal gable roof and metal siding. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 45b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1230 W. Bear Creek Rd. 32.560505°, -96.886673° |
| Function/Sub-function: | AGRICULTURE/ Barn |
| Construction Date: | Ca. 1967 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 45b is a wood-frame shed with a metal gable roof. |



Camera facing southeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 45b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1230 W. Bear Creek Rd. 32.560505°, -96.886673° |
| Function/Sub-function: | AGRICULTURE/ Barn |
| Construction Date: | Ca. 1967 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 45b is a wood-frame shed with a metal gable roof. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 45c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1230 W. Bear Creek Rd. 32.559426°, -96.885458° |
| Function/Sub-function: | AGRICULTURE/ Barn |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 45c is a wood-frame barn with a shallow-pitch, metal front-gable roof, metal siding, and large sliding metal doors. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 45c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1230 W. Bear Creek Rd. 32.559426°, -96.885458° |
| Function/Sub-function: | AGRICULTURE/ Barn |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 45c is a wood-frame barn with a shallow-pitch, metal front-gable roof, metal siding, and large sliding metal doors. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 45d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1230 W. Bear Creek Rd. 32.559319°, -96.885273° |
| Function/Sub-function: | AGRICULTURE/ Barn |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 45d is a grain bin with a conical metal roof and metal panel siding. |



Camera facing north.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 45d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1230 W. Bear Creek Rd. 32.559319°, -96.885273° |
| Function/Sub-function: | AGRICULTURE/ Barn |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 45d is a grain bin with a conical metal roof and metal panel siding. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 46a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1230 W. Bear Creek Rd. 32.560309°, -96.885832° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1967 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, side-gable roofs with generous eaves, polychrome brick siding, cedar shake siding on gable ends, replacement windows, a partial-width porch supported by classical columns, and a rear slope chimney. An enclosed, integrated garage is located on the east façade. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 46a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1230 W. Bear Creek Rd. 32.560309°, -96.885832° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1967 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, side-gable roofs with generous eaves, polychrome brick siding, cedar shake siding on gable ends, replacement windows, a partial-width porch supported by classical columns, and a rear slope chimney. An enclosed, integrated garage is located on the east façade. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 46b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1230 W. Bear Creek Rd. 32.560318°, -96.885483° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | 1967 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 46b is a shed with a front-gable roof, exposed rafter tails, generous eaves, brackets, and vertical wood panel siding. |



Camera facing southeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 46b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1230 W. Bear Creek Rd. 32.560318°, -96.885483° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | 1967 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 46 b is a shed with a front-gable roof, exposed rafter tails, generous eaves, brackets, and vertical wood panel siding. |



Camera facing south.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 46 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1230 W. Bear Creek Rd. 32.560240°, -96.885560° |
| Function/Sub-function: | DOMESTIC/ Carport |
| Construction Date: | Ca. 2009 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern carport. |



Camera facing south.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 47a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1002 W. Bear Creek Rd. 32.556377°, -96.881444° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1977 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with a shallow-pitch, cross-gable metal roof, rusticated stone and vertical wood siding, a recessed entry, and an exterior stone chimney. An integrated carport extends from the west façade of the house. The carport features a shallow-pitch, side gable roof, and vertical wood siding. |



Camera facing south.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 47a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1002 W. Bear Creek Rd. 32.556377°, -96.881444° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1977 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with a shallow-pitch, cross-gable metal roof, rusticated stone and vertical wood siding, a recessed entry, and an exterior stone chimney. An integrated carport extends from the west façade of the house. The carport features a shallow-pitch, side gable roof, and vertical wood siding. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 47b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1002 W. Bear Creek Rd. 32.555779°, -96.882432° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | 1977 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 47b is possibly a barn. Project historians were unable to view Resource 47b from public ROW due to vegetation. Per aerial imagery, Resource 47b features a rectangular footprint and a metal, gable roof. |



Aerial photograph, facing north (Google Earth 2020).

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 47c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1002 W. Bear Creek Rd. 32.556127°, -96.882465° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | 1977 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 47c is possibly a barn. Project historians were unable to view Resource 47c from public ROW due to vegetation. Per aerial imagery, Resource 47c features a rectangular footprint and a metal, gable roof. |



Aerial photograph, facing north (Google Earth 2020).

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 47d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1002 W. Bear Creek Rd. 32.556602°, -96.882356° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | 1977 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 47d is a possibly a barn. Project historians were unable to view Resource 47d from public ROW due to vegetation. Per aerial imagery, the structure features a rectangular footprint and a metal roof. |



Aerial photograph, facing north (Google Earth 2020).

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 47e |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 1002 W. Bear Creek Rd. 32.556625°, -96.882143° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | 1977 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 47e is possibly a shed. Project historians were unable to view Resource 47e from public ROW. Per aerial imagery, the shed appears to have a metal, gable roof. |



Aerial photograph, facing north (Google Earth 2020).

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 48 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 838 Cockrell Hill Rd. 32.553202°, -96.889864° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1942 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with cross-gable roof, stone façade, and replacement windows. There appear to be decorative brick or stone quoins at the corners of the house. |



Camera facing east.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 48 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 838 Cockrell Hill Rd. 32.553202°, -96.889864° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1942 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with cross-gable roof, stone façade, and replacement windows. There appear to be decorative brick or stone quoins at the corners of the house. |



Camera facing east.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 49a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2100 S. Westmoreland Dr. 32.552293°, -96.874392° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1960 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with vinyl or hardplank siding, replacement vinyl windows, and two small inset porches (one with a single wood support) under a cross-gabled roof with modest eaves and low pitch. The seemingly detached garage with modern carport has been attached to the house via a rear porch addition. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 49a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2100 S. Westmoreland Dr. 32.552293°, -96.874392° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1960 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with vinyl or hardplank siding, replacement vinyl windows, and two small inset porches (one with a single wood support) under a cross-gabled roof with modest eaves and low pitch. The seemingly detached garage with modern carport has been attached to the house via a rear porch addition. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 49b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2100 Westmoreland Dr. 32.552616°, -96.874639° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1960 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Metal side-gabled barn with corrugated metal siding and roofing, roll metal door, and metal-covered windows. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 49b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2100 Westmoreland Dr. 32.552616°, -96.874639° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1960 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Metal side-gabled barn with corrugated metal siding and roofing, roll metal door, and metal-covered windows. |



Camera facing west.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 50a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2011 S. Westmoreland Rd. 32.551517°, -96.874644° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1920 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Craftsman style house with a metal hip roof, exposed rafter tails, replacement siding, a full-width porch featuring rustic wood supports, and replacement windows. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 50a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2011 S. Westmoreland Rd. 32.551517°, -96.874644° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1920 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Craftsman style house with a metal hip roof, exposed rafter tails, replacement siding, a full-width porch featuring rustic wood supports, and replacement windows. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 50b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2011 S. Westmoreland Rd. 32.550857°, -96.875232° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1920 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 50b is a barn with a metal front-gable roof and a metal shed roof, vertical wood siding, and a hay loft. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 50b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2011 S. Westmoreland Rd. 32.550857°, -96.875232° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1920 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 50b is a barn with a metal front-gable roof and a metal shed roof, vertical wood siding, and a hay loft. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 50c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2011 S. Westmoreland Rd. 32.551131°, -96.875166° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 50c is a shed with a metal front-gable roof, wood siding on the gable ends, and metal siding. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 50c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2011 S. Westmoreland Rd. 32.551131°, -96.875166° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 50c is a shed with a metal front-gable roof, wood siding on the gable ends, and metal siding. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 50d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2011 S. Westmoreland Rd. 32.551790°, -96.874651° |
| Function/Sub-function: | DOMESTIC/ Stable |
| Construction Date: | Ca. 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 50d is a stable with a shallow-pitch, front-gable metal roof, exposed rafter tails, and vertical wood siding. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 50d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2011 Westmoreland Rd. 32.551790°, -96.874651° |
| Function/Sub-function: | DOMESTIC/ Stable |
| Construction Date: | Ca. 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 50d is a stable with a shallow-pitch, front-gable metal roof, exposed rafter tails, and vertical wood siding. |



Camera facing west.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 50 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2011 S. Westmoreland Rd. 32.550766°, -96.874882° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 2005 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern barn. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 51 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2020 Westmoreland Rd. 32.549761°, -96.873675° |
| Function/Sub-function: | DOMESTIC/ Vacant |
| Construction Date: | 1955 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | A vacant Ranch style house with a shallow-pitch, hip roof with generous eaves, brick siding, a variety of original windows, a covered front porch featuring decorative wrought iron supports, and an integrated, enclosed garage extending from the north façade of the house. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 51 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2020 Westmoreland Rd. 32.549761°, -96.873675° |
| Function/Sub-function: | DOMESTIC/ Vacant |
| Construction Date: | 1955 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | A vacant Ranch style house with a shallow-pitch, hip roof with generous eaves, brick siding, a variety of original windows, a covered front porch featuring decorative wrought iron supports, and an integrated, enclosed garage extending from the north façade of the house. |



Camera facing east.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 52 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 807 Westmoreland Rd. 32.548842°, -96.874409° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1974 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with a cross gable roof and a shallow-pitch hip roof, brick siding with decorative brick projections bordering windows, a low, brick screen wall along the front (east) façade, a recessed entry with stoop, replacement windows, and a rear slope, brick chimney. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 52 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 807 Westmoreland Rd. 32.548842°, -96.874409° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1974 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with a cross gable roof and a shallow-pitch hip roof, brick siding with decorative brick projections bordering windows, a low, brick screen wall along the front (east) façade, a recessed entry with stoop, replacement windows, and a rear slope, brick chimney. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 53a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 108 Lariat Tr. 32.547700°, -96.876467° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with a shallow-pitch, gable-hip roof, brick siding, replacement windows, a covered stoop, and an exterior brick chimney. An enclosed, integrated garage extends from the west façade of the house. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 53a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 108 Lariat Tr. 32.547700°, -96.876467° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with a shallow-pitch, gable-hip roof, brick siding, replacement windows, a covered stoop, and an exterior brick chimney. An enclosed, integrated garage extends from the west façade of the house. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 53b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 108 Lariat Tr. 32.548000°, -96.876649° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Metal barn with a shallow gabled roof and sliding metal doors. Viewing angles limited due to location. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 53b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 108 Lariat Tr. 32.548000°, -96.876649° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Metal barn with a shallow gabled roof and sliding metal doors. Viewing angles limited due to location. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 53c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 108 Lariat Tr. 32.548122°, -96.876451° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Metal side-gabled shed with a shallow roof pitch behind the main house. Visibility limited due to fencing and vegetation. |



Camera facing north.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 53c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 108 Lariat Tr. 32.548122°, -96.876451° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Metal side-gabled shed with a shallow roof pitch behind the main house. Visibility limited due to fencing and vegetation. |



Camera facing north.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 54 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 106 Lariat Tr. 32.547695°, -96.875975° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, hip roof, brick siding, a partial-width porch accentuated with classical columns, a recessed entry, replacement windows, a rear slope brick chimney, and an enclosed, integrated garage extending from the east façade of the house. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 54 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 106 Lariat Tr. 32.547695°, -96.875975° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, hip roof, brick siding, a partial-width porch accentuated with classical columns, a recessed entry, replacement windows, a rear slope brick chimney, and an enclosed, integrated garage extending from the east façade of the house. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 54 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 106 Lariat Tr. 32.547914°, -96.876173° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 2018 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed. |



Camera facing north.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 54 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 106 Lariat Tr. 32.547914°, -96.876173° |
| Function/Sub-function: | DOMESTIC/ RV shed |
| Construction Date: | Ca. 2018 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern RV shed |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 54 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 106 Lariat Tr. 32.548080°, -96.875875° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 2018 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 55a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 104 Lariat Tr. 32.547706°, -96.875455° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house (subtype: linear with clusters) with a shallow-pitch, side-gable roof, brick siding, a recessed entry, a front slope brick chimney, and replacement windows. An enclosed integrated garage extends from the west façade of the house. The attached garage has been converted to interior space. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 55a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 104 Lariat Tr. 32.547706°, -96.875455° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house (subtype: linear with clusters) with a shallow-pitch, side-gable roof, brick siding, a recessed entry, a front slope brick chimney, and replacement windows. An enclosed integrated garage extends from the west façade of the house. The attached garage has been converted to interior space. |



Camera facing north.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 55b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 104 Lariat Tr. 32.547796°, -96.875616° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 55b is a detached garage post-dating the main house. The building has a hipped roof and single garage door. |




Camera facing north.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 55b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 104 Lariat Tr. 32.547796°, -96.875616° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 55b is a detached garage post-dating the main house. The building has a hipped roof and single garage door. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 55c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 104 Lariat Tr. 32.548009°, -96.875473° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 55c is a barn. Project historians were unable to view the barn from public ROW due to vegetation and structures obstructing views. Per aerial imagery, the barn appears to have a rectangular footprint, a side-gable, metal roof, and an addition with a metal roof extending from the east façade. |



Aerial view of Resource No. 55c, facing north (Google Earth 2020).

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 55d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 104 Lariat Tr. 32.548098°, -96.875707° |
| Function/Sub-function: | DOMESTIC/ Pole barn |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 55d is a recent gambrel roof barn or shed with vinyl sash windows. Visibility was limited due to vegetation, fencing, and other buildings. |



Camera facing north.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 55d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 104 Lariat Tr. 32.548098°, -96.875707° |
| Function/Sub-function: | DOMESTIC/ Pole barn |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 55d is a recent gambrel roof barn or shed with vinyl sash windows. Visibility was limited due to vegetation, fencing, and other buildings. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 56 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 803 Westmoreland Rd. 32.547842°, -96.874606° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | A 1.5-story Ranch style house with a steep-pitch clipped cross-gable roof, a dormer with a shed roof and horizontal vinyl siding polychrome brick siding and horizontal vinyl siding on gable ends, original metal-frame sash windows and diamond-plated casement windows. An integrated, enclosed garage extends from the south façade of the house. The garage features a replacement door. |



Camera facing west.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 56 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 803 Westmoreland Rd. 32.547842°, -96.874606° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1972 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | A 1.5-story Ranch style house with a steep-pitch clipped cross-gable roof, a dormer with a shed roof and horizontal vinyl siding polychrome brick siding and horizontal vinyl siding on gable ends, original metal-frame sash windows and diamond-plated casement windows. An integrated, enclosed garage extends from the south façade of the house. The garage features a replacement door. |



Camera facing north.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 57 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 443 Sleepy Top Rd. 32.548926°, -96.865141° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1973 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch hip roof, brick siding, a variety of original windows, a partial-width front porch, a recessed entry, an exterior brick chimney, and an integrated, enclosed garage at the south end of the house. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 57 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 443 Sleepy Top Rd. 32.548926°, -96.865141° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1973 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch hip roof, brick siding, a variety of original windows, a partial-width front porch, a recessed entry, an exterior brick chimney, and an integrated, enclosed garage at the south end of the house. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 58 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 432 Pearly Top Dr. 32.548476°, -96.865221° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1976 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, side-gable roof with generous eaves, brick siding, horizontal vinyl siding on gable ends, a partial-width porch with a recessed entry, replacement windows, louvered shutters, and an integrated, enclosed garage on the east end of the house. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 58 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 432 Pearly Top Dr. 32.548476°, -96.865221° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1976 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, side-gable roof with generous eaves, brick siding, horizontal vinyl siding on gable ends, a partial-width porch with a recessed entry, replacement windows, louvered shutters, and an integrated, enclosed garage on the east end of the house. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 58 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 432 Pearly Top Dr. 32.548357°, -96.865050° |
| Function/Sub-function: | DOMESTIC/ Carport |
| Construction Date: | Ca. 1995 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed and carport. |



Camera facing south.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 59 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 426 Pearly Top Dr. 32.548481°, -96.864749° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1976 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with steep-pitch, side-gable roof, brick siding, partial-width porch, horizontal wood siding on gable ends, and replacement windows with louvered shutters. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 59 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 426 Pearly Top Dr. 32.548481°, -96.864749° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1976 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with steep-pitch, side-gable roof, brick siding, partial-width porch, horizontal wood siding on gable ends, and replacement windows with louvered shutters. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 59 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 426 Pearly Top Dr. 32.548226°, -96.864954° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 2010 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 60 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 419 Pearly Top Dr. 32.548921°, -96.864558° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1973 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, hip roof, brick siding, a series of rounded arches mimicking an arcade along the partial-width porch, replacement rounded arch windows, replacement shutters, and a front slope brick chimney. An integrated, enclosed garage is located at the west end of the house. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 60 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 419 Pearly Top Dr. 32.548921°, -96.864558° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1973 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, hip roof, brick siding, a series of rounded arches mimicking an arcade along the partial-width porch, replacement rounded arch windows, replacement shutters, and a front slope brick chimney. An integrated, enclosed garage is located at the west end of the house. |



Camera facing north.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 61 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 420 Pearly Top Dr. 32.548485°, -96.864384° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1974 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-gable and hip roof, brick siding, horizontal wood siding on the gable end over the partial-width porch, replacement windows with panel shutters, and an integrated, enclosed garage on the west end of the house. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 61 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 420 Pearly Top Dr. 32.548485°, -96.864384° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1974 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-gable and hip roof, brick siding, horizontal wood siding on the gable end over the partial-width porch, replacement windows with panel shutters, and an integrated, enclosed garage on the west end of the house. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 62a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 414 Pearly Top Dr. 32.548492°, -96.863956° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1974 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with cross-clip gable roof, brick siding with decorative herringbone pattern and decorative half-timbering with stucco siding. In addition, the house features original double hung windows, a straddle ridge chimney, and a brick half wall extending from the northwest corner of the house. An integrated, enclosed garage is located at the west end of the house. |



Camera facing southeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 62a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 414 Pearly Top Dr. 32.548492°, -96.863956° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1974 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with cross-clip gable roof, brick siding with decorative herringbone pattern and decorative half-timbering with stucco siding. In addition, the house features original double hung windows, a straddle ridge chimney, and a brick half wall extending from the northwest corner of the house. An integrated, enclosed garage is located at the west end of the house. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 62b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 414 Pearly Top Dr. 32.548211°, -96.864158° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 62b is a shed with a gambrel roof and wood panel siding. |



Camera facing south.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 62b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 414 Pearly Top Dr. 32.548211°, -96.864158° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 62b is a shed with a gambrel roof and wood panel siding. |



Camera facing south.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 63 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 408 Pearly Top Dr. 32.548475°, -96.863542° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1974 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-gable roof, brick siding, horizontal vinyl siding on gable ends, a series of rounded arches along the partial-width porch, replacement rounded arch windows, a front slope chimney, and brick half-walls extending from the northwest and northeast corners of the house. An integrated, enclosed garage with a replacement door is located at the west end of the house. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 63 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 408 Pearly Top Dr. 32.548475°, -96.863542° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1974 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-gable roof, brick siding, horizontal vinyl siding on gable ends, a series of rounded arches along the partial-width porch, replacement rounded arch windows, a front slope chimney, and brick half-walls extending from the northwest and northeast corners of the house. An integrated, enclosed garage with a replacement door is located at the west end of the house. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 63 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 408 Pearly Top Dr. 32.548438°, -96.863764° |
| Function/Sub-function: | DOMESTIC/ Carport |
| Construction Date: | Ca. 1989 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern carport. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 64 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 402 Pearly Top Dr. 32.548460° , -96.863172° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1973 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, hip roof, brick siding, a partial-width porch, a variety of replacement windows, including bay windows, brick half-walls extending from the northwest and northeast corners of the house. An integrated, enclosed garage is located at the rear (south) of the house. |



Camera facing southeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 64 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 402 Pearly Top Dr. 32.548460°, -96.863172° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1973 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, hip roof, brick siding, a partial-width porch, a variety of replacement windows, including bay windows, brick half-walls extending from the northwest and northeast corners of the house. An integrated, enclosed garage is located at the rear (south) of the house. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 65 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 320 Pearly Top Dr. 32.548483°, -96.862751° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1973 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, hip roof with generous eaves, brick and horizontal vinyl siding, a covered front stoop with decorative wrought-iron supports, original rounded arch windows, and brick half-walls extending from the west and east corners of the house. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 65 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 320 Pearly Top Dr. 32.548483°, -96.862751° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1973 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, hip roof with generous eaves, brick and horizontal vinyl siding, a covered front stoop with decorative wrought-iron supports, original rounded arch windows, and brick half-walls extending from the west and east corners of the house. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 65 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 320 Pearly Top Dr. 32.548331°, -96.862928° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 2004 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed. |



Camera facing south.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 66 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 314 Pearly Top Dr. 32.548476°, -96.862311° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1974 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, hip roof, brick siding, a recessed entry, replacement windows, a rear slope chimney, and brick half-walls extending from the northwest and northeast corners of the house. An integrated, enclosed garage with a replacement door is located on the west end of the house. |



Camera facing southeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 66 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 314 Pearly Top Dr. 32.548476°, -96.862311° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1974 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, hip roof, brick siding, a recessed entry, replacement windows, a rear slope chimney, and brick half-walls extending from the northwest and northeast corners of the house. An integrated, enclosed garage with a replacement door is located on the west end of the house. |



Camera facing southeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 66 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 314 Pearly Top Dr. 32.548222°, -96.862521° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed. |



Camera facing south.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 67a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2123 S. Hampton Rd. 32.547222°, -96.857089° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1967 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, hip roof, brick and horizontal vinyl siding, a partial-with porch with a flat roof and decorative, wrought iron supports, original and replacement windows, and an integrated, enclosed garage located on the north end of the house. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 67a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2123 S. Hampton Rd. 32.547222°, -96.857089° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1967 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, hip roof, brick and horizontal vinyl siding, a partial-with porch with a flat roof and decorative, wrought iron supports, original and replacement windows, and an integrated, enclosed garage located on the north end of the house. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 67b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2123 S. Hampton Rd. 32.547381°, -96.858016° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1967 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 67b is a metal barn with a shallow-pitch, side-gable roof, metal siding, and three open bays. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 67b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2123 S. Hampton Rd. 32.547381°, -96.858016° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1967 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 67b is a metal barn with a shallow-pitch, side-gable roof, metal siding, and three open bays. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 67c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2123 S. Hampton Rd. 32.547319°, -96.858211° |
| Function/Sub-function: | DOMESTIC/ Loafing shed |
| Construction Date: | Ca. 1967 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 67c is a wood-frame barn with a shed roof and an additional cantilevered metal shed roof extending from the front (south) façade, metal siding, and three open bays. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 67c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2123 S. Hampton Rd. 32.547319°, -96.858211° |
| Function/Sub-function: | DOMESTIC/ Loafing shed |
| Construction Date: | Ca. 1967 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 67c is a wood-frame barn with a shed roof and an additional cantilevered metal shed roof extending from the front (south) façade, metal siding, and three open bays. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 67d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2123 S. Hampton Rd. 32.547192°, -96.858272° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1967 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 67d is a wood-frame shed with a metal shed roof, metal siding, and two open bays. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 67d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2123 S. Hampton Rd. 32.547192°, -96.858272° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1967 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 67d is a wood-frame shed with a metal shed roof, metal siding, and two open bays. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 67 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2123 S. Hampton Rd. 32.547125°, -96.858146° |
| Function/Sub-function: | DOMESTIC/ Feeder |
| Construction Date: | Ca. 2016 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern feeder. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 68a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2127 S. Hampton Rd. 32.546404°, -96.857195° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1971 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-gable and hip metal roof with generous eaves, brick siding, a variety of replacement windows, a rear slope brick chimney, and brick half-walls extending from the southeast and northeast corners of the house. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 68a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2127 S. Hampton Rd. 32.546404°, -96.857195° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1971 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-gable and hip metal roof with generous eaves, brick siding, a variety of replacement windows, a rear slope brick chimney, and brick half-walls extending from the southeast and northeast corners of the house. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 68b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2127 S. Hampton Rd. 32.546412°, -96.857897° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 68b is barn with a shallow-pitch, metal monitor roof, metal siding, and three open bays. |



Camera facing west.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 68b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2127 S. Hampton Rd. 32.546412°, -96.857897° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 68b is barn with a shallow-pitch, metal monitor roof, metal siding, and three open bays. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 68 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2127 S. Hampton Rd. 32.546540°, -96.857716° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 2011 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed. |



Camera facing west.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 69 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2307 S. Hampton Rd. 32.542903°, -96.857221° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-gable roof, brick siding, stucco and vertical vinyl siding on gable ends, a covered front stoop with a shed roof, replacement windows, and an attached wood-frame carport extending from the rear (west) façade. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 69 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2307 S. Hampton Rd. 32.542903°, -96.857221° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-gable roof, brick siding, stucco and vertical vinyl siding on gable ends, a covered front stoop with a shed roof, replacement windows, and an attached wood-frame carport extending from the rear (west) façade. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 70a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 500 W. Overhill Dr. 32.544444°, -96.849491° |
| Function/Sub-function: | DOMESTIC/ Unknown |
| Construction Date: | 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 70a is a metal building with a shallow-pitch, side-gable metal roof, metal siding, and replacement windows. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 70a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 500 W. Overhill Dr. 32.544444°, -96.849491° |
| Function/Sub-function: | DOMESTIC/ Unknown |
| Construction Date: | 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 70a is a metal building with a shallow-pitch, side-gable metal roof, metal siding, and replacement windows. |



Camera facing west.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 70b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 500 W. Overhill Dr. 32.544421°, -96.849402° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 70b is a metal shed with an irregular footprint. It includes both a gable and shed roof and metal siding. |



Camera facing north.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 70b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 500 W. Overhill Dr. 32.544421°, -96.849402° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 70b is a metal shed with an irregular footprint. It includes both a gable and shed roof and metal siding. |



Camera facing west.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 71 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 308 Watercrest Ln. 32.544533°, -96.846960° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1978 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 71 is a single-family dwelling with no discernible style. It features a side-gable roof, horizontal vinyl siding, a partial-width porch with a metal shed roof and wood supports, and replacement windows. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 71 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 308 Watercrest Ln. 32.544533°, -96.846960° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1978 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 71 is a single-family dwelling with no discernible style. It features a side-gable roof with generous eaves, Masonite siding, a partial-width porch with a metal shed roof, and replacement windows. |



Camera facing southeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 72 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 402 Watercrest Ln. 32.544948°, -96.846789° |
| Function/Sub-function: | DOMESTIC/ Vacant |
| Construction Date: | 1952 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Vacant Ranch style house with shallow-pitch hip roof, horizontal vinyl siding, a recessed porch, and replacement double-hung windows. The south end of the house is in ruin. |



Camera facing southeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 72 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 402 Watercrest Ln. 32.544948°, -96.846789° |
| Function/Sub-function: | DOMESTIC/ Vacant |
| Construction Date: | 1952 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Vacant ranch style house with shallow-pitch hip roof, horizontal vinyl siding, a recessed porch, and replacement double-hung windows. The south end of the house is in ruin. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 73a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 307 Lake Shore Ln. 32.544420°, -96.846280° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-gable roof, vertical and horizontal vinyl siding, a recessed porch, and replacement double-hung windows. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 73a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 307 Lake Shore Ln. 32.544420°, -96.846280° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-gable roof, vertical and horizontal vinyl siding, a recessed porch, and replacement double-hung windows. |



Camera facing west.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 73b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 307 Lake Shore Ln. 32.544242°, -96.846355° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 73b is a wood-frame barn with a shallow-pitch, side-gable metal roof, metal and vertical vinyl siding. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 73b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 307 Lake Shore Ln. 32.544242°, -96.846355° |
| Function/Sub-function: | DOMESTIC/ Barn |
| Construction Date: | Ca. 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 73b is a wood-frame barn with a shallow-pitch, side-gable metal roof, metal and vertical vinyl siding. |



Camera facing west.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 73c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 307 Lake Shore Ln. 32.544333°, -96.846508° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 73c is a wood-frame shed with a front-gable roof and vertical vinyl siding. |



Camera facing west.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 73c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 307 Lake Shore Ln. 32.544333°, -96.846508° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 73c is a wood-frame shed with a front-gable roof and vertical vinyl siding. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 74 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 309 Lake Shore Ln. 32.544684°, -96.846186° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1976 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, side-gable roof, horizontal vinyl siding, a partial width porch with a flat roof, and replacement windows. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 74 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 309 Lake Shore Ln. 32.544684°, -96.846186° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1976 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, side-gable roof, horizontal vinyl siding, a partial width porch with a flat roof, and replacement windows. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 75 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 320 Lake Shore Ln. 32.544386°, -96.845687° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Mixed style house with steep-pitch, side-gable roof over second story addition and shallow-pitch side-gable roof over original footprint, horizontal vinyl siding, a portico, and replacement windows. |



Camera facing southeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 75 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 320 Lake Shore Ln. 32.544386°, -96.845687° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1950 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Mixed style house with steep-pitch, side-gable roof over second story addition and shallow-pitch side-gable roof over original footprint, horizontal vinyl siding, a portico, and replacement windows. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 75 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 320 Lake Shore Ln. 32.544407°, -96.845517° |
| Function/Sub-function: | DOMESTIC/ Gazebo |
| Construction Date: | Ca. 1995 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern gazebo. |



Camera facing southeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 75 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 320 Lake Shore Ln. 32.544299°, -96.845496° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed. |



Camera facing east.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 75 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 320 Lake Shore Ln. 32.544227°, -96.845500° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed. |



Camera facing east.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 75 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 320 Lake Shore Ln. 32.544093°, -96.845475° |
| Function/Sub-function: | DOMESTIC/ Grain bin |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern grain bin. |



Camera facing east.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 75 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 320 Lake Shore Ln. 32.544033°, -96.845495° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1985 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed. |



Camera facing east.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 76 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 603 E. Southbrook Dr. 32.544109°, -96.845138° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-gable roof, horizontal vinyl and composite siding, a partial-width porch with a shed roof and picket-fence style railing, replacement windows, and a carport extending from the east façade of the house. An addition is located along the rear (north) façade of the house. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 76 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 603 E. Southbrook Dr. 32.544109°, -96.845138° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-gable roof, horizontal vinyl and composite siding, a partial-width porch with a shed roof and picket-fence style railing, replacement windows, and a carport extending from the east façade of the house. An addition is located along the rear (north) façade of the house. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 76 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 603 E. Southbrook Dr. 32.544314°, -96.845037° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 1989 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern garage and carport. |



Camera facing north.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 77 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 609 E. Southbrook Dr. 32.544233°, -96.844651° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 77 is a garage with a cross-gable roof, horizontal wood and vinyl siding, and sliding doors along the south façade. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 77 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 609 E. Southbrook Dr. 32.544233°, -96.844651° |
| Function/Sub-function: | DOMESTIC/ Carport |
| Construction Date: | Ca. 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 77 is a garage with a cross-gable roof, horizontal wood and vinyl siding, and sliding doors along the south façade. |



Camera facing northeast.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 77 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 609 E. Southbrook Dr. 32.544202°, -96.844456° |
| Function/Sub-function: | DOMESTIC/ Mobile home |
| Construction Date: | Ca. 1989 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Mobile home. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 78 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 611 E. Overhill Dr. 32.545065°, -96.843843° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1940 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Craftsman style bungalow with clip-gable roof with generous eaves and brackets, horizontal vinyl siding, a partial-width porch with a shed roof, and replacement windows. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 78 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 611 E. Overhill Dr. 32.545065°, -96.843843° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1940 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Craftsman style bungalow with clip-gable roof with generous eaves and brackets, horizontal vinyl siding, a partial-width porch with a shed roof, and replacement windows. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 78 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 611 E. Overhill Dr. 32.545065°, -96.843843° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 2010 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 79a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 619 E. Overhill Dr. 32.545046°, -96.842911° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1981 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, side-gable roof, exposed rafter tails vertical vinyl siding, covered front stoop, and original double-hung windows. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 79a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 619 E. Overhill Dr. 32.545046°, -96.842911° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1981 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, side-gable roof, exposed rafter tails vertical vinyl siding, covered front stoop, and original double-hung windows. |



Camera facing north.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 79b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 619 E. Overhill Dr. 32.545156°, -96.843035° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 79b is a shed with a metal shed roof, metal siding, and an open bay on the front (south) façade. |



Camera facing north.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 79b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 619 E. Overhill Dr. 32.545156°, -96.843035° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 79b is a shed with a metal shed roof, metal siding, and an open bay on the front (south) façade. |



Camera facing northeast.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 80 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2121 Uhl Rd. 32.546609° , -96.842587° |
| Function/Sub-function: | DOMESTIC/ Unknown |
| Construction Date: | Ca. 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 80 is a composite building featuring a variety of roof types, including gable, hip, and shed, as well as a variety of materials, including horizontal vinyl siding, wood siding, and metal siding. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 80 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2121 Uhl Rd. 32.546609°, -96.842587° |
| Function/Sub-function: | DOMESTIC/ Unknown |
| Construction Date: | Ca. 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 80 is a composite building featuring a variety of roof types, including gable, hip, and shed, as well as a variety of materials, including horizontal vinyl siding, wood siding, and metal siding. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 81a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2115 S. Uhl Rd. 32.547617°, -96.842632° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-gable roof with generous eaves, brick and stone siding, vertical vinyl siding on gable ends, a recessed porch with decorative wrought iron supports and a brick half-wall, an exterior brick chimney, and a variety of replacement windows. A metal carport extends from the rear (west) façade of the house. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 81a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2115 S. Uhl Rd. 32.547617°, -96.842632° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with shallow-pitch, cross-gable roof with generous eaves, brick and stone siding, vertical vinyl siding on gable ends, a recessed porch with decorative wrought iron supports and a brick half-wall, an exterior brick chimney, and a variety replacement windows. A metal carport extends from the rear (west) façade of the house. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 81b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2115 S. Uhl Rd. 32.547780°, -96.842957° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 81b is a garage with a shallow-pitch, front-gable metal roof, metal siding, original windows, and a rolling garage door and panel door. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 81b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2115 S. Uhl Rd. 32.547780°, -96.842957° |
| Function/Sub-function: | DOMESTIC/ Garage |
| Construction Date: | Ca. 1982 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 81b is a garage with a shallow-pitch, front-gable metal roof, metal siding, original windows, and a rolling garage door and panel door. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 81c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2115 S. Uhl Rd. 32.547740°, -96.843701° |
| Function/Sub-function: | DOMESTIC/ Pole barn |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 81c is a wood-frame pole barn with a shallow-pitch, metal shed roof, metal siding and three open bays. |



Camera facing southwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 81c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2115 S. Uhl Rd. 32.547740°, -96.843701° |
| Function/Sub-function: | DOMESTIC/ Pole barn |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 81c is a wood-frame pole barn with a shallow-pitch, metal shed roof, metal siding and three open bays. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 81d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2115 S. Uhl Rd. 32.547657°, -96.843703° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 81d is a shed with a metal gambrel shed, metal siding, wood panel doors, and an original window. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 81d |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2115 S. Uhl Rd. 32.547657°, -96.843703° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 1979 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Resource 81d is a shed with a metal gambrel shed, metal siding, wood panel doors, and a original window. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 81 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2115 S. Uhl Rd. 32.547657°, -96.843703° |
| Function/Sub-function: | DOMESTIC/ Carport |
| Construction Date: | Ca. 1989 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern Carport. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 82 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2155 S. I-35 32.549433°, -96.823457° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1965 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with chalet influence featuring vertical vinyl and rusticated stone siding, replacement windows, and a shallow-pitch, cross-gable roof with generous eaves. A modern shed and storage container are located nearby. The house appears to serve as the office or primary residence for an RV park located immediately to the south. A tall wood fence with brick posts and entry separates the house and RV park from the interstate frontage road. |



Camera facing west.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 82 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2155 S. I-35 32.549433°, -96.823457° |
| Function/Sub-function: | DOMESTIC/ Single family dwelling |
| Construction Date: | Ca. 1965 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with chalet influence featuring vertical vinyl and rusticated stone siding, replacement windows, and a shallow-pitch, cross-gable roof with generous eaves. A modern shed and storage container are located nearby. The house appears to serve as the office or primary residence for an RV park located immediately to the south. A tall wood fence with brick posts and entry separates the house and RV park from the interstate frontage road. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 82 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 2155 S. I-35 32.549433°, -96.823457° |
| Function/Sub-function: | DOMESTIC/ Shed |
| Construction Date: | Ca. 2008 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Modern shed. |



Camera facing west.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 83a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 901 N. I-35 32.546948°, -96.823828° |
| Function/Sub-function: | HEALTHCARE/ Medical business/ Office |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Office building with a shallow-pitch, metal gable roof, metal siding, a vestibule, and replacement windows. A large addition spans from the north façade. The addition features a shallow-pitch, metal, gable roof, metal siding, a sliding bay door, and a metal cantilevered structure across the north façade. Currently occupied by Country Veterinary Clinic. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 83a |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 901 N. I-35 32.546948°, -96.823828° |
| Function/Sub-function: | HEALTHCARE/ Medical business/ Office |
| Construction Date: | Ca. 1970 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Office building with a shallow-pitch, metal gable roof, metal siding, a vestibule, and replacement windows. A large addition spans from the north façade. The addition features a shallow-pitch, metal, gable roof, metal siding, a sliding bay door, and a metal cantilevered structure across the north façade. Currently occupied by Country Veterinary Clinic. |



Camera facing northwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 83b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 901 N. I-35 32.546918°, -96.824690° |
| Function/Sub-function: | HEALTHCARE/ Medical business/ Barn |
| Construction Date: | Ca. 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Metal barn with a shallow-pitch, metal gable-front roof and metal siding. Currently occupied by Country Veterinary Clinic. |



Camera facing southwest.

| | |
|------------------------|--|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 83b |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 901 N. I-35 32.546918°, -96.824690° |
| Function/Sub-function: | HEALTHCARE/ Medical business/ Barn |
| Construction Date: | Ca. 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Metal barn with a shallow-pitch, metal gable-front roof and metal siding. Currently occupied by Country Veterinary Clinic. |



Camera facing northwest.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 83c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 901 N. I-35 32.547044°, -96.825112° |
| Function/Sub-function: | HEALTHCARE/ Medical business/ RV shed |
| Construction Date: | Ca. 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Large RV shed with a metal shed roof and steel supports. Currently occupied by Country Veterinary Clinic. |



Camera facing west.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 83c |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 901 N. I-35 32.547044°, -96.825112° |
| Function/Sub-function: | HEALTHCARE/ Medical business/ RV shed |
| Construction Date: | Ca. 1980 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Large RV shed with a metal shed roof and steel supports. Currently occupied by Country Veterinary Clinic. |



Camera facing west.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 84 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 897 N. I-35 32.545574°, -96.822963° |
| Function/Sub-function: | DOMESTIC/ Vacant |
| Construction Date: | Ca. 1955 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with brick siding, a partial width porch with simple wood posts, replacement sliding windows, and original casement windows. The house has a shallow pitch, gable-on-hip roof with modest eaves. Aerial photos show a covered back porch adjacent to the attached garage. Visibility of the house was somewhat limited due to heavy vegetation growth. The house is surrounded by a dilapidated chain link fence. The house appears to serve as the office or primary residence for the Village Square Mobile Home and RV Park, although it appears to be vacant. |



Camera facing west.

| | |
|------------------------|---|
| Survey Date: | October 28-October 29, 2019 |
| Resource No: | 84 |
| Project Location: | Dallas & Ellis Counties |
| Project Name and CSJ: | Loop 9 Segment A, CSJ 2964-10-006, 0261-01-041 |
| Address, Lat/Long: | 897 N. I-35 32.545574°, -96.822963° |
| Function/Sub-function: | DOMESTIC/ Vacant |
| Construction Date: | Ca. 1955 |
| NRHP Eligibility: | Not Eligible |
| Integrity/Comments: | Ranch style house with brick siding, a partial width porch with simple wood posts, replacement sliding windows, and original casement windows. The house has a shallow pitch, gable-on-hip roof with modest eaves. Aerial photos show a covered back porch adjacent to the attached garage. Visibility of the house was somewhat limited due to heavy vegetation growth. The house is surrounded by a dilapidated chain link fence. The house appears to serve as the office or primary residence for the Village Square Mobile Home and RV Park, although it appears to be vacant. |



Camera facing northwest.

Appendix D: Figures




Figure 1: Project Location Map (Aerial)




Figure 2: Project Location Map (Topo)




Figure 3a: Project Study Area and APE




Figure 3b: Project Study Area and APE




Figure 3c: Project Study Area and APE




Figure 4a: Surveyed Resource Locations




Figure 4b: Surveyed Resource Locations




Figure 4c: Surveyed Resource Locations




Figure 4d: Surveyed Resource Locations




Figure 4e: Surveyed Resource Locations




Figure 4f: Surveyed Resource Locations




Figure 4g: Surveyed Resource Locations




Figure 5: 1970 Aerial of Property 08 (USGS EarthExplorer).



Figure 6: 2001 Aerial of Property No. 08 (Google Earth).



Figure 7: 1970 Aerial of Resource No. 14 (USGS EarthExplorer).



Figure 8: 2001 Aerial of Resource No. 14 (Google Earth 2020).




Figure 9: 1970 Aerial of Property No. 17 (USGS EarthExplorer).



Figure 10: 2001 Aerial of Property Nos. 17 and 19 (Google Earth).





Figure 11: 1970 Aerial of Property No. 31 (USGS EarthExplorer).



Figure 12: 2018 Aerial View of Property No. 33 (Google Earth 2020).

Appendix E: Schematics

(For additional information, please see schematics files uploaded to ECOS)



Appendix F: Project Area Photographs

(From PCR – All Photos Taken October 2018)



Camera facing west from IH 35E southbound frontage road, north of the proposed LP 9 main lanes.



Camera facing east from S. Hampton Road towards the proposed ROW of LP 9.



Camera facing north towards northwest corner of S. Hampton and W. Bear Creek Roads.



Camera facing east from S. Cockrell Hill Road, looking towards home located just south of the proposed LP 9 main lanes.



Camera facing west towards bar/restaurant located at the southwest corner of the intersection of W. Bear Creek Road and S. Cockrell Hill Road.



Camera facing south towards bar/restaurant located at the southwest corner of the intersection of W. Bear Creek Road and S. Cockrell Hill Road.



Camera facing north looking towards horse farm located in the northeast corner of the intersection of W. Bear Creek Road and S. Duncanville Road.



Camera facing east from US 67 northbound frontage road, looking towards facility located south of the proposed LP 9 main lanes.



Camera facing west from S. Hampton Road looking towards the entrance to the Stone Creek residential subdivision.



Camera facing north looking towards residence located on Green Mound Drive.

Appendix G: Consulting Party Comments



June 13, 2020

Dallas County Historical Commission
Richard Stewart, Commission Chair
2327 Southern Oak Dr.
Irving, TX 75063
rgstewartjr@sbcglobal.net

NATIONAL HISTORIC PRESERVATION ACT REVIEW: Loop 9 Segment A, Dallas and Ellis Counties, Dallas District (CSJ 2964-10-006)

Dear Mr. Stewart,

We ask that the Dallas County Historical Commission (CHC) comment on area historic resources for the above referenced project. If your CHC does not contact the Texas Department of Transportation (TxDOT) by **Monday, July 13, 2020**, we will assume that the CHC has no comment.

TxDOT Dallas District is proposing to construct a six-lane, new location frontage road system between United States 67 (US 67) and Interstate 35 East (IH 35E) through Dallas and Ellis Counties.¹ The length of the proposed project is an approximate 9.4 miles. The proposed project right-of-way (ROW) would include a median that would accommodate the future construction of an ultimate access-controlled mainlane facility. As proposed, a new location roadway and four preliminary build alternatives (Alternative 1, Alternative 2, Alternative 3, and Alternative 4) are under consideration, and an Environmental Impact Statement (EIS) will be prepared pursuant to the National Environmental Policy Act (NEPA). Between 697.6 and 704.9 acres of new ROW would be required for this project, depending on the alternative selected.

Environmental issues, including the identification of historic properties, will be resolved prior to construction. Please see the attached map for the proposed project location. The Report for Historical Studies Survey for the Loop 9 Segment A Project will be submitted to you via email by TxDOT Dropbox for your review when the survey is complete.

We request the CHC's help to locate historic properties within our project area. Historic properties are generally those that are 50 years old, that are listed in, or eligible to be listed in, the National Register of Historic Places. To date, **our research identified no historic properties within the project area.**

Does CHC agree with our findings--are there no known historic resources in the project area? If so, please sign where indicated below and return this document to TxDOT by **Monday, July 13, 2020**.

Does CHC have any additional information about other historic resources--pre-1982 historic buildings, structures, objects, cemeteries or other historic resources that may be important locally within the project area? If so, contact TxDOT via letter, e-mail, or phone call by **Monday, July 13, 2020**.

Does CHC have general comments or questions about how our project could impact historic properties in the project area? If so, contact TxDOT via letter, e-mail, or phone call **Monday, July 13, 2020**.

Direct CHC responses and questions to Sandra J. Williams, Environmental Program Manager, at (214) 320-6686 (email: Sandra.williams2@txdot.gov). When replying to this correspondence by US Mail, please ensure

OUR GOALS

MAINTAIN A SAFE SYSTEM ▪ ADDRESS CONGESTION ▪ CONNECT TEXAS COMMUNITIES ▪ BEST IN CLASS STATE AGENCY

An Equal Opportunity Employer


June 13, 2020

that the envelope address includes reference to Texas Dept. of Transportation – Dallas District Office, 4777 E. Hwy 80, Mesquite, Texas 75150-6643, Attn: Sandra J. Williams.

Thank you for your assistance in this project.

Sincerely,

DocuSigned by:



Dan Perge, P.E.

Advance Project Development Director
TxDOT Dallas District

OUR GOALS

MAINTAIN A SAFE SYSTEM ▪ ADDRESS CONGESTION ▪ CONNECT TEXAS COMMUNITIES ▪ BEST IN CLASS STATE AGENCY

An Equal Opportunity Employer

This letter and its enclosures serve to initiate consultation with the Dallas CHC on historic resource identification efforts for the proposed project. Please concur with our findings of historic properties listed above or provide other comments below.

CHC Chairperson

Date:

Contact TxDOT via letter, e-mail, or phone call using information provided in the letter above. If you'd prefer, use the comment section below to share information and return signed copy to TxDOT.

Comments:

¹ The environmental review, consultation, and other actions required by applicable Federal environmental laws for this project are being, or have been, carried out by TxDOT pursuant to 23 U.S.C. 327 and a Memorandum of Understanding dated December 9, 2019, and executed by FHWA and TxDOT. TxDOT's regulatory role for this project is that of the Federal action agency.



June 13, 2020

Ellis County Historical Commission
Sylvia Stanford-Smith, Commission Chair
PO Box 175
Waxahachie, TX 75168
sylsmithro@att.net

NATIONAL HISTORIC PRESERVATION ACT REVIEW: Loop 9 Segment A, Dallas and Ellis Counties, Dallas District (CSJ 2964-10-006)

Dear Ms. Stanford-Smith,

We ask that the Ellis County Historical Commission (CHC) comment on area historic resources for the above referenced project. If your CHC does not contact the Texas Department of Transportation (TxDOT) by **Monday, July 13, 2020**, we will assume that the CHC has no comment.

TxDOT Dallas District is proposing to construct a six-lane, new location frontage road system between United States 67 (US 67) and Interstate Highway 35 East (IH 35E) through Dallas and Ellis Counties.¹ The length of the proposed project is an approximate 9.4 miles. The proposed project right-of-way (ROW) would include a median that would accommodate the future construction of an ultimate access-controlled mainlane facility. As proposed, a new location roadway and four preliminary build alternatives (Alternative 1, Alternative 2, Alternative 3, and Alternative 4) are under consideration, and an Environmental Impact Statement (EIS) will be prepared pursuant to the National Environmental Policy Act (NEPA). Between 697.6 and 704.9 acres of new ROW would be required for this project, depending on the alternative selected.

Environmental issues, including the identification of historic properties, will be resolved prior to construction. Please see the attached map for the proposed project location. The Report for Historical Studies Survey for the Loop 9 Segment A Project will be submitted to you via email by TxDOT Dropbox for your review when the survey is complete.

We request the CHC's help to locate historic properties within our project area. Historic properties are generally those that are 50 years old, that are listed in, or eligible to be listed in, the National Register of Historic Places. To date, **our research identified no historic properties within the project area.**

Does CHC agree with our findings--are there no known historic resources in the project area? If so, please sign where indicated below and return this document to TxDOT **Monday, July 13, 2020**.

Does CHC have any additional information about other historic resources--pre-1982 historic buildings, structures, objects, cemeteries or other historic resources that may be important locally within the project area? If so, contact TxDOT via letter, e-mail, or phone call by **Monday, July 13, 2020**.

Does CHC have general comments or questions about how our project could impact historic properties in the project area? If so, contact TxDOT via letter, e-mail, or phone call **Monday, July 13, 2020**.

Direct CHC responses and questions to Sandra J. Williams, Environmental Program Manager, at (214) 320-6686 (email: Sandra.williams2@txdot.gov). When replying to this correspondence by US Mail, please ensure


June 13, 2020

that the envelope address includes reference to Texas Dept. of Transportation – Dallas District Office, 4777 E. Hwy 80, Mesquite, Texas 75150-6643, Attn: Sandra J. Williams.

Thank you for your assistance in this project.

Sincerely,

DocuSigned by:

Dan Perge

17193E45A8CF04E
Dan Perge, P.E.

Advance Project Development Director
TxDOT Dallas District

OUR GOALS

MAINTAIN A SAFE SYSTEM ▪ ADDRESS CONGESTION ▪ CONNECT TEXAS COMMUNITIES ▪ BEST IN CLASS STATE AGENCY

An Equal Opportunity Employer

This letter and its enclosures serve to initiate consultation with the Ellis CHC on historic resource identification efforts for the proposed project. Please concur with our findings of historic properties listed above or provide other comments below.

CHC Chairperson


Date:

Contact TxDOT via letter, e-mail, or phone call using information provided in the letter above. If you'd prefer, use the comment section below to share information and return signed copy to TxDOT.

Comments:


[illegible]

¹ The environmental review, consultation, and other actions required by applicable Federal environmental laws for this project are being, or have been, carried out by TxDOT pursuant to 23 U.S.C. 327 and a Memorandum of Understanding dated December 9, 2019, and executed by FHWA and TxDOT. TxDOT's regulatory role for this project is that of the Federal action agency.



Sources: ESRI Imagery 2018; Open Street Map; TIGER Roads 2015; GNIS Towns 2019; NCTCOG Cities 2019

- COMMON ALIGNMENT PROPOSED ROW
- ALTERNATE 1 PROPOSED ROW
- ALTERNATE 2 PROPOSED ROW
- ALTERNATE 3 PROPOSED ROW
- ALTERNATE 4 PROPOSED ROW
- US 67 PROJECT AREA (EVALUATED UNDER SEPARATE DOCUMENT)
- IH 35E PROJECT AREA (EVALUATED UNDER SEPARATE DOCUMENT)



LOOP 9, SEGMENT A: US 67 TO IH 35E
CSJ: 2964-10-006
PROJECT LOCATION MAP
DALLAS & ELLIS COUNTIES, TEXAS




FIGURE 1

DATE:
MARCH 2020